



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 29655

Vehicle Insured : SLB 1250 K  
Accident Date : 20-Mar-2018

Date : 23-Mar-2018

Our Ref : 180221 (AXA) / SHUMAN

PAGE : 1

PING MIN MEDICAL HALL  
Singapore

### ESTIMATED COST OF REPAIR FOR HYUNDAI H1 STAREX 2.5 CRDI (2017) PC6294Z

1 pc rear bumper	435.00	
1 pc rear bumper step garnish	57.90	
1 pc rear bumper sponge	74.30	
1 pc rear bumper reinforcement	347.00	
1 pc o/s rear bumper side retainer	29.50	
10 pcs rear bumper clips @ S\$ 2.00	20.00	
1 pc o/s rear bumper corner garnish	98.30	
1 pc o/s rear bumper corner garnish side retainer	29.50	
1 pc o/s taillamp	384.90	
	-----	
	1,476.40	
Less 20% :	-295.28	
	-----	1,181.12
1 pc reverse sensor		220.00 sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.		700.00
To focus taillamps. To check rear wiring and lighting operation.		50.00
To remove and refit reverse sensor assy.		80.00
To putty and respray on affected portions.		600.00
	-----	
Total :	S\$ 2,831.12	=====

Singapore Dollars Two Thousand Eight Hundred and Thirty One and Cents Twelve Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.