



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
LIM KIAN GUAN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/04/2018
Vehicle Reg. No.:	SKL5852G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	BMW 118I, 1.6 SPORT (A)	Vehicle Reg. Date:	28/11/2013
Vehicle Colour:	WHITE	Chassis No:	WBA1A32050J067006
Engine No:	B796J232N13B16A		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

*Tanjong 97495746
WP 11/4/18 (1545)
Lumpsum
Resurvey before paint
5 days
Su v @ LKK auto.com*

COST OF CLAIMS

	Amount
Parts	7,535.64
Miscellaneous Items	10.00
Labour	2,230.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,775.64
+ GST 7.00% (S\$)	684.29
Nett Amount (S\$)	10,459.93

This claim is handled by: **BILLY**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the **Repairer** of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2018)

Parts: 144 BMW 118I 1.6 Sport (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL5852G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*BONNET	bt ✓	5.00	0.00	*1,122.10 FL
2	1		*BONNET LOCK TOP - CHECK		5.00	0.00	-
3	1		*BONNET LOCK BOTTOM - CHECK		5.00	0.00	-
4	1		*HEADLAMP ASSY LH	cra ✓	5.00	0.00	*1,751.40 FL
5	1		*HEADLAMP LOWER BRACKET LH	neu ✓	5.00	0.00	*53.95 FL
6	1		*HEADLAMP PANEL LH	?	5.00	0.00	*160.55 FL
7	1		*HEADLAMP CONTROL UNIT LH - CHECK		5.00	0.00	-
8	1		*HEADLAMP MODULE LH - CHECK		5.00	0.00	-
9	1		*HEADLAMP LED CONTROL LH - CHECK		5.00	0.00	-
10	1		*FRONT BUMPER	de ✓	5.00	0.00	*786.70 FL
11	1		*FRONT BUMPER LOGO	neu ✓	5.00	0.00	*69.50 FL
12	1		*FRONT BUMPER TOP RUBBER		5.00	0.00	*20.00 FL
13	1		*FRONT BUMPER SPONGE	?	5.00	0.00	*43.55 FL
14	1		*FRONT BUMPER REINFORCEMENT - CHECK		5.00	0.00	-
15	1		*FRONT BUMPER RETAINER LH	neu ✓	5.00	0.00	*11.75 FL
16	10		*FRONT BUMPER RIVET	neu ✓	5.00	0.00	*25.00 FL
17	1		*FRONT FENDER LH	bt ✓	5.00	0.00	*546.00 FL
18	1		*FRONT FENDER COWLING (FRT) LH	de ✓	5.00	0.00	*104.00 FL
19	1		*FRONT FENDER COWLING (REAR) LH	de ✓	5.00	0.00	*104.00 FL
20	1		*FRONT FENDER EMBLEM (SPORT) LH	ant ✓	5.00	0.00	*45.00 FL
21	1		*FRONT FENDER BRACKET LH	neu ✓	5.00	0.00	*32.15 FL
22	1		*FRONT SPORT RIM LH	ant ✓	5.00	0.00	*899.25 FL
23	1		*FRONT TYRE LH - CHECK		5.00	0.00	-
24	1		*FRONT WHEEL BEARING LH	?	5.00	0.00	*465.75 FL
25	1		*FRONT KNUCKLE ARM LH	?	5.00	0.00	*439.10 FL
26	1		*FRONT LOWER ARM LH	?	5.00	0.00	*262.20 FL
27	1		*FRONT LOWER ARM STAY LH	?	5.00	0.00	*262.20 FL
28	1		*FRONT DRIVE SHAFT LH - CHEK		5.00	0.00	-
29	1		*FRONT SHOCK ABSORBER LH - CHECK		5.00	0.00	-
30	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH - CHECK		5.00	0.00	-
31	1		*FRONT SHOCK ABSORBER TOP MOUNTING BEARING LH - CHECK		5.00	0.00	-
32	1		*STEERING RACK & PINON - CHECK		5.00	0.00	-
33	1		*STEERING RACK TIE ROD END LH	?	5.00	0.00	*169.35 FL
34	1		*STEERING RACK TIE ROD LH	?	5.00	0.00	*282.35 FL
35	1		*ENGINE MOUNTING LH - CHECK		5.00	0.00	-
36	1		*ENGINE MOUNTING RH - CHECK		5.00	0.00	-
37	1		*FOG LAMP LH	dis ✓	5.00	0.00	*276.40 FL
38	1		*FOG LAMP GARNISH LH		5.00	0.00	-
39	1		*FOG LAMP MOULDING LH		5.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,932.25
- List Item Discount on L Items (S\$)	396.61
Total Parts (S\$)	7,535.64

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK AND STRAIGHTEN FRONT BODY MEMBER, FRONT FENDER INNER PANEL LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	600 800.00
2	SPRAY PAINT BONNET, FRONT BUMPER, FRONT FENDER INNER PANEL, FRONT FENDER LH	New	600 700.00
3	REMOVE AND REPLACE FRONT UNDER CARRIAGE SUSPENSION	New	photo 150? 250.00
4	REMOVE & REPLACE ENGINE MOUNTING & CHECK GEAR BOX MOUNTING	New	100? 180.00
5	REINSTALL HEADLAMP AND REPROGRAMME	New	100 200.00
6	COMPUTER WHEEL ALIGNMENT	New	✓ 60.00
7	CHECK WIRING AND FOCUS HEADLIGHT	New	30. 40.00
Gross Labour Cost (S\$)			2,230.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >