



Automotive Pte Ltd

**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 1008, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise in Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**  
**Hilton Auto Trading**

Dealing in New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** India International Insurance Pte Ltd (HQ)  
**LIM KIAN GUAN**  
Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/04/2018
Vehicle Reg. No.:	SKL5852G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	BMW 118I, 1.6 SPORT (A)	Vehicle Reg. Date:	28/11/2013
Vehicle Colour:	WHITE	Chassis No:	WBA1A32050J067006
Engine No:	B796J232N13B16A		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	7,535.64
Miscellaneous Items	10.00
Labour	2,230.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>9,775.64</b>
<b>+ GST 7.00% (S\$)</b>	<b>684.29</b>
<b>Nett Amount (S\$)</b>	<b>10,459.93</b>

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 10 Apr 2018)  
 Parts: 144      BMW 118i 1.6 Sport (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SKL5852G)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	5.00	0.00	*1,122.10 FL
2	1		*BONNET LOCK TOP - CHECK	5.00	0.00	-
3	1		*BONNET LOCK BOTTOM - CHECK	5.00	0.00	-
4	1		*HEADLAMP ASSY LH	5.00	0.00	*1,751.40 FL
5	1		*HEADLAMP LOWER BRACKET LH	5.00	0.00	*53.95 FL
6	1		*HEADLAMP PANEL LH	5.00	0.00	*160.55 FL
7	1		*HEADLAMP CONTROL UNIT LH - CHECK	5.00	0.00	-
8	1		*HEADLAMP MODULE LH - CHECK	5.00	0.00	-
9	1		*HEADLAMP LED CONTROL LH - CHECK	5.00	0.00	-
10	1		*FRONT BUMPER	5.00	0.00	*786.70 FL
11	1		*FRONT BUMPER LOGO	5.00	0.00	*69.50 FL
12	1		*FRONT BUMPER TOP RUBBER	5.00	0.00	*20.00 FL
13	1		*FRONT BUMPER SPONGE	5.00	0.00	*43.55 FL
14	1		*FRONT BUMPER REINFORCEMENT - CHECK	5.00	0.00	-
15	1		*FRONT BUMPER RETAINER LH	5.00	0.00	*11.75 FL
16	10		*FRONT BUMPER RIVET	5.00	0.00	*25.00 FL
17	1		*FRONT FENDER LH	5.00	0.00	*546.00 FL
18	1		*FRONT FENDER COWLING (FRT) LH	5.00	0.00	*104.00 FL
19	1		*FRONT FENDER COWLING (REAR) LH	5.00	0.00	*104.00 FL
20	1		*FRONT FENDER EMBLEM (SPORT) LH	5.00	0.00	*45.00 FL
21	1		*FRONT FENDER BRACKET LH	5.00	0.00	*32.15 FL
22	1		*FRONT SPORT RIM LH	5.00	0.00	*899.25 FL
23	1		*FRONT TYRE LH - CHECK	5.00	0.00	-
24	1		*FRONT WHEEL BEARING LH	5.00	0.00	*465.75 FL
25	1		*FRONT KNUCKLE ARM LH	5.00	0.00	*439.10 FL
26	1		*FRONT LOWER ARM LH	5.00	0.00	*262.20 FL
27	1		*FRONT LOWER ARM STAY LH	5.00	0.00	*262.20 FL
28	1		*FRONT DRIVE SHAFT LH - CHEK	5.00	0.00	-
29	1		*FRONT SHOCK ABSORBER LH - CHECK	5.00	0.00	-
30	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH - CHECK	5.00	0.00	-
31	1		*FRONT SHOCK ABSORBER TOP MOUNTING BEARING LH - CHECK	5.00	0.00	-
32	1		*STEERING RACK & PINON - CHECK	5.00	0.00	-
33	1		*STEERING RACK TIE ROD END LH	5.00	0.00	*169.35 FL
34	1		*STEERING RACK TIE ROD LH	5.00	0.00	*282.35 FL
35	1		*ENGINE MOUNTING LH - CHECK	5.00	0.00	-
36	1		*ENGINE MOUNTING RH - CHECK	5.00	0.00	-
37	1		*FOG LAMP LH	5.00	0.00	*276.40 FL
38	1		*FOG LAMP GARNISH LH	5.00	0.00	-
39	1		*FOG LAMP MOULDING LH	5.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,932.25
- List Item Discount on L Items (\$\$)	396.61
<b>Total Parts (\$\$)</b>	<b>7,535.64</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO KNOCK AND STRAIGHTEN FRONT BODY MEMBER, FRONT FENDER INNER PANEL LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	800.00
2	SPRAY PAINT BONNET, FRONT BUMPER, FRONT FENDER INNER PANEL, FRONT FENDER LH	New	700.00
3	REMOVE AND REPLACE FRONT UNDER CARRIAGE SUSPENSION	New	250.00
4	REMOVE & REPLACE ENGINE MOUNTING & CHECK GEAR BOX MOUNTING	New	180.00
5	REINSTALL HEADLAMP AND REPROGRAMME	New	200.00
6	COMPUTER WHEEL ALIGNMENT	New	60.00
7	CHECK WIRING AND FOCUS HEADLIGHT	New	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,230.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >