

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. :	BG 3648	Page No. :	1 of 2
Date Estimated :	11/04/2018		
Prepared By :	Wong Guo Xiang		

- ESTIMATE REPAIR FOR - Lin Pei-Jun Angela 27 Holland Hill #02-01 Singapore 278741	- ACCOUNT - 2000 CASH - Sale service .
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL6388L	WF05XXGCC5GK13869	07/03/2017	Foc 1.0 5Dr	0

DESCRIPTION	VALUE
SUNDRIES	30 150.00
REPLACE / REPAIR REAR BUMPER, REAR END PANEL	900 1,800.00
RESpray REAR BUMPER, REAR END PANEL	1200 1,800.00
WIRING CONNECTION & CHECK (NETT)	120 150.00
TO REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)	X 150.00
TO REMOVE & REFIX REVERSE SENSOR (NETT)	150.00
REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH (NETT)	X 300.00
TUFF KOTE @ \$60 PER PANEL	X 120.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE (NETT)	600.00

Total Labour 1: 5,220.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB17906ABX	REAR BUMPER	1	1,314.00	10.00	1,182.60
WAA					
BM51A17B861A	BRACKET	1	125.00	10.00	112.50
E					
F1EB17F954AB	REAR BUMPER LWR EXTENSION	1	301.00	10.00	270.90
BM51A403C94A	RR BPR REINFORCEMENT - F11	1	626.00	10.00	563.40
F					
F1EB17E850DB	RR BUMPER SIDE BRACKET RH	1	75.00	10.00	67.50
F1EB17E851DC	RR BUMPER SIDE BRACKET LH	1	75.00	10.00	67.50
F1EB17A881AA	RHR BUMPER MTG BRACKET	1	63.00	10.00	56.70
F1EB17A882AA	LHR BUMPER MTG BRACKET	1	63.00	10.00	56.70
AM5T15K870BB	RR PARKING AID BRACKET, UNPRIMED	2	48.00	10.00	86.40
XUAA					

Total Parts : 2,464.20

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. :	BG 3648	Page No. :	2 of 2
Date Estimated :	11/04/2018		
Prepared By :	Wong Guo Xiang		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL6388L	WF05XXGCC5GK13869	07/03/2017	Foc 1.0 5Dr	0

Resul
Hp 90010068
4 days
13/04/18 @ 1615
Resum by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	Labour 1 :	5,220.00
	Parts :	2,464.20
	Labour 2 :	0.00
	Excess :	0.00
	Total GST @ 7% :	537.89
Customer Service Officer	Contact	Grand Total : 8,222.09

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.