

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SLT3859Y	Excess.	NIL
Policy No.	B29045797MCX	Coverage.	Comprehensive
Claiming Against.	SLF2193P	AIG	
Insured Under.	MSIG		

Vehicle Particulars & Condition

Make & Model	Honda City
Engine No.	L15A71806706
Chassis No.	MRHGM26709P020342
Odometer	
Engine CC.	1497
Year Of Reg.	2009
Colour.	WHITE
Parf/COE Rebate.	\$ 12,161.00

Not Allowed
over
2/5 #3050/2
\$ day.
11/4/18

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion damaged.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

General Information

Accident Date. 7/4/2018
Survey held at

Acknowledged by Repairer
Signature:
Date:

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper <i>DD</i>	\$ 476.30 <i>/</i>
1	Rear bumper side retainer LH <i>Bul</i>	\$ 28.38 <i>/</i>
1	Rear bumper side retainer RH <i>Bul</i>	\$ 28.38 <i>/</i>
1	Rear bumper bracket LH <i>nu</i>	\$ 14.70 <i>/</i>
1	Rear bumper bracket RH <i>nu</i>	\$ 14.70 <i>/</i>
1	Boot lid <i>ms/Bul</i>	\$ 430.10 <i>/</i>
1	Boot lid logo <i>nu</i>	\$ 23.10 <i>/</i>
1	Boot lid "VTEC" emblem <i>nu</i>	\$ 14.10 <i>/</i>
1	Boot lid "CITY" emblem <i>nu</i>	\$ 30.80 <i>/</i>
1	Boot lid hinge LH <i>1</i>	\$ 70.73 <i>X</i>
1	Boot lid hinge RH <i>1</i>	\$ 70.73 <i>X</i>
1	Boot lid lock <i>7w1</i>	\$ 172.15 <i>/</i>
1	Boot lid lock catch <i>11</i>	\$ 15.30 <i>X</i>
1	Boot lid rubber <i>7w1</i>	\$ 98.70 <i>/</i>
1	Boot lid inner trim <i>11</i>	\$ 140.50 <i>X</i>
1	Rear taillamp LH <i>1KQ</i>	\$ 226.27 <i>2</i>
1	Rear taillamp RH <i>1KQ</i>	\$ 226.27 <i>2</i>
1	Rear taillamp panel LH <i>1</i>	\$ 114.40 <i>X</i>
1	Rear taillamp panel RH <i>1</i>	\$ 114.40 <i>X</i>
1	Rear taillamp rubber LH <i>11</i>	\$ 60.00 <i>X</i>
1	Rear taillamp rubber RH <i>11</i>	\$ 60.00 <i>X</i>
1	Rear end panel	\$ 419.60 <i>2</i>
1	Rear end panel top garnish <i>7w1</i>	\$ 183.26 <i>2</i>
1	Rear spare tyre board <i>7w1</i>	\$ 187.88 <i>/</i>
1	Rear spare tyre bolt <i>11</i>	\$ 22.00 <i>X</i>
1	Rear spare tyre panel <i>1</i>	\$ 757.40 <i>X</i>

List \$ 4,000.15
Less 20% \$ 800.03
Total \$ 3,200.12

2574.69

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper clips (1 set) <i>nu</i>	\$ 45.00 <i>✓</i>
1	Rear number plate <i>cu7</i>	\$ 45.00 <i>40</i>
1	Rear reverse sensor (1 set) <i>shub</i>	\$ 200.00 <i>200</i>
1	Rear spare tyre panel insulator (1 set) <i>u1</i>	\$ 180.00 <i>X</i>
1	Rear end panel top garnish clips (1 set) <i>u1</i>	\$ 40.00 <i>X</i>
	S/N	\$ 425.00

LABOUR

To apply undercoating on the repaired and replaced panels for rust protection.

\$ 100.00 *60*

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.

\$ 60.00 *30*

To remove and refit rear bumper sensor.

\$ 80.00 *50*

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

\$ 1,000.00 *600*

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

\$ 800.00 *750*

LABOUR \$ 2,040.00 *1775*

Sub Total. \$ 5,665.12

7% GST \$ 396.56

Grand Total \$ 6,061.68

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.