

FIRST AUTOWORKS

Repair Estimate

Date: 10/04/2018

Make : Chevrolet
Captiva

To Whom It May Concern

Dear Sir,

Re: VEHICLE.SKT 7338U
CHASSIS NO.: KL1CA26UJFB014288
ENGINE NO.: LE9142820037

Names of insured : Alpine Car Rental Pte Ltd
Date of accident : 09/04/2018

*Not Authorised
to KKK Marcus.
Take photo before repair
3 days.
11/4/18*

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>11</i>	1,962.00 <i>X</i>
2	1	HOOD LATCH <i>11</i>	130.00 <i>X</i>
3	1	TOP PANEL COVER <i>11</i>	160.00 <i>X</i>
4	1	FRT BUMPER FASCIA <i>11/12</i>	1,882.00 <i>1</i>
5	1	FRT BUMPER BRACKET LH <i>11/12</i>	56.00 <i>1</i>
6	1	FRT BUMPER BRACKET RH <i>11/12</i>	56.00 <i>1</i>
7	1	FRT BUMPER (BOLT) SET <i>11/12</i>	60.00 <i>1</i>
8	1	FRT LWR BUMPER <i>11</i>	912.00 <i>X</i>
9	1	FRT EMBLEM <i>11</i>	153.00 <i>1</i>
10	1	NO. PLATE BASE <i>11/12</i>	47.00 <i>1</i>
11	1	TOP GRILLE <i>11</i>	380.00 <i>X</i>
12	1	TOP PANEL <i>11</i>	712.00 <i>X</i>
13	1	TOP PANEL COVER CLIP SET <i>11</i>	50.00 <i>X</i>
14	1	BOTTOM GRILLE <i>11</i>	578.00 <i>1</i>
15	1	AIR DUCT <i>11</i>	167.00 <i>X</i>
16	1	BUMPER ABSORBER <i>11</i>	130.00 <i>X</i>
17	1	REINFORCEMENT BAR <i>11</i>	966.00 <i>X</i>
18	1	RADIATOR ASSY <i>11</i>	983.00 <i>X</i>
19	1	CONDENSOR ASSY <i>11</i>	871.00 <i>X</i>
20	1	HORN <i>11</i>	80.00 <i>X</i>
21	1	HEAD LAMP LH <i>11</i>	1,274.00 <i>X</i>
22	1	HEAD LAMP LH UPPER COVER <i>11</i>	19.00 <i>X</i>
23	1	FOG LIGHT LH COVER <i>11</i>	37.00 <i>X</i>
24	1	FOG LIGHT LH <i>11</i>	320.00 <i>X</i>
25	1	HEAD LAMP RH <i>11</i>	1,274.00 <i>X</i>
26	1	HEAD LAMP RH UPPER COVER <i>11</i>	19.00 <i>X</i>
27	1	FOG LIGHT RH COVER <i>11</i>	37.00 <i>X</i>
28	1	FOG LIGHT RH <i>11</i>	320.00 <i>X</i>

Parts Total : 13635.00
Less 10% : 1363.50
Total : 12271.50

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	2500.00 700
<u>2</u>	Carry out spray painting on affect area frt portion	1800.00 450
<u>3</u>	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	50.00 30
<u>4</u>	Carry out check on air con system due to accident	11 120.00 X
Labour Total :		4470.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>1</u>	Frt number plate	mis / 40.00 40.00 ✓
<u>2</u>	Coolant	11 60.00 X
<u>3</u>	ATF fluid	11 100.00 X
Other Total :		200.00

Total : 16941.50
Gst (7%) : 1185.91
Grand Total: 18127.41

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Advisor

Ronnie Tan

DID: 6844 1985 Fax:6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: