

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4830D

DATE 10/4/2018 10:39

MAKE :

Jumani

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Grille (LH) ✓			\$ 40.30
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) x			\$ 169.80
	Frt Wheel Hub Cap, LH ✓			\$ 150.70
	SUB TOTAL			\$ 3,096.90
	LESS 20%			\$ 619.38
	DISCOUNTED TOTAL			\$ 2,477.52
	Labour Charge			750
	Panel Beating			\$ 450.00
	Spray Painting Charge			\$ 500.00 450
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 x
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 3,607.52
Ka la (LKK) 10/4/18 12456 3 Days 45 After Repair p.k.				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				