

REPAIR ESTIMATE*

VEHICLE NO : SH 9000Z

MAKE :

MODEL : HYUNDAI i40

DATE 10/4/2018 11:27

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH) <i>X 147 52</i>			\$ 980.50
	SUB TOTAL			\$ 980.50
	LESS 20%			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	Labour Charge			<i>50</i>
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,234.40
	<i>Ka Lin 1/1/14</i>			
	<i>10/4/14 1215h</i>			
	<i>1 Ry</i>			
	<i>RIP</i>			
	<i>After from p4</i>			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			