

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7588A

DATE 10/4/2018 11:41

MAKE :

MODEL : HYUNDAI i40

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid CRDI Plate X			\$ 41.00	
	Bootlid Moulding X			\$ 85.00	
	Bootlid i40 Emblem X			\$ 41.00	
	Bootlid Lower Garnish X			\$ 398.00	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	Rear Panel X Rep			\$ 592.30	
	Rear Panel Garnish ?			\$ 57.70	
	Rear Panel Lower Panel X Rep			\$ 495.50	

Kahai 10/4/18

10/4/18 1315 L

3 days

L

After Repair job