

ASS. REC. BY:

REF: CS/FCI18006714/ Kvd3⁷²

Special Instruction:

Surveyor:

Kendall

ASSIGNMENT (Office)

CWS

From (Person):

Serene Ler

of

FCI

Date/Time: 11/4/18 @ 3:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 9705K

Insured:

SHC 28392

at Workshop m/s:

Trans-Cab

Tel:

6287 6666

of

No. 2 AMK sf-63

Policy No:

Claim No:

D18002761MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/04/2018

CA / REV / REP. / REV 24 HRS

'wp'

12/04/2018

H.O.D. Endorsement:

Date/Time:

3:46pm @ 11/4/18

Person Contacted:

Candy

Vehicle: IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate Error on TPV (Est. COR for SHD 327s not related to this accident)
	SHB 9705K - CC3/AXA 16002451/Kyg3s2 DOA: 02/02/16
	SHC 28392 - CS/MSG 17013411/Klvbn2 DOA: 10/07/17
13/4/18	Email preli revised to FCI

REF: FCI

Signature

ASSIGNMENT

From:

Date:

12/04/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 9705K

at Workshop m/s

Trans-cab

of

No. 2 AMK st. 63

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Error on TPV Cest-COR for SHB 327S not
related to this accident
(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01

days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 9705K

Yr Regn:

07, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault ^(A) Latitude C.C. 1995

Colour:

White 1R

A/C:

Insured / Std / NI / NA

Sp. Reading

434217

T/Radio:

Insured / Std / NI / NA

Eng/No:

VF1ABL15AUC 273249

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

5/4/18

D.O.I.

12/4/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/4 File pass to Catherine

8 22 ch (Red 45, 327-07, 9910)

RECEIVED 13 APR 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

13/4 - typist

Report Format :

TP

Lump Sum / I.B.I. (\$) :

22002

Days Of Repair:

1

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

) S + RS) SI

) Phone

) Others

13/4/18

35 X 15 = 525

170 + 525
50

9

754



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006714/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2839Z	Veh. Inspected	SHB 9705K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002761MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/04/2018	Inspection Date		
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002761MFSH

Our ref: CS/FCI18006714/Kvd3

Date : 13/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9705K


We thank for your instruction on 11/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/4/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$45,547.07
Revised Estimate Amount	: S\$220.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Job Sheet (/ClaimWS/Surveyor/JobSheet/236754)



PRI Documents



Close



PRI Header Details

Claim No	D18002761MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/ [M/S TRANS-(CHONG KOK)
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 62876666 , Phone: 62876666 , Fax: 62877766 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ERROR ON TPV (EST. COR FOR S THIS ACCIDENT).		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2839Z	TP Vehicle No	SHB9705K
PRI Recieved Date	10-04-2018 03:46:18 PM	Surveyor Appointed Date	11-04-2018 03:38:19 PM	Surveyor Accept Date	11-04-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

MOTOR SURVEY ASSIGNMENT

Date	09-04-2018	Our Ref No. D18002761MFSH
Accident Date	05-04-2018	Claim Type. Third Party
Insured Vehicle	SHC2839Z	Third Party Vehicle. SHB9705K
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 62876666	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE: ERROR ON TPV (EST. COR FOR SHD327S NOT RELATED TO THIS ACCIDENT).	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 April 2018 2:44 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002761MFSH/1, SHB 9705K
Attachments: SHB 9705K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 9705K
Date of survey: 12/4/2018
Number of days: 1 day

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 11 April 2018 3:49 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002761MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 11 April 2018 3:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002761MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9705K
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000211
Chassis No.:	VF1ABL15AUC273249
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Jul 2013
First Registration Date:	18 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2021
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	17 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$21,239.00
Total Rebate Amount:	\$30,612.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Apr 2018.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 327S**AAD1804-065***Not Authorised
LH 8220p*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 97006

VF1ABL15AUC282638

RENAULT

LATITUDE

5.4.2018

*FIL***PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>R</i>	1,108.46	} <i>X</i>
2	1 BUMPER LOWER REAR	\$	<i>SL</i>	768.84	
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i>	113.47	
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i>	135.97	
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i>	44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i>	43.61	
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i>	135.97	
8	1 BUMPR RETAINER LH REAR	\$	<i>SL</i>	44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i>	43.61	
10	1 BUMPER BEAM REAR	\$	<i>R</i>	777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i>	225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i>	225.95	
13	1 BOOT REAR	\$	<i>R</i>	2,872.68	
14	1 BOOT FINISHER	\$	<i>SL</i>	470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i>	323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i>	493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i>	493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i>	225.36	
19	1 BOOT BADGE	\$	<i>SL</i>	225.36	
20	1 BOOT STRUT LH	\$	<i>SL</i>	276.08	
21	1 BOOT STRUT RH	\$	<i>SL</i>	276.08	
22	1 BOOT HINGE LH	\$	<i>R</i>	367.84	
23	1 BOOT HINGE RH	\$	<i>R</i>	367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i>	586.45	
25	1 BOOT SWITCH	\$	<i>SL</i>	168.13	
26	1 BOOT LOCK	\$	<i>R</i>	202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i>	74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i>	50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i>	221.81	

Trans-cab Auto Services Pte Ltd**AAD1804-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 327S

30	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	}	X
31	1 FENDER PANEL REAR LH	\$	N	3,299.13		
32	1 WHEELARCH REAR LH	\$	Sn	543.47		
33	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45		
34	1 FENDER PANEL REAR RH	\$	N	3,299.13		
35	1 WHEELARCH REAR RH	\$	Sn	543.47		
36	1 TAILLAMP RH	\$	Sn	552.55		
37	1 TAILLAMP PANEL RH	\$	N	986.70		
38	1 TAILLAMP LH	\$	Sn	552.55		
39	1 TAILLAMP PANEL LH	\$	N	986.70		
40	1 OUTER PANEL REAR (End Panel)	\$	N	1,471.77		
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56		
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88		
43	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
44	1 EXHAUST REAR	\$	N	7,489.05		
45	1 EXHAUST CAP REAR	\$	N	230.49		

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET PARKING AID	\$	Sn	700.00	}	X
2	1SET REAR BUMPER CLIP	\$	N	66.00		
3	1SET BUMPER BRACKET CTR CLIP	\$	N	33.00		
4	1SET BUMPR BRACKET SIDE CLIP RH RR	\$	N	10.00		
5	1SET BUMPR RETAINER RH CLIP RR	\$	N	20.00		
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	N	10.00		
7	1SET BUMPR RETAINER CLIP LH RR	\$	N	20.00		
8	1SET BUMPER LOWER REAR RIVET	\$	N	22.00		
9	1SET BUMPER LOWER REAR CLIP	\$	N	66.00		
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82		
11	1SET BOOT FINISHER CLIP	\$	N	24.20		
12	1 BOOT STICKER "Trans-cab"	\$	N	30.00		
13	1 BOOT STICKER "6555-3333"	\$	N	30.00		
14	1 BOOT INNER TRIM CLIP	\$	N	45.00		
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	N	35.00		

Trans-cab Auto Services Pte Ltd**AAD1804-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 327S

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	~ 35.00	}
17 1 FENDER INNER TRIM CLIP LH	\$	~ 28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	~ 28.00	
19 1 TAILLAMP CLIP RH	\$	~ 5.00	
20 1 TAILLAMP CLIP LH	\$	~ 5.00	
21 2 REAR WINDSCREEN SELANT	\$	~ 80.00	
22 1 WINDSCREEN MOULDING	\$	~ 100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	~ 100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	~ 385.00	
25 1 SPARE TYRE	\$	~ 330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 34,507.07****LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 4,500.00 2201

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ ~ 4,200.00 X

To Rust-Proofing Of The Affected Areas. \$ ~ 170.00 X

To reinstall rear bumper parking sensor. \$ ~ 170.00 X

To transfer of bootlid fittings, attachments and
perform water seepage test. \$ ~ 170.00 X

To repair and realign rear exhaust pipe. \$ ~ 170.00 X

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe. \$ ~ 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ ~ 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1804-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 3275

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	4 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X

TOTAL \$ 11,040.00**Over All Total \$ 45,547.07**

05

Repair Days (PART BY PART)~~15 Days~~

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006714/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2839Z	Veh. Inspected	SHB 9705K	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002761MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273249	Colour	WHITE / RED	
Odometer	434217	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/04/2018	Inspection Date	12/04/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9705K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FCI18006714/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,586.89	-
			32,282.03	-
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/FCI18006714/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	-
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.	NOT NECESSARY	4,200.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI18006714/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATING PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			11,040.00	220.00
	GRAND TOTAL		45,547.05	220.00
RECOMMENDED COST OF REPAIRS				220.00

Report Ref No. CS/FC118006714/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.