

INS CASE OWNER

CC 4, AIG160 19440, G793

LEK
IDAC

Surveyor:

X6Q

DOI

13/10/16

Date/Time

13/10/16

Registered in Meritman

13/10/16

Pre-assign / CCU / FTE



Insured Vehicle No

SJS 2287 H

Name of Insured

SHYAN A BASU

Insured Tel No

HP

91252392

Excess Sec II :\$5

D.O.A

27/9/16

Is driver the owner?

YES / NO

Nature of Accident

If NO, Driver Name / Age

AZIZAN BIN MOHAMMAD

Driver Tel No

(V/L YES/NO)

Claim No

85488 7024256

Policy No

71004 35001

Make / Model

7. ESTIMA

Place of Accident

Tampines Ave 9

OI GLA REPORT YES / NO, TP GLA REPORT YES / NO

Insured Liability

%

Final ? Yes / No

SJS 6232 L



INSRS

WSP

Tel

Liability

RMKS

Tai Chong



INSRS

WSP

Tel

Liability

RMKS

SJS 6232 L



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS

REC BY: 228REF: 16019440/5793**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Tan Ching Motor

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? **Yes** or **No**GIA / PR Seen: _____ Consistent? **Yes** or **No**Est. Repairs: 1 days Res. **Yes** or **No**Lum Sum: 20 % 3 Val. **Yes** or **No****CA / REV / REP. / 24 HRS**

Date: _____ Person Contacted: _____

Vehicle: **IN / OUT**Veh No: 3TIC322 Yr Regn: 19/54/1Type: **M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make: 1992 Honda Civic / cc 1700Colour: Blue A/C: **Insured / Std / NI / NA**Sp Reading: 123000 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: BT100-970Gen Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** or _____Brake: **Inorder / Jammed / Leaked / Burnt** or _____Mod: **Nil / S/Rim / STD A/Rim** or _____Tyre Size **F:** 215/55R17**R:** _____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or _____**Front****Rear**

R/Bal: _____ mm R/Bal: _____ mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A: _____ D.O.I: 13-10-16Survey held at: 10/12/16 11:30AmDes. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or _____The **U/C / Chassis frame / Body Structure** affected due to collision

Date / Time: _____ Action / Instruction: _____

PD \$ 6342.56, 6 days2nd L/Bal \$ 6000 with conditions [F 173] 30Reel \$ 517.36, 6 f.RED (\$2,059.92/23%)

Date/Time, File Pass to?

☐**Prel. Report**

Days Of Repair: _____

1)

☐**Final Report**

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2016 13:59
Date Of Accident	27/09/2016 08:00
Exact Location Of Accident	TAMPINES AVE 9 / TAMPINES ST 73 (YELLOW BOX)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ6232L
Insured/Policyholder	
Name Of Registered Owner	TAN AI GEK
NRIC No	S1685103E
Email Address	TANAGCT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94301478
Alternative Phone No	Office-67477740
Vehicle Particulars	
Manufacturer	HONDA
Model	CROSSROAD
Exact Purpose for which vehicle was being used at time of accident	GOING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5077231830
Cover Note Number	
Driver	
Name of Driver	TAN AI GEK
NRIC No	S1685103E
Date Of Birth	13/05/1965
Occupation	Indoor
Date Of Driving Pass	04/06/1987
Driving Experience	29 Years And 3 Months
Gender	Female
Mobile Number	(Local) +65-94301478
Fax Number	
Contact Number	Office-67477740
EMail Address	TANAGCT@GMAIL.COM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2016 13:18
Date Of Accident	27/09/2016 08:05
Exact Location Of Accident	TAMPINES AVE 9
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS2287H
Insured/Policyholder	
Name Of Registered Owner	SAYANTA BASU
NRIC No	S2767044Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96252392
Alternative Phone No	Office-96252392

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 AERAS (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100425331
Cover Note Number	

Driver

Name of Driver	AZIZAN BIN MOHAMED
NRIC No	S7426368B
Date Of Birth	29/08/1974
Occupation	Indoor
Date Of Driving Pass	05/09/2002
Driving Experience	14 Years And 0 Months
Gender	Male
Mobile Number	
Fax Number	
Contact Number	
Email Address	spyace.saint@gmail.com

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #04-18
ANG MO KIO AUTOPOINT SINGAPORE 568047
TEL: 64835595 62547029 64835515 FAX: 64835895
Business Registration No: 234718/00E
GST Registration No: 23-471800-E

Email: shenhuai@taichengpaints.com

MS ASIA PACIFIC TRADING PTE LTD
CHARTE BUILDING
78 SPRATON WAY #08-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT.
THIRD PARTY

DEAR SIR/MADAM

ACCIDENT ALONG TAMPINES AVE 9 / TAMPINES ST 73 Box Junction
INVOLVING VEHICLE NO SJS 62326 / SJS 22874 ON 27/9/16

We understand that you are the insurer of SJS 22874 vehicle.

I/ We wish to inform you that my/ our vehicle SJS 62326 have been completed repairs to my/ our satisfaction by M/s Tai Cheng Motor Vehicle Spray Painting

I/ We therefore propose to claim from your as follows:

- 1 Cost of repair
- 2 Loss of use/ rental (S\$ 60 x 7 days) 6+1 Sunday
- 3 LTA Search Fee/ GIA Reports

TOTAL

\$ 7276.00 incl. GST 7%
\$ 60.00
\$ 5.25
\$ 7701.35

Please let us have the reply soonest possible

Thank You

Your faithfully,
天進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#04-18 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6483 5515 Fax: 6483 5895

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #04-18
ANG MO KIO AUTOPORT SINGAPORE 568047
TEL: 64835515 62547029 64835515 FAX: 64835895
Business Registration No: 234718/00E
GST Registration No: 23-471800-E

YOUR REF:
OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT (THIRD PARTY)

Accident Along Tampines Ave 9 / Tampines St.73 Involving Vehicle SJA6232L
And SJS2287H On 27.09.16

Cost of repair to damage vehicle SJA6232L claiming against your insured
SJS2287H

Description	QTY	Price
front fender	1	\$ 623.40
front fender end side rubber	1	\$ 286.20
front fender undershield	1	\$ 148.70
front fender side protector	1	\$ 233.60
front bumper	1	\$ 1,308.20
front bumper side garnish	1	\$ 290.10
front headlamp	1	\$ 980.40
front headlamp lower bracket	1	\$ 68.00
front sport rim	2	\$ 180.00
front shock absorber	1	\$ 428.70
front shock absorber top mounting	1	\$ 105.60
front knuckle arm	1	\$ 175.30
front knuckle arm bearing	1	\$ 129.60
front lower arm	1	\$ 420.80
steering rack and pinion	1	\$ 1,891.00
steering ball joint	1	\$ 125.60
anti roll bar link	1	\$ 115.20
		\$ 8,262.40
PARTS LESS 20%		\$ 1,652.48
		\$ 6,609.92

Miscellaneous

supply of clips	\$ 40.00
tyre	\$ 380.00

Labour

to remove all accident affected wiring, check and focus of headlamp	\$ 40.00
to wheel alignment after repair	\$ 60.00
to remove of front damaged undercarriage replace and fixing of same	\$ 150.00
to replace of rim and tyre and wheel balancing after repair	\$ 40.00
to reset of ECU after repair	\$ 60.00
to remove damaged panels, jacking, straighten, knocking flattening of fender inner panel, fixing and align of parts	\$ 550.00
to respray of accident affected portion	\$ 750.00
	\$ 8,839.92

Total Dollars Estimated: Eight Thousand Eight Hundred Fifty Nine And Cent
Ninety Two Only.

大進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#04-18 Ang Mo Kio Auto Port
Singapore 568047
Tel: 6483 5515 Fax: 6483 5895

Billup
Insurance Spr
After repair photos
Email to: 828012
Phone: 011-11111111
12/10/16

700 (S.A.)

748 304

5588 52

296

486

700

1820

8518.52

20% 1763.90

TAI CHENG MOTOR VEHICLE SPRAY PAINTING
 BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #04-08
 ANG MO KIO AUTOPORT SINGAPORE 668047
 TEL 64835595 62547029 64835515 FAX 64835595
 Business Registration No: 23471800E
 GST Registration No: 23471800E

Consultants hence notify
 the Repairer of the following:
 To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurer
 27/9/16
 Acknowledged by Repairer
 Signature:
 Date:

YOUR REF:
 OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT (THIRD PARTY)
Accident Along Tampines Ave 9 / Tampines St 73 Involving Vehicle SJ6232L
And SJS2287H On 27.09.16
Cost of repair to damage vehicle SJ6232L claiming against your insured
SJS2287H

Description	QTY	Price
front fender	1	142.10
front fender end side rubber	1	2.15
front fender undershield	1	148.70
front fender side protector	1	2.15
front bumper	1	2,308.20
front bumper side garnish	1	240.10
front headlamp	1	980.40
front headlamp lower bracket	1	68.00
front sport rim	1	781.10
front shock absorber	1	428.10
front shock absorber top mounting	1	111.80
front knuckle arm	1	177.00
front knuckle arm bearing	1	129.80
front lower arm	1	420.80
steering rack and pinion	1	1,891.00
steering ball joint	1	125.60
anti roll bar link	1	117.20
		8,296.40
		1,632.48
		9,928.88

PARTS LESS 20%

Miscellaneous

supply of clips	1	10.00
tyre	1	180.00

Labour

to remove all accident affected wiring, shock and focus of headlamp	1	40.00
to wheel alignment after repair	1	60.00
to remove of front damaged undercarriage replace and fixing of water	1	1,500.00
to replace of rim and tyre and wheel balancing after repair	1	10.00
to reset of ECU after repair	1	60.00
to remove damaged panels, jacking, straighten, knocking/ flattening of	1	300.00
fender inner panel, fixing and align of parts	1	700.00
to respray of accident affected portion	1	8,834.92

Total Dollars Estimated: Eight Thousand Eight Hundred Fifty Nine And Cent
Ninety Two Only

大進汽車噴漆廠
 Tai Cheng Motor Vehicle Spray Painting
 Blk 10 Ang Mo Kio Industrial Park 2A
 #04-18 Ang Mo Kio Auto Port

After repair photos
 8515.92
 20%: 6800.
 15/10/16

7482.4
 5985.92

290.

1540

Before Repair Alignment
 Repair NEBBOS



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG16019440/Gza3

21 OCTOBER 2016

SAYANTA BASU
11 UPPER BEDOK ROAD
SINGAPORE 466644

Dear Sir/Madam,

ACCIDENT INVOLVING SJS 2287H / SJJ 6232L / OTHERS ON 27/09/2016

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

R Vasanthi(Ms)
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: vicapgeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT


(AIG Asia Pacific - Express Third Party Claim)

I, TAN AI GER (the third party claimant) BLK 739 #03-52 TAMPINES ST 72(9) 50739
(address), owner of SJS 6332L (vehicle no.) hereby authorize TAI CHENG MOTOR VEHICLE SPRAY
PAINTING ("the workshop") to act for me with respect to my claim for repair costs and/or rental
and/or loss of use ("claim") for my vehicle no. SJS 6332L, that was damaged pursuant to the accident
which occurred on 27/09/16 (date) along TAMPINES AVE 9 / ST 72 (location) involving vehicle no/s SJS
2287H ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 13 (day) of 10 (month) 2016 (year)


Signed by "the third party claimant"
(with chop if applicable)

大進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#04-18 Ang Mo Kio Auto Point
Singapore 568947
Tel: 6483 5545 Fax: 6483 5895


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **TAI CHENG MOTOR VEHICLE SPRAY PAINTING** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$7,276.00** (Repair Cost), **S\$420.00** (Loss of Use) **5.35** (Disbursement) for vehicle no. **SJJ 6232L** that was damaged pursuant to the accident which occurred on **27/09/2016** (date) along **TAMPINES AVE 9** (location) involving vehicle no/s **SJS 2287H**. This is pursuant to the inspection conducted on **13/10/2016** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TAN AI GEK** ("the third party claimant") of vehicle no. **SJJ 6232L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJJ 6232L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of APRIL (month) 20 18 (year)



Signed by appointed surveyor

大進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#04-18 Ang Mo Kio Auto Point
Singapore 568047

Signed by the workshop (with chop)

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #04-18
ANG MO KIO AUTOPOINT SINGAPORE 568047
TEL: 64835595 62547029 64835515 FAX: 64835895

Business Registration No: 234718/00E

GST Registration No: 23-471800-E

Email: shchua@taichengmotor.com

TAX INVOICE

YOUR REF: SJS2287H

DATE: 08.01.18

OUR REF: SJJ6232L

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

THIRD PARTY CLAIM

ATTN: THE MOTOR CLAIM DEPT.

RE: FINAL BILL TO DAMAGED VEHICLE SJJ6232L ACCIDENT ON 27.09.16
CLAIMING AGAINST YOUR INSURED SJS2287H

BEING LUMP SUM REPAIR COST TO VEHICLE SJJ6232L
INCLUSIVE OF SPARE PARTS AND LABOUR CHARGES
AS RECOMMENDED BY THE SURVEYOR

	\$	6,800.00
GST 7%:	\$	476.00
Total:	\$	<u>7,276.00</u>

TOTAL FOLLARS: SEVEN THOUSAND TWO HUNDRED SEVENTY SIX ONLY.

大進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#04-18 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6483 5515 Fax: 6483 5895



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 08 Oct 2016 / 08:18:51

Receipt Date/Time : 08 Oct 2016 / 08:18:51

Tax Invoice/Receipt

Receipt No. : ITNET-00000-161008-000056

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJS2287H As at 27 Sep 2016/08:00:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJS2287H Enquiry Fee 20161008081729149753	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	20161008081803587	Direct Debit: eNETS Debit (Internet Banking)		5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Oct 2016 Edit Reg		13 Oct 2016 00:00 Edit Adj Rpt	\$46,800.00 Edit Estimates	\$46,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	SAYANTA BASU , ID: S2767044Z								
Main Claimant:	TAN AI GEK , ID: S1685103E								
Vehicle Reg. No.:	SJJ6232L	Date of Loss:	27/09/2016 08:00 - :59 [96 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8548878242SG	Policy/Cover Note No.:	2100425331						
Vehicle Reg. No. (Insured):	SJS2287H	Policy No. (Claimant):	5077231830						
		Excess:							
Repairer:	Tai Cheng Motor Vehicle Spray Painting (HQ) Block 10 Ang Mo Kio Industrial Park 2A, #04-18 AMK Autopoint, 568047 Ang Mo Kio - Tel: +65 64835515								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijie.Wui@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/04/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• AIG_SG_EXPRESS (11/04/2018): Report Send Back Alerts - SJJ6232L (TP)									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJJ6232L (8548878242SG)**
[SJS2287H]
TP
TAN AI GEK
Sep 27 2016 8:00AM
[SAYANTA BASU]
Tai Cheng Motor Vehicle Spray Painting

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
2	12/02/18 13:13	Insurer Offer Letter/DV [Offer superseded on 2018/04/11]												1	Load HTM					
															1 per page		<input checked="" type="checkbox"/>			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	14/10/16 10:46	Accident Statement From:OD - Reg. No: SJS2287H, Claimant: SAYANTA BASU												1	Load HTM					
															3 per page		<input checked="" type="checkbox"/>			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	14/10/16 13:50	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>				
2	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
3	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
4	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
11	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
12	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
15	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
16	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
17	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
18	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
19	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
20	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
21	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
22	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
23	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
24	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
25	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
26	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
27	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				
28	14/10/16 13:51	General View												1	Load JPG	<input checked="" type="checkbox"/>				

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
29	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
35	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
36	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
40	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
41	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
42	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
43	14/10/16 13:51	General View	 Load JPG	<input checked="" type="checkbox"/>	
44	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
45	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
46	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
47	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
48	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
49	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
50	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
51	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
52	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
53	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
54	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
55	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
56	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
57	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
58	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
59	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
60	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
61	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
62	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
63	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
64	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
65	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
66	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
67	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
68	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
69	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
70	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
71	27/12/17 09:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	13/10/16 14:52	EMAIL FROM AIG DD 131016	 Load PDF		
2	13/10/16 14:52	TP ESTIMATE + TP GIA REPORT	 Load PDF		
3	14/10/16 13:49	TP ESTIMATE - MARKED	 Load PDF		
4	20/10/16 08:59	LETTER TO OI	 Load PDF		
5	27/12/17 17:17	email to AIG	 Load PDF		

Letters/Correspondences			1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	11/04/18 16:51	TP LOD		Load PDF	
7	18/04/18 15:23	WORKSHOP INVOICE		Load PDF	
8	18/04/18 15:23	AUTHORISATION TO ACT FORM		Load PDF	
9	18/04/18 15:23	Release Voucher		Load PDF	
10	18/04/18 15:23	LTA SEARCH		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJS2287H (Insd veh)	Model:	HONDA CROSSROAD 1.8 (A)
	SJJ6232L (TP veh)		
Date of Accident:	27/09/2016		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,147.79
Final Repair Cost	:	\$	7,276.00
Loss of Use	:	\$	420.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,701.35

7.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tai Cheng Motor Vehicle Spray Painting	:	\$ 7,701.35
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

18 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG16019440/GJA3Q2-1

Date: 18/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425331
 Claimant Vehicle No: SJJ6232L Insured Vehicle No: SJS2287H
 Date of Loss: 27/09/2016 Nature of Claim: TP Claim No: 8548878242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ6232L
 Make & Model: HONDA CROSSROAD, 1.8 (A) Engine No: HIDDEN
 Reg. Date: 19/09/2008 (Man, Year: 2008) Chassis No: RT11007780
 Colour: Blue Odometer: 122986 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,643.92	6,975.92	668.00	8.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,540.00	300.00	16.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,483.92	8,515.92	968.00	10.21
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	9,483.92	6,800.00	2,683.92	28.30
+ GST 7.00/7.00% (S\$)	663.87	476.00	187.87	28.30
Nett Amount (S\$)	10,147.79	7,276.00	2,871.79	28.30
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		7,701.35		

INSPECTION

Date of Assignment: 13/10/2016
 Date Inspected: 13/10/2016 Inspected At: Tai Cheng Motor Vehicle Spray Painting (HQ)
 Block 10 Ang Mo Kio Industrial Park 2A,

#04-18 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Buckled	623.40 FL	*623.40 FL
2	1		*FRONT FENDER END SIDE RUBBER	Cracked	236.20 FL	*236.20 FL
3	1		*FRONT FENDER UNDERSHIELD	Torn	148.70 FL	*148.70 FL
4	1		*FRONT FENDER SIDE PROTECTOR	Cut	235.60 FL	*235.60 FL
5	1		*FRONT BUMPER	Cut	1,308.20 FL	*1,308.20 FL
6	1		*FRONT BUMPER SIDE GARNISH	Cracked	290.10 FL	*290.10 FL
7	1		*FRONT HEADLAMP	Cut	980.40 FL	*980.40 FL
8	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	68.00 FL	*68.00 FL
9	2		*FRONT SPORT RIM	Cut	1,248.00 FS	*700.00 FS
10	1		*FRONT SHOCK ABSORBER	Bent	428.70 FL	*428.70 FL
11	1		*FRONT SHOCK ABSORBER TOP MOUNTING	Bent	105.60 FL	*105.60 FL
12	1		*FRONT KNUCKLE ARM	Bent	375.30 FL	*375.30 FL
13	1		*FRONT KNUCKLE ARM BEARING	Bent	129.60 FL	*129.60 FL
14	1		*FRONT LOWER ARM	Bent	420.80 FL	*420.80 FL
15	1		*STEERING RACK AND PINION	Bent	1,891.00 FL	*1,891.00 FL
16	1		*STEERING BALL JOINT	Bent	125.60 FL	*125.60 FL
17	1		*ANTI ROLL BAR LINK	Bent	115.20 FL	*115.20 FL
18	1		*SUPPLY OF CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*TYRE	Cut	380.00 FS	*260.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,140.40	8,472.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,496.48	1,496.48

Total Parts (\$\$)	7,643.92	6,975.92
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL ACCIDENT AFFECTED WIRING ,CHECK AND FOCUS OF HEADLAMP	New	40.00	30.00
2	TO REMOVE OF FRONT DAMAGED UNDERCARRIAGE REPLACE AND FIXING OF SAME	New	350.00	200.00
3	TO REPLACE OF RIM AND TYRE AND WHEEL BALANCING AFTER REPAIR	New	30.00	30.00
4	TO RESET OF ECU AFTER REPAIR	New	60.00	40.00
5	TO REMOVE DAMAGED PANELS ,JACKING ,STRAIGHTEN ,KNOCKING FLATTENING OF FENDER INNER PANEL, FIXING AND ALIGN OF PARTS	New	550.00	480.00
6	TO RESPRAY OF ACCIDENT AFFECTED PORTION	New	750.00	700.00
7	TO WHEEL ALIGNMENT AFTER REPAIR WHEEL ALIGNMENT REPORT	New	60.00	60.00
Gross Labour Cost (S\$)			1,840.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >