

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTDER12WX03002906

TAN AI CHING SERENE
BLK 273D PUNGGOL PLACE
#03-892
S 824273

TP FWD.
Asher

Date :30.05.2018
Vehicle no :SFZ 5555 A
Make/Model :TOYOTA WISH
Accident date :11.04.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Rear tailgate <i>Dented.</i>	1	\$ 1403.5 1275.
2	Rear tailgate upper lock <i>and</i>	1	\$ 397.8 ✓
3	Rear tailgate lower lock <i>new</i>	1	\$ 38.8 x
4	Rear tailgate hinges @ \$94.50 <i>3 new</i>	2	\$ 189 x
5	Rear tailgate absorber @ \$252.60 <i>2 new</i>	2	\$ 505.2 x
6	Rear tailgate inner board <i>3 new</i>	1	\$ 361 x
7	Rear tailgate weather strip <i>new</i>	1	\$ 332.9 x
8	Rear tailgate centre logo <i>new</i>	1	\$ 72.7 ✓
9	Rear tailgate handle <i>new</i>	1	\$ 191.3 x
10	Rear end panel <i>Dented.</i>	1	\$ 509.5 ✓
11	Rear end panel inner top garnish <i>deformed</i>	1	\$ 269.5 ✓
12	Rear lamp @ \$622.40 <i>cauled</i>	2	\$ 1244.8 816.
13	Rear lamp housing @ \$186.60 <i>new</i>	2	\$ 373.2 x
14	Rear bumper <i>Deformed.</i>	1	\$ 941.5 470.70.
15	Rear bumper reflector @ \$63.20 <i>new</i>	2	\$ 126.4 x
16	Rear bumper bracket @ \$51.00 <i>new</i>	2	\$ 102 x
17	Rear bumper side holder @ \$61.20 <i>new</i>	2	\$ 122.4 ✓
18	Rear bumper clips (1set) <i>new</i>	1	\$ 50.30.
19	Rear exhaust pipe <i>Best.</i>	1	\$ 1085.7 782.50.
20	Rear exhaust pipe chrome <i>Best</i>	1	\$ 95 ✓
21	Rear exhaust pipe mounting <i>new</i>	1	\$ 85 x
22	Rear centre exhaust pipe <i>new</i>	1	\$ 2835.4 x

4841.10

3630.82

Less 25 % Disc

Total

\$ 11332.6

\$ 2833.15

\$ 8499.45

Special Nett Items

1	Rear bumper lip <i>Deformed</i>	1	\$ 900 750
2	Rear bumper reverse sensor <i>and</i>	1	\$ 380 200.
3	Rear camera <i>new</i>	1	\$ 800 x
Total			\$ 2080

950

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN AI CHING SERENE
BLK 273D PUNGGOL PLACE
#03-892
S 824273

Date :30.05.2018
Vehicle no :SFZ 5555 A
Make/Model :TOYOTA WISH
Accident date :11.04.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

1 To supply rear end panel inner sealant		\$	200 ⁶⁰
2 To supply rear widnscreen sealant		\$	50 ✓
3 Remove & reinstall rear widnscreen		\$	200 120
4 Remove & reinstall exhaust pipe	2330	\$	280 80
5 Remove & reinstall reverse sensor		\$	150 50
6 Remove & reinstall boot lid inner garnish		\$	150 80
7 Remove & reinstall camera		\$	100 50
8 Remove, replace & repair consistent to the accident		\$	1800 80
9 Respray painting		\$	1500 100
10 Tuff kote		\$	150 40
Total		\$	4580
Grand Total		\$	15159.45

total: 6910.82

1/8: 5.5K
07 Days

5.5K
07 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: