

4/11/2018

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
CHUA KIAN CHUAN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/04/2018
Vehicle Reg. No.:	SJM3443Z	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Vehicle Reg. Date:	29/12/2008
Vehicle Colour:	WHITE	Chassis No:	JHMRN68809S200709
Engine No:	R18A13800709		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	3,636.60
Miscellaneous Items	10.00
Labour	2,110.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,756.60
+ GST 7.00% (\$\$)	402.96
Nett Amount (\$\$)	6,159.56

This claim is handled by: SAMUEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 97495749
'up'
12/4/18 @ 1700
Lumpsum
Resurvey after repair
Gelaya
Suo @ LKK Auto Consultants
* check Repair Limit

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2018)
 Parts: M1-MPV HONDA STREAM 1.8 L SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJM3443Z)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN MOULDING	20.00	0.00	ne ✓ *250.00 FL
2	1		*TAILGATE	20.00	0.00	bt ✓ *880.00 FL
3	1		*TAILGATE GARNISH	20.00	0.00	x ✓ *280.00 FL
4	1		*TAILGATE LOGO	20.00	0.00	ne ✓ *80.00 FL
5	1		*TAILGATE EMBLEM (STREAM)	20.00	0.00	ne ✓ *80.00 FL
6	1		*TAILGATE EMBLEM (RSZ)	20.00	0.00	ne ✓ *80.00 FL
7	1		*TAILGATE LOCK	20.00	0.00	bt ✓ *180.00 FL
8	1		*TAILGATE WEATHERSTRIP	20.00	0.00	cul? ✓ *150.00 FL
9	1		*TAILGATE TRIM BOARD	20.00	0.00	✓ *388.00 FL
10	1		*REAR BUMPER	20.00	0.00	de ✓ *660.00 FL
11	1		*REAR BUMPER TOW COVER	20.00	0.00	de ✓ *35.00 FL
12	1		*REAR BUMPER RETAINER LH	20.00	0.00	ne ✓ *22.00 FL
13	1		*REAR BUMPER RETAINER RH	20.00	0.00	ne ✓ *22.00 FL
14	10		*REAR BUMPER CLIPS	20.00	0.00	ne ✓ *60.00 FL
15	1		*REAR LAMP LH - CHECK	20.00	0.00	
16	1		*REAR LAMP RH - CHECK	20.00	0.00	
17	1		*REAR END PANEL	20.00	0.00	7 ✓ *630.00 FL plug
18	1		*REAR END PANEL TOP GARNISH	20.00	0.00	de ✓ *290.00 FL
19	1		*TOWING CHARGE	0	0.00	ne ✓ *55.00 FS
20	1		*REAR WINDSCREEN SEALANT	0	0.00	ne ✓ *40.00 FS
21	1		*REAR REVERSE SENSOR	0	0.00	ne ✓ 200 *280.00 FS
Sub Total (\$\$)						4,452.00
- List Item Discount on L Items (\$\$)						815.40
Total Parts (\$\$)						3,636.60

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

4/11/2018

Estimate Report

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CUT/WELD REAR END PANEL. TO KNOCK AND STRAIGHTEN REAR FLOOR PANEL, REAR CHASSIS LH & RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION	New	700 850.00
2	TO SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL	New	600 650.00
3	TO REMOVE AND REPLACE REAR REVERSE SENSOR AND CHECK FUNCTION WELL	New	30 60.00
4	TO REMOVE AND REFIX REAR WINDSCREEN AND CHECK WATER LEAKAGE	New	120.00
5	TO APPLY SEAL ON WELDING JOINT	New	40 80.00
6	TO APPLY RUST PROOF ON AFFECTED AREA	New	40 120.00
7	TO REMOVE AND REFIX TAILGATE LOCK MECHANISM AND CHECK LOCKING SYSTEM	New	60 80.00
8	TO REMOVE AND REFIX LUGGAGE COMPARTMENT TRIM IN ORDER TO STRAIGHTEN REAR FLOOR PANEL AND REAR CHASSIS	New	50 150.00
Gross Labour Cost (S\$)			2,110.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >