

INS. CASE OWNER:

CC 3/CTI1800

6754, F1H63N2

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

ASSIGNMENT


11/4/18

Date / Time:

11/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PC 2124H

Claim No.:

GMM/4001827002

Name of Insured:

FAT TRANSPORTATION &amp; TRAVEL

Policy No.:

OMBISN 1748311700

Insured Tel No.:

HP:

Make / Model:

YATIMU

Excess Sec II :SS

D.O.A.:

9/4/18

Place of Accident:

SINGAPORE EAST BY WONG MELAYU

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

LEONG KEE KIAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHB 4606X



INSRS:

WSP:

Tel:

Liability:

RMKS:

come w.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/Time | STAGE                             | DATE / PIC |
|-----------|-----------------------------------|------------|
| 16/4/18   | Non-Reporting ltr (1st):          |            |
| 16/4/18   | Non-Reporting ltr (2nd):          |            |
| 16/4/18   | Non-Reporting ltr (Final):        |            |
| 16/4/18   | Notification ltr (if non-pickup): |            |
| 16/4/18   | Call OI:                          |            |
| 16/4/18   | After call ltr to OI:             |            |
| 16/4/18   | Documentation Check List:         |            |
| 16/4/18   | Notification ltr (if non-pickup)  |            |
| 16/4/18   | After call ltr to OI:             |            |
| 16/4/18   | Authorisation To Act:             |            |
| 16/4/18   | Release Voucher:                  |            |
| 16/4/18   | Final Repair Bill:                |            |
| 16/4/18   | Car Rental Invoice:               |            |
| 16/4/18   | Towing Invoice:                   |            |
| 16/4/18   | LTA / GIA:                        |            |
| 16/4/18   | Medical Bill:                     |            |
| 16/4/18   | PIR:                              |            |
| 16/4/18   | Mandate/Reject Instruction:       |            |
| 16/4/18   | LOD:                              |            |
| 16/4/18   | Payment Breakdown Form:           |            |
| 16/4/18   | Post-Repair Photos:               |            |
| 16/4/18   | Others:                           |            |

PRELIMINARY ADVICE Date/Time: 17/4/18

| FINALIZATION                                                        | Date/Time:                                                                       | Confirm with:         | Confirm by:                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------|
| Repair Cost: P/P                                                    | SS 6,580.22 ( 4 days) Reduction: 48 %                                            |                       | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| FINAL SETTLEMENT                                                    | Date/Time: 07/09/18                                                              | Confirm with: WILLIAM | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Final Liability:                                                    | % 100 (Agreed / Assessed) B.O. No.:                                              | 27                    | If NO or B 28, Ass. Lia:                                     |
| Repair Cost: (w/gst)                                                | SS 7,040.84                                                                      |                       | (OLD ROAD - BUNDLED TP)                                      |
| Loss of Rental (LOR):                                               | SS 596.40 ( 5 days) X \$ 119.28                                                  |                       |                                                              |
| Loss of Use (LOU):                                                  | SS 280.00 50 x 5 days                                                            |                       |                                                              |
| Loss of Income (LOI):                                               | SS - (\$ x days)                                                                 |                       |                                                              |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/> | [Tick only one]       |                                                              |
| GIA/LTA Search                                                      | SS 7.49                                                                          |                       |                                                              |
| Medical:                                                            | SS -                                                                             |                       |                                                              |
| Disbursement:                                                       | SS -                                                                             | (if not independent)  |                                                              |
| Legal Cost                                                          | SS -                                                                             |                       |                                                              |
| Total:                                                              | SS 7,890.73                                                                      | Global Sum: 7,890.00  |                                                              |
| FINAL PAYMENT                                                       | Date/Time:                                                                       | Confirm with:         | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Payee 1:                                                            | SS 7,890.00                                                                      | Name 1:               | COMPTON ENGINEERING PTE LTD                                  |
| Payee 2: (Strike if N.A.)                                           | SS -                                                                             | Name 2:               |                                                              |
| Payee 3: (Strike if N.A.)                                           | SS -                                                                             | Name 3:               |                                                              |

(06/11/23)

Surname: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: \_\_\_\_\_

at Work stop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 4606X Yr Regn: 26 Nov, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ix0 c.c. 1685Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 747263 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCB414464080687Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WeldFront 7 mmR/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/4/18 D.O.I. 11/4/18Survey held at CD4E (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction    |
|-------------|-------------------------|
|             | PIP #6,580.22           |
|             | (1200: #6,014.04 / 48%) |
|             |                         |
|             |                         |
|             |                         |
|             |                         |
|             |                         |
|             |                         |
|             |                         |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                          |                 |                             |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                          |                 | Ref : CC3/CTI18006754/K1hb3 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                          |                 | Date : 12-04-2018           |  |
|                                                                                                                                           |                                                                          |                 | Code : CTI                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                          |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                              | PC 2124H                                                                 | Veh. Inspected  | SHB 4606X                   |                                                                                     |
| Policy No.                                                                                                                                |                                                                          | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                 |                                                                          | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                               |                                                                          | Assign Date     | 12/04/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                          |                 |                             |                                                                                     |
| Make & Model                                                                                                                              |                                                                          | c.c             | 0                           |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                   | Year of Reg.    |                             |                                                                                     |
| Chassis No.                                                                                                                               |                                                                          | Colour          |                             |                                                                                     |
| Odometer                                                                                                                                  | -                                                                        | Steering        |                             |                                                                                     |
| Brakes                                                                                                                                    |                                                                          | Modification    |                             |                                                                                     |
| General                                                                                                                                   |                                                                          |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                          |                 |                             |                                                                                     |
|                                                                                                                                           | Size                                                                     | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                          |                 | mm                          |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                          |                 | mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                          |                 | mm                          |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                          |                 | mm                          |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                          |                 |                             |                                                                                     |
|                                                                                                                                           |                                                                          |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                          |                 |                             |                                                                                     |
| Accident Date                                                                                                                             | 09/04/2018                                                               | Inspection Date | 11/04/2018                  |                                                                                     |
| Survey held at                                                                                                                            | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                          |                 |                             |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                             |                                                                                     |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/CT118006754/K1hb3

Date: 12.04.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHB4606X**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.04.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 12,594.26 |
| Revised Estimate Amount  | : S\$ | 6,580.22  |
| "Check" Items Amount     | : S\$ | 3,204.00  |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## Shu Pei (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Friday, 13 April 2018 3:16 PM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Chong Boon Sen  
**Subject:** RE: Direct Settlement - Accident Involving PC2124H (OI : CTI - SNM18D01867C02) and SHB4606X (TP : LKK REF - CC3/CTI18006754/K1hb3 )on 09.04.2018  
**Attachments:** leeSZ\_SNM18D01867C02-PC2124H-LKKDirectSettlementAccidentLtr\_CLCR95.399.pdf; MCCA18047666-PC2124H.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Regards,

**Lucas Lee**  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Thursday, 12 April, 2018 5:26 PM  
**To:** Claims Dept of CTI  
**Cc:** Lucas Lee; Chong Boon Sen; Admin A; Vic (LKKAUTO)  
**Subject:** Direct Settlement - Accident Involving PC2124H (OI : CTI - TBA) and SHB4606X (TP : LKK REF - CC3/CTI18006754/K1hb3 )on 09.04.2018

### WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 4606X at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:  
- TP's GIA report

- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.

Thank you

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079908

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D01867/C02/6**

Date : **13 APRIL 2018**

via Ordinary & Registered Mail

**KAT TRANSPORTATION & TRADING  
BLK 9006 TAMPINES STREET 93  
#04-202  
SINGAPORE 528840**

Dear Sir / Madam

**ACCIDENT INVOLVING PC2124H AND SHB4606X ON 09 APRIL 2018  
ALONG SIMS AVE EAST BEFORE LOR MELAYU**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB4606X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : VIC

Ref : CC3/CTI18006754/K1HB3

Contact No : 68412360

via Email : VIC@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

Team: ARC Repair TP(CFSO)1 **JOB CARD** Sales Order: JC NO305140506

|                                                                                                                                                |                                   |                                  |
|------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|----------------------------------|
| CUSTOMER<br>CITYCAB PTE LTD<br>7010070<br>CUSTOMER NO<br>383 SIN MING DRIVE<br>ADDRESS Singapore SINGAPORE 575717<br>65551188<br>L (R) (P) (O) | REGN NO:<br>SHB4606X              | MILEAGE                          |
|                                                                                                                                                | MAKE:<br>HYUNDAI                  | FUEL<br>E.....1/2.....F          |
|                                                                                                                                                | MODEL<br>I-40                     | DATE/TIME IN<br>09.04.2018 17:20 |
|                                                                                                                                                | YR OF MANU.<br>26.11.2015         | TARGET DATE                      |
|                                                                                                                                                | CHASSIS CODE<br>KMHLB41UMGU080687 | COMPLETION DATE/TIME:            |

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 09.04.2018  
NATURE: 3P 09.04.2018

| C / NO | LABOR CODE   | DESCRIPTION |
|--------|--------------|-------------|
|        | CHINA - taxi | Rear damage |
|        | LKK /        |             |

CHECKED & PASSED OUT BY: \_\_\_\_\_

|                 |                      |
|-----------------|----------------------|
| SERVICE ADVISOR | CUSTOMER'S SIGNATURE |
|-----------------|----------------------|

Acknowledgement Slip

Exit Pass

ie:  
Job No.: SHB4606X LARRY

Vehicle No.: SHB4606X

Larry Ng

ie of Service Advisor Signature/Date

Name of Service Advisor Date

ie returned to Service Reception upon collection

To be kept by Security Guard

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 4606X

CHINA

DATE 10/4/2018 16:01

MAKE :

DOA: 09.04.18

MODEL : HYUNDAI i40

| Qty | Parts Description/ Labour                   | Type | Unit Price | Amount              |      |
|-----|---------------------------------------------|------|------------|---------------------|------|
|     | Boot Lid ✓                                  |      |            | \$ 1,681.40         |      |
|     | Boot Lid Rubber ✕                           |      |            | \$ 115.80           |      |
|     | Boot Lid Hinge (LH/RH) ✓                    |      | \$ 178.10  | \$ 356.20           |      |
|     | Boot Lid Lock Upper ✕                       |      |            | \$ 137.90           |      |
|     | Boot Lid Lock Lower ✕                       |      |            | \$ 31.70            |      |
|     | Boot Lid 'H' Emblem ✓                       |      |            | \$ 27.20            |      |
|     | Boot Lid CRDI Plate ✓                       |      |            | \$ 41.00            |      |
|     | Boot Lid Lamp (LH/RH) LH? RH- ✓             |      | \$ 556.80  | \$ 1,113.60         |      |
|     | Licence Lamp (LH/RH) ✕                      |      | \$ 33.95   | \$ 67.90            |      |
|     | Boot Lid Trimboard ✕                        |      |            | \$ 172.70           |      |
|     | Boot Lid Trimboard Clips (11pcs) ✕          |      |            | \$ 11.00            |      |
|     | Bootlid Moulding ✕                          |      |            | \$ 85.00            |      |
|     | Bootlid i40 Emblem ✕ ✓                      |      |            | \$ 41.00            |      |
|     | Bootlid Lower Garnish ✕ ✓                   |      |            | \$ 398.00           |      |
|     | Rear Bumper ✓                               |      |            | \$ 603.60           |      |
|     | Rear Bumper Reinforcement ✓                 |      |            | \$ 504.35           |      |
|     | Rear Bumper Reinforcement Bracket (LH/RH) ✓ |      | \$ 180.00  | \$ 360.00           |      |
|     | Rear Bumper Side Bracket ?                  |      | \$ 49.00   | \$ 98.00            |      |
|     | Rear Bumper Clips ✓                         |      |            | \$ 22.00            |      |
|     | Rear Bumper Sponge ✓                        |      |            | \$ 143.40           |      |
|     | Rear Bumper Under Cover ✓                   |      |            | \$ 225.00           |      |
|     | Tail Lamp (LH/RH) ✓                         |      | \$ 565.60  | \$ 1,131.20         |      |
|     | Rear Panel ✕ ✓                              |      |            | \$ 592.30           |      |
|     | Rear Panel Garnish ?                        |      |            | \$ 57.70            |      |
|     | Rear Panel Lower Panel ✕ ✓                  |      |            | \$ 495.50           |      |
|     | Exhaust Pipe Insulator ?                    |      | \$ 58.55   | \$ 117.10           |      |
|     | Exhaust Silencer ?                          |      | \$ 954.00  | \$ 1,908.00         |      |
|     | Exhaust Pipe Hanger ?                       |      | \$ 58.55   | \$ 117.10           |      |
|     | Exhaust Pipe Centre ?                       |      |            | \$ 1,150.30         |      |
|     | Fuel Lid Cover ✕ ✓                          |      |            | \$ 98.50            |      |
|     | <b>SUB TOTAL</b>                            |      |            | <b>\$ 11,904.45</b> |      |
|     | <b>LESS 20%</b>                             |      |            | <b>\$ 2,380.89</b>  |      |
|     | <b>DISCOUNTED TOTAL</b>                     |      |            | <b>\$ 9,523.56</b>  |      |
|     | Boot Lid Comfort Logo & Tel No. Sticker ✓   |      |            | \$ 30.00            | Nett |
|     | Rear No. Plate ✕                            |      |            | \$ 25.00            | Nett |
|     | Rear Bumper Reverse Sensor ✓                |      |            | \$ 135.70           | Nett |
|     | Rear Bumper Rubber Mat ✓                    |      |            | \$ 50.00            | Nett |
|     |                                             |      |            | <b>\$ 240.70</b>    |      |

Lain Ng

| Qty                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Parts Description/ Labour            | Type | Unit Price | Amount              |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------|------------|---------------------|
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>Labour Charge</b>                 |      |            | <b>700</b>          |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Panel Beating- Repair Rear LH Fender |      |            | \$ 1,000.00         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Spray Painting Charge                |      |            | \$ 1,250.00 1000    |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Wiring Charge                        |      |            | \$ 50.00 20         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Tuff Kote                            |      |            | \$ 50.00 20         |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Remove/Refix Reverse Sensor          |      |            | \$ 120.00 20        |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Remove/Refix Exhaust Pipe            |      |            | \$ 360.00           |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | TOWING FEE                           |      |            | \$ 50.00            |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>TOTAL LABOUR</b>                  |      |            | <b>\$ 2,830.00</b>  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | <b>ESTIMATE TOTAL</b>                |      |            | <b>\$ 12,594.26</b> |
| <p>Kahiri (LKK)</p> <p>11/4/18 1045hrs</p> <p>4 Days</p> <p>P/P</p> <p>Before Part photo</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                      |      |            |                     |
| <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> |                                      |      |            |                     |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>                                                                                                                                                                                                                                                                                                                                                     |                                      |      |            |                     |

### REPAIR ESTIMATE\*

MAKE :

**MODEL : HYUNDAI i40**

DATE 10/4/2018 16:01

DOA: 09.04.18

| MODEL | : HYUNDAI i40                                    |      |            |               |
|-------|--------------------------------------------------|------|------------|---------------|
| Qty   | Parts Description/ Labour                        | Type | Unit Price | Amount        |
|       | Boot Lid — Bent                                  |      |            | \$ 1,681.40 ✓ |
|       | Boot Lid Rubber X see                            |      |            | \$ 115.80     |
|       | Boot Lid Hinge (LH/RH) — Bent                    |      | \$ 178.10  | \$ 356.20 ✓   |
|       | Boot Lid Lock Upper X see                        |      |            | \$ 137.90     |
|       | Boot Lid Lock Lower X see                        |      |            | \$ 31.70      |
|       | Boot Lid 'H' Emblem — see                        |      |            | \$ 27.20 ✓    |
|       | Boot Lid CRDI Plate — see                        |      |            | \$ 41.00 ✓    |
|       | Boot Lid Lamp (LH/RH) LH X RH — cm               | \$   | 556.80     | \$ 1,113.60   |
|       | Licence Lamp (LH/RH) X see                       | \$   | 33.95      | \$ 67.90      |
|       | Boot Lid Trimboard X see                         |      |            | \$ 172.70     |
|       | Boot Lid Trimboard Clips (11pcs) X in            |      |            | \$ 11.00      |
|       | Bootlid Moulding X see                           |      |            | \$ 85.00      |
|       | Bootlid i40 Emblem X — see                       |      |            | \$ 41.00 ✓    |
|       | Bootlid Lower Garnish X see                      |      |            | \$ 398.00     |
|       | Rear Bumper — Reformal                           |      |            | \$ 603.60 ✓   |
|       | Rear Bumper Reinforcement — cm                   |      |            | \$ 504.35 ✓   |
|       | Rear Bumper Reinforcement Bracket (LH/RH) — Bent | \$   | 180.00     | \$ 360.00 ✓   |
|       | Rear Bumper Side Bracket X see                   | \$   | 49.00      | \$ 98.00      |
|       | Rear Bumper Clips — see                          |      |            | \$ 22.00 ✓    |
|       | Rear Bumper Sponge — tan                         |      |            | \$ 143.40 ✓   |
|       | Rear Bumper Under Cover — cm                     |      |            | \$ 225.00 ✓   |
|       | Tail Lamp (LH/RH) — cm                           | \$   | 565.60     | \$ 1,131.20 ✓ |
|       | Rear Panel X see                                 |      |            | \$ 592.30     |
|       | Rear Panel Garnish X see                         |      |            | \$ 57.70      |
|       | Rear Panel Lower Panel X see                     |      |            | \$ 495.50     |
|       | Exhaust Pipe Insulator X see                     | \$   | 58.55      | \$ 117.10     |
|       | Exhaust Silencer X see                           | \$   | 954.00     | \$ 1,908.00   |
|       | Exhaust Pipe Hanger X see                        | \$   | 58.55      | \$ 117.10     |
|       | Exhaust Pipe Centre X see                        |      |            | \$ 1,150.30   |
|       | Fuel Lid Cover X see                             |      |            | \$ 98.50      |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       |                                                  |      |            |               |
|       | </                                               |      |            |               |

| Qty | Parts Description/ Labour            | Type | Unit Price | Amount                      |
|-----|--------------------------------------|------|------------|-----------------------------|
|     | <b>Labour Charge</b>                 |      |            |                             |
|     | Panel Beating- Repair Rear LH Fender |      |            | \$ 1,000.00 <sup>700</sup>  |
|     | Spray Painting Charge                |      |            | \$ 1,250.00 <sup>1000</sup> |
|     | Wiring Charge                        |      |            | \$ 50.00 <sup>20</sup>      |
|     | Tuff Kote                            |      |            | \$ 50.00 <sup>20</sup>      |
|     | Remove/Refix Reverse Sensor          |      |            | \$ 120.00 <sup>20</sup>     |
|     | Remove/Refix Exhaust Pipe            |      |            | \$ 360.00                   |
|     | TOWING FEE                           |      |            | \$ 50.00                    |
|     | <b>TOTAL LABOUR</b>                  |      |            | <b>\$ 2,830.00</b>          |
|     | <b>ESTIMATE TOTAL</b>                |      |            | <b>\$ 12,594.26</b>         |

Larry Ng

Kahri (LKK)

11/4/18 10 45hrs

4 Days

P/P

Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 19.04.2018  
Time: 16:45:54  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305140506  
REGN NO : SHB4606X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 26.11.2015  
DATE/TIME IN : 09.04.2018 17:20  
ACCIDENT DATE : 09.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|      |                   |                           |    |          |       |          |
|------|-------------------|---------------------------|----|----------|-------|----------|
| 0001 | 04-01-0103-0577-G | I40VC PANEL ASSY-TRUNK LI | 1  | 1,681.40 | 20.00 | 1,345.12 |
| 0002 | 04-01-0103-0712-G | I40VC HINGE ASSY-TRUNK LI | 1  | 178.10   | 20.00 | 142.48   |
| 0003 | 04-01-0103-0713-G | I40VC HINGE ASSY-TRUNK LI | 1  | 178.10   | 20.00 | 142.48   |
| 0004 | 04-01-0103-0800-G | I40VC SYMBOL MARK-TRUNK L | 1  | 27.20    | 20.00 | 21.76    |
| 0005 | 04-01-0103-0786-G | I40VC EMBLEM-CRDI         | 1  | 41.00    | 20.00 | 32.80    |
| 0006 | 04-01-0103-0583-G | I40V2 LAMP ASSY-RR COMB I | 1  | 556.80   | 20.00 | 445.44   |
| 0007 | 04-01-0103-0787-G | I40VC EMBLEM-I40          | 1  | 41.00    | 20.00 | 32.80    |
| 0008 | 04-01-0103-0579-G | I40VC COVER ASSY-RR BUMPE | 1  | 603.60   | 20.00 | 482.88   |
| 0009 | 04-01-0103-0740-G | I40VC BEAM-RR BUMPER#     | 1  | 504.35   | 20.00 | 403.48   |
| 0010 | 04-01-0103-0742-G | I40VC STAY-RR BUMPER LH   | 1  | 180.00   | 20.00 | 144.00   |
| 0011 | 04-01-0103-0743-G | I40VC STAY-RR BUMPER RH   | 1  | 180.00   | 20.00 | 144.00   |
| 0012 | 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 | 22.00    | 20.00 | 17.60    |
| 0013 | 04-01-0103-0739-G | I40VC ABSORBER-RR BUMPER  | 1  | 143.40   | 20.00 | 114.72   |

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 19.04.2018  
Time: 16:45:54  
Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS: CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305140506  
REGN NO : SHB4606X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 26.11.2015  
DATE/TIME IN : 09.04.2018 17:20  
ACCIDENT DATE : 09.04.2018

| JOB / PARTS DESCRIPTION                          | QTY | IND | UNIT-PRICE | DISC% | AMOUNT   |
|--------------------------------------------------|-----|-----|------------|-------|----------|
| 0014 04-01-0103-0738-G I40VC COVER-RR BUMPER LWR | 1   |     | 225.00     | 20.00 | 180.00   |
| 0015 04-01-0103-0581-A I40VC LAMP ASSY-RR COMB O | 1   |     | 565.60     | 20.00 | 452.48   |
| 0016 04-01-0103-0585-A I40VC LAMP ASSY-RR COMB O | 1   |     | 565.60     | 20.00 | 452.48   |
| 0017 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS | 1   |     | 135.70     | 2.00- | 135.70   |
| 0018 04-01-0103-1150-A I40VC PROTECTOR MAT       | 1   |     | 50.00      | 0.20  | 50.00    |
| 0019 28-01-0103-0009-A (I40)REAR BOOT LOGO CCTPL | 1   |     | 20.00      | 0.02- | 20.00    |
| 0020 28-01-0103-0010-A (I40)REAR BOOT TEL NUMBER | 1   |     | 10.00      | 0.00  | 10.00    |
| SUB-TOTAL :                                      |     |     |            |       | 4,770.22 |

JOB NATURE

|             |                             |         |
|-------------|-----------------------------|---------|
| 0000 L      | PANEL BEATING               | 700.00  |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA | 1000.00 |

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 19.04.2018

Time: 16:45:54

Page: 3

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS: CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305140506  
REGN NO : SHB4606X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 26.11.2015  
DATE/TIME IN : 09.04.2018 17:20  
ACCIDENT DATE : 09.04.2018

| JOB / PARTS DESCRIPTION |                              | QTY | IND | UNIT-PRICE | DISC% | AMOUNT   |
|-------------------------|------------------------------|-----|-----|------------|-------|----------|
| 0002 17-01              | WIRING CHARGE                |     |     | 20.00      |       |          |
| 0003 20-00              | TUFF COAT ON AFFECTED PARTS. |     |     | 20.00      |       |          |
| 0004 L                  | REMOVE/REFIX REVERSE SENSOR  |     |     | 20.00      |       |          |
| 0005 23-01              | TOWING FEE                   |     |     | 50.00      |       |          |
| SUB-TOTAL :             |                              |     |     |            |       | 1,810.00 |
| TOTAL :                 |                              |     |     |            |       | 6,580.22 |

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305140506  
Date : 19. Apr. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHB4606X

Date of Accident: 09/04/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: CHINA PC2124H
- The finalized amount shall be:
  - Spare Parts after List discount \$4,770.22
  - Labour Charges \$1,810.00
  - Total for Part-By-Part Repair Cost** \$6,580.22
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
Final Lumpsum Repair cost \_\_\_\_\_
- Estimated normal period for repairs: 4 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : Larry Ng  
Name : Larry Ng  
Tel : 6214 8316  
Fax : 6546 8156

Signature : Kalvin  
Name : Kalvin  
Date : 19/4/18

### For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        |                             |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    |        |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |


Remarks:

## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

### Job Requisition

|                                                                                                                                                                                                                                             |  |                                                                                                                                                                                           |                                                                                                                                                                                       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. Date: <u>9/04/18</u> Time Received: <u>1720</u>                                                                                                                                                                                          |  | 3. Vehicle Type:<br><input type="checkbox"/> Private<br><input checked="" type="checkbox"/> Taxi (CTPL/CCPL)<br><input type="checkbox"/> Fleet<br><input type="checkbox"/> STK (Boon Lay) | 4. Type of Towing:<br><input checked="" type="checkbox"/> Normal Tow<br><input type="checkbox"/> King Dolly<br><input type="checkbox"/> Flat Bed<br><input type="checkbox"/> Crane-up |
| 2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis<br>Name of Customer : <u>OW Stanley</u><br>Contact No. : <u>96862213</u><br>Vehicle No. : <u>S1104606X</u><br>Make / Model / Colour : <u>140/CITY/BLACK</u><br>Email : |  |                                                                                                                                                                                           |                                                                                                                                                                                       |
| 7. Location:                                                                                                                                                                                                                                |  | 5. Nature of Service:<br><input type="checkbox"/> Jumpstart<br><input type="checkbox"/> Recovery<br><input type="checkbox"/> Change Tyre / Battery                                        | 6. Parts Replaced/Remarks:                                                                                                                                                            |

|                                                                                                                                                                                                                                                                                                                                                                                                                       |  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| 9. Preferred Workshop:<br><input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan<br><input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi<br><input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD)<br><input type="checkbox"/> Others: |  | 8. Vehicle Tow - In Workshop:<br><input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed<br><input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty<br><input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty<br><input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power<br><input type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled<br><input type="checkbox"/> Return Taxi |  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|

|                                                                                                                                                                                                     |  |                                                                                                                                |                                                                                       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 10. Odometer Reading : <u>347263km</u><br>Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E |  | 11. Radio / CD Player<br><input type="checkbox"/> OK<br><input type="checkbox"/> Faulty<br><input type="checkbox"/> Not tested |  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|

|                                                                                                                                                                                                                                                                                                                                                                                            |  |                                                                              |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------|
| 12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input checked="" type="checkbox"/> YISHUN TOWING <input type="checkbox"/> OTHERS<br>Name of Driver : <u>Gao X J</u><br>Vehicle No. : <u>Y128480P</u><br>Time Dispatch : <u>1726</u><br>Time of Arrival : <u>1820</u><br>Time Completed : |  | # : Cracked X : Dented<br>/ : Scratched O : Missing<br>Signature of Customer |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------|

|                                                                |  |
|----------------------------------------------------------------|--|
| Cash Invoice Details (if applicable)<br>13. Cash Invoice No. : |  |
|----------------------------------------------------------------|--|

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                   |                                           |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------------------------|
| Customer Acknowledgement<br>a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.<br>b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.<br>c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™. |                   |                                           |
| Date: <u>09/04/2018</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Time: <u>1820</u> | Signature of Customer: <u>[Signature]</u> |

|                                                                                                                              |  |  |
|------------------------------------------------------------------------------------------------------------------------------|--|--|
| 14. WORKSHOP<br>Name of Attending Staff/Guard: _____ Date & Time of Arrival: _____ Signature of Attending Staff/Guard: _____ |  |  |
|------------------------------------------------------------------------------------------------------------------------------|--|--|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18006754/K1hb3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 14-09-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | PC 2124H         | Veh. Inspected | SHB 4606X  |
| Policy No.   | DMB1SN1748311700 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D01867C02/4 | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 11/04/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI I40       | c.c          | 1685               |
| Engine No.   | HIDDEN            | Year of Reg. | 2015               |
| Chassis No.  | KMHLB41UMGU080687 | Colour       | YELLOW             |
| Odometer     | 347263            | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | GOOD              |              |                    |

## 3. Conditions of Tyres

|                | Size       | Make      | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 205/60 R16 | WEST LAKE | 7 mm    |
| L/H Front Tyre | 205/60 R16 | WEST LAKE | 7 mm    |
| R/H Rear Tyre  | 205/60 R16 | WEST LAKE | 7 mm    |
| L/H Rear Tyre  | 205/60 R16 | WEST LAKE | 7 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 09/04/2018                                                               | Inspection Date | 11/04/2018 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4606X

| Qty                         | Description of Parts                                | Condition                     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------------------------|-------------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                     |                               |                           |                   |
| 1                           | BOOT LID                                            | DENTED                        | 1,681.40                  | 1,681.40          |
| 1                           | BOOT LID RUBBER                                     | SERVICEABLE                   | 115.80                    | -                 |
| 2                           | BOOT LID HINGE (LH/RH) @\$178.10                    | BENT                          | 356.20                    | 356.20            |
| 1                           | BOOT LID LOCK UPPER                                 | SERVICEABLE                   | 137.90                    | -                 |
| 1                           | BOOT LID LOCK LOWER                                 | SERVICEABLE                   | 31.70                     | -                 |
| 1                           | BOOT LID 'H' EMBLEM                                 | NECESSARY                     | 27.20                     | 27.20             |
| 1                           | BOOT LID CRDI PLATE                                 | NECESSARY                     | 41.00                     | 41.00             |
| 2                           | BOOT LID LAMP (LH/RH) @\$556.80                     | N/S SERVICEABLE / O/S CRACKED | 1,113.60                  | 556.80            |
| 2                           | LICENCE LAMP (LH/RH) @\$33.95                       | SERVICEABLE                   | 67.90                     | -                 |
| 1                           | BOOT LID TRIMBOARD                                  | SERVICEABLE                   | 172.70                    | -                 |
| 11                          | BOOT LID TRIMBOARD CLIPS                            | NOT NECESSARY                 | 11.00                     | -                 |
| 1                           | BOOTLID MOULDING                                    | SERVICEABLE                   | 85.00                     | -                 |
| 1                           | BOOTLID I40 EMBLEM                                  | NECESSARY                     | 41.00                     | 41.00             |
| 1                           | BOOTLID LOWER GARNISH                               | TO REPAIR SEE LABOUR          | 398.00                    | -                 |
| 1                           | REAR BUMPER                                         | DEFORMED                      | 603.60                    | 603.60            |
| 1                           | REAR BUMPER REINFORCEMENT                           | CRACKED                       | 504.35                    | 504.35            |
| 2                           | REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00 | BENT                          | 360.00                    | 360.00            |
| 2                           | REAR BUMPER SIDE BRACKET @\$49.00                   | SERVICEABLE                   | 98.00                     | -                 |
| 10                          | REAR BUMPER CLIPS                                   | NECESSARY                     | 22.00                     | 22.00             |
| 1                           | REAR BUMPER SPONGE                                  | TORN                          | 143.40                    | 143.40            |
| 1                           | REAR BUMPER UNDER COVER                             | CRACKED                       | 225.00                    | 225.00            |
| 2                           | TAIL LAMP (LH/RH) @\$565.60                         | CRACKED                       | 1,131.20                  | 1,131.20          |
| 1                           | REAR PANEL                                          | TO REPAIR SEE LABOUR          | 592.30                    | -                 |
| 1                           | REAR PANEL GARNISH                                  | SERVICEABLE                   | 57.70                     | -                 |
| 1                           | REAR PANEL LOWER PANEL                              | TO REPAIR SEE LABOUR          | 495.50                    | -                 |
| 2                           | EXHAUST PIPE INSULATOR @\$58.55                     | SERVICEABLE                   | 117.10                    | -                 |
| 2                           | EXHAUST SILENCER @\$954.00                          | SERVICEABLE                   | 1,908.00                  | -                 |

Report Ref No. CC3/CT118006754/K1hb3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                                                                                          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 2   | EXHAUST PIPE HANGER @\$58.55                                                                                                                  | SERVICEABLE          | 117.10                    | -                 |
| 1   | EXHAUST PIPE CENTRE                                                                                                                           | SERVICEABLE          | 1,150.30                  | -                 |
| 1   | FUEL LID COVER                                                                                                                                | TO REPAIR SEE LABOUR | 98.50                     | -                 |
|     | LESS 20% DISCOUNT                                                                                                                             |                      | -2,380.89                 | -1,138.63         |
|     |                                                                                                                                               |                      | 9,523.56                  | 4,554.52          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                                                                     |                      |                           |                   |
| 1   | BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)                                                                                                   | NECESSARY            | 30.00                     | 30.00             |
| 1   | REAR NO.PLATE (SN)                                                                                                                            | SERVICEABLE          | 25.00                     | -                 |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                                                                                                               | SHORTED              | 135.70                    | 135.70            |
| 1   | REAR BUMPER RUBBER MAT (SN)                                                                                                                   | NECESSARY            | 50.00                     | 50.00             |
|     |                                                                                                                                               |                      | 240.70                    | 215.70            |
|     | <b>LABOUR</b>                                                                                                                                 |                      |                           |                   |
|     | PANEL BEATING -REPAIR REAR LH FENDER .INCLUSIVE OF THE REPAIR OF BOOTLID LOWER GARNISH,REAR PANEL,REAR PANEL LOWER PANEL AND FUEL LID COVER . |                      | 1,000.00                  | 700.00            |
|     | SPRAY PAINTING CHARGE.                                                                                                                        |                      | 1,250.00                  | 1,000.00          |
|     | WIRING CHARGE.                                                                                                                                |                      | 50.00                     | 20.00             |
|     | TUFF KOTE.                                                                                                                                    |                      | 50.00                     | 20.00             |
|     | REMOVE/REFIX REVERSE SENSOR .                                                                                                                 |                      | 120.00                    | 20.00             |
|     | REMOVE/REFIX EXHAUST PIPE.                                                                                                                    | NOT NECESSARY        | 360.00                    | -                 |
|     | TOWING FEE.                                                                                                                                   |                      | 50.00                     | 50.00             |
|     |                                                                                                                                               |                      | 2,880.00                  | 1,810.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                            |                      | <b>12,644.26</b>          | <b>6,580.22</b>   |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                                                                            |                      |                           | <b>6,580.22</b>   |

Report Ref No. CC3/CT18006754/K1hb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.