



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATECompany Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
LEOW HONG YEW (LIAO FENGYOU)		Cust No/Name	/MR LEOW HONG YEW (LIAO FENGYOU)
BLK 303A PUNGGOL CTRL		Reg No/Reg Date	SGV618U / 25/11/2015
#09-780 Coralinus		Date In/Mileage	/ 0
Singapore 821303		Chassis No	VF73DBHZTFJ771672
Contact No Mobile: 84557888		Engine No	10JBHD3014836
		Make/Model	CIT/C4P 1.6 BLUEHDI EAT6 SEDUCTION
		Colour/Trim	WPP / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	09/04/2018/ 19:44		465 / Tay Jian Ye	13399

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				1200.00
TO RENEW REAR BUMPER				
E PNT98000				840.00
PAINT WORK SPRAY REAR BUMPER				
A 54900099				50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				
A 10028901				200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				
M SUNDRY				50.00
SUNDRIES				
M REAR BUMPER	1.00	898.00	0.00	898.00
M BUMPER BRACKET	1.00	258.00	0.00	258.00
M BUMPER SKIRT	1.00	313.00	0.00	313.00
M BRACKET SET	1.00	101.00	0.00	101.00
M BRACKET	1.00	143.00	0.00	143.00
M LOW RR PAN FIX	1.00	167.00	0.00	167.00
M SENSOR	2.00	131.00	0.00	262.00

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Confirm & accepted by

Authorized signatory and company stamp

Parts	2,142.00
Labour	2,290.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	50.00
Total (w/o GST)	4,482.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.