

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SJR6978B
Chassis No : MRHGM26509P020189
Model : CITY 1.5V AUTO
Owner's Name : CHAN NAI TIONG
Ins Policy No. :
Date of Accident : 7/4/2018

Document No. : SQT18001471
Date : 10. Apr 2018
Customer No. : WE011
Svc Advisor :
Engine No : L15A71800652
Date | Time : 10. Apr 2018 8:39:31 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CHAN NAI TIONG OWNER INSURER:AVIVA ACC DATE:047/04/2018 SURVEYED BY: DATE: REF NO: TP INSURER:EQ INSURANCE TP VEH:SKH6702X						
68500-TM0-T20ZZ	LID COMP TRUNK / BNC	1	408.70	25	306.52	21.46	327.98
74865-TM0-T00	WEATHERSTRIP TRUNK LID ?	1	74.40	25	55.80	3.91	59.71
68660-TM0-T00ZZ	HINGE COMPL TRUNK X NNN	1	52.10	25	39.07	2.73	41.80
68610-TM0-T00ZZ	HINGE COMPR TRUNK X	1	52.10	25	39.07	2.73	41.80
75725-TM0-T00	EMBLEM RR I-VTEC	1	22.20	25	16.65	1.17	17.82
75701-TM0-000	EMBLEM H	1	17.80	25	13.35	0.93	14.28
75722-TM0-T00	EMBLEM RR CITY	1	16.20	25	12.15	0.85	13.00
04715-TM0-T00ZZ	FACEREAR BUMPER / ee	1	9999.99	25	7499.99	525.00	8024.99
71593-TM0-T00	SPACERR.RR.BUMPER SIDE	1	14.80	25	11.10	0.78	11.88
71598-TM0-T00	SPACER L RR BUMPER SIDE / mc.	1	14.80	25	11.10	0.78	11.88
91503-SZ3-003	CLIP ABUMPER	2	3.90	25	5.85	0.41	6.26
71594-TM0-T00	SPACER R RR BUMPER UPPER / mc.	1	10.20	25	7.65	0.54	8.19
71599-TM0-T00	SPACER L RR BUMPER UPPER	1	10.20	25	7.65	0.54	8.19
33550-TM0-T01	TAILLIGHT ASSYL / CRA	1	205.70	25	154.27	10.80	165.07
33500-TM0-T01	TAILLIGHT ASSYR ?	1	205.70	25	154.27	10.80	165.07
74890-TM0-T01	GARNISHRR LICENCE X NN	1	60.40	25	45.30	3.17	48.47
66100-TM0-T00ZZ	PANEL COMP RR / BNC.	1	323.90	25	242.92	17.00	259.92
	Front No. plate / BT.						
BOSUN	SUNDRIES	1	80.00		80.00	5.60	85.60
				Sum Item	8622.71	603.60	9,226.31

789.21

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18001471	Page	2
	5 MAXWELL ROAD	Date	: 10. Apr 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WE011		
	SINGAPORE 069110	Svc Advisor	:		
Registration No	: SJR6978B	Engine No	: L15A71800652		
Chassis No	: MRHGM26509P020189	Date Time	: 10. Apr 2018 8:39:31 AM		
Model	: CITY 1.5V AUTO	Surveyor Name	:		
Owner's Name	: CHAN NAI TIONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 7/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	60.00	/	60.00	4.20	64.20
BOJSE	BODY JOINT SEALANT.	1	100.00	/	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	380.00	360	380.00	26.60	406.60
AA13R	INSTALL REVERSE SENSOR - 2 PCS	1	120.00	/	120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	560 1	4000.00	2800	4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	450 1	3000.00	2250	3000.00	210.00	3210.00
Sum Labor					7740.00	541.80	8,281.80

Survey By	<u>Guo Qiang - 8288 0282</u>	5690		
Date & Time	<u>13/4/18</u>	Total Amount	16,362.71	1,145.40
Excess		Total (Inclusive of GST)		17,508.11
Status				
Signature				

before paint photos.
7 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 11/4/2018 9:25:19 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)