

SE98S , Lamborghini LP550-2 SLE

S/NO.	Parts Description	QTY	SGD \$
1	FRONT BUMPERS <i>distorted.</i>	1	\$ 4,550.00 ✓
2	LEFT FRONT GRID <i>Not there</i>	1	\$ 580.00 X
3	RIGHT FRONT GRID <i>Rehnd</i>	1	\$ 580.00 ✓
4	GRID <i>Not there</i>	1	\$ 350.00 X
5	BUMPER STRUCTURE ?	1	\$ 650.00 ?
6	REAR DIFFUSER (CARBON) <i>toru</i>	1	\$ 8,950.00 ✓
7	REAR LEFT SIDE MARKER <i>cracked</i>	1	\$ 580.00 ✓
8	FRONT RIGHT SIDE MARKER	1	\$ 580.00 ✓
9	REAR FRONT BUMPERS <i>toru</i>	1	\$ 2,650.00 ✓
10	FENDER, FRONT LH <i>Distorted.</i>	1	\$ 3,900.00 ✓
11	FENDER, FRONT RH <i>Distorted</i>	1	\$ 4,360.00 ✓
12	REAR FENDER, LH <i>Distorted.</i>	1	\$ 14,600.00 ✓
13	FRONT LH WHEELHOUSE APRON, FRONT PORTION <i>} distorted.</i>	1	\$ 500.00 ✓
14	FRONT LH WHEELHOUSE APRON, REAR PORTION	1	\$ 350.00 ✓
15	LEFT SIDE VIEW MIRROR <i>cracked.</i>	1	\$ 4,750.00 ✓
16	RIGHT SIDE VIEW MIRROR <i>Not there</i>	1	\$ 4,750.00 X
17	RH PLATE EXTERNAL REAR-VIEW MIRROR RIGHT CONVEX <i>Not there</i>	1	\$ 150.00 X
18	LH PLATE EXTERNAL REAR-VIEW MIRROR LEFT NONSPHERICAL <i>missing</i>	1	\$ 160.00 ✓
19	WINDSCREEN <i>cracked.</i>	1	\$ 6,150.00 ✓
20	RH REAR OMOKINETIC DRIVE SHAFT ?	1	\$ 1,330.00 ?
21	RH ABS SENSOR ?	1	\$ 35.00 ?
22	KIT REAR AXLE UNTIL THE VIN ALA09565 - INCLUDES: LH RH UPPER LOWER ARM - NUT M14 - REAR LH RH HUB CARRIER - CONNECTING ROD - SCREW	1	\$ 4,250.00 ?
23	HEADLIGHT, LH ?	1	\$ 5,850.00 ?
24	HEADLIGHT, RH <i>cracked.</i>	1	\$ 5,850.00 ✓
25	POWER STEERING RACK <i>Broken.</i>	1	\$ 5,505.00 ✓
26	SIDE MEMBER COVER, OUTER RH <i>Requis</i>	1	\$ 1,400.00 X
27	SIDE MEMBER COVER, OUTER LH <i>toru</i>	1	\$ 1,400.00 ✓
28	ELECTRIC FAN ?	2	\$ 1,400.00 ?
29	RH WATER RADIATOR <i>Distorted.</i>	1	\$ 1,950.00 ✓

Fan Cover	30	A/C CONDENSOR Distorted	1	\$	760.00 ✓
	31	RH SUPPORT ?	1	\$	480.00 ?
	32	RH CONVEYOR ?	1	\$	500.00 ?
	33	RH CONVEYOR ?	1	\$	145.00 ?
	34	RH CONVEYOR ?	1	\$	145.00 ?
	35	SHOCK ABSORBER (STANDARD/LIFTING SYSTEM - UNTIL THE VIN ALA09701 REPLACE PER AXLE) STANDARD ?	2	\$	5,350.00 ?
	36	RIM (SCORPIUS- FOR SUPERLEGGERA LP 570-4 MODEL) Lt	2	\$	11,850.00 ✓
	37	RIM (SCORPIUS- FOR SUPERLEGGERA LP 570-4 MODEL) Lt	2	\$	12,750.00 ✓
	38	RH FRONT BRAKE CALIPER (ORANGE FORNT CALIPERS-FROM VIN ALA09374) Not Nec	1	\$	2,150.00 X
under covers	39	STREAMLINE SHROUD torn	1	\$	3,510.00 ✓
	40	STREAMLINE SHROUD, REAR torn	1	\$	250.00 ✓
				\$	126,000.00
			Less Discount 10% :		\$ (12,600.00)
			List Parts Sub-Total :		\$ 113,400.00

SPECIAL NETT

1	STANDARD TYRES (Front) Lt	2	\$	1,500.00 1000
2	STANDARD TYRES (Rear) RHut, LH Not Nec	2	\$	1,500.00 500
3	1 SET RR NO. PLATE cradded (Front)	1 SET	\$	120.00 60
SPECIAL NETT SUB-TOTAL :			\$	3,120.00

PARTS TOTAL : \$ 116,520.00



Labour Description

ETLIA AUTOWORKZ PTE LTD
No. 53 Ubi Avenue 1 # 01-16
Paya Ubi Industrial Park
Singapore 408934 .

Tel : 6747 5277 Fax : 6444 0200
Co.Reg.No. : 201707802C
GST.Reg.No. : 201707802C
Quotation No. : ETQ0026/18

Vehicle No. : SE 98 S

Car Model : Lamborghini LP550-2 SLE

S/No.	Labour Descriptions	Repairer's Estimate (S\$)
1	Towing from Malaysia to Singapore workshop .	\$ 1,200.00 ?
2	To check electrical system and repair wire hardness for front bumper .	\$ 250.00 200
3	To transfer front bumper component to front bumper .	\$ 300.00 180
4	To remove and reinstall front interior trims , garnishes , etc. for necessary repairs	\$ 300.00 150
5	To remove and reinstall exhaust silencer for necessary repairs	\$ 300.00 ?
6	To straighten , repair , realign on affected area and replace damaged parts for front bumper .	\$ 2,400.00 1800
7	To check electrical system and repair wire hardness for rear bumper .	\$ 250.00 200
8	To transfer tailgate component parts to new tailgate .	\$ 250.00 X
9	To remove , replace and/or transfer rear reverse sensors & control unit .	\$ 300.00 100
10	To straighten , repair , realign on affected area and replace damaged parts for rear bumper .	\$ 2,400.00 2100
11	To conduct chassus alignments .	\$ 350.00 300
12	To spray painting , blending on effected and adjacent area including right hand fender , left hand fender and rear left hand fender .	\$ 5,600.00 4500
13	To spray anti-rust coating on new and affected panels .	\$ 400.00 280
14	To remove , replace ad reinstall suspension for front right hand and rear right hand .	\$ 500.00 ✓
15	To inspection , diagnose , reset and perform coding programming on :- 12.1) Rear reverse camera and sensor systems . 12.2) Rear air suspension system . 12.3) Security lock and rear boot system .	\$ 500.00 400
16	To remove and repair drive shaft .	\$ 300.00 ?
17	To remove and replace rim tyres , including tyres balancing .	\$ 400.00 280
18	To straighten , repair , realign on affected area for roof top include remove roof lining , garnishes , trim ,etc	\$ 2,000.00 ?

LABOUR TOTAL : \$ 18,000.00

TOTAL (PARTS & LABOUR) : \$ 134,520.00

Adrian King 96893735
4/5

No. 53 Ubi Avenue 1 #01-16
 Paya Ubi Industrial Park
 Singapore 408934
 Tel : 6747 5277 Fax : 6444 0200
 Co.Reg.No. : 201707802C

Proforma Invoice : 240418
 Work Order No. : 0406
 Date : 24/4/2018
 No. of Pages : 1
 Terms of Payment : CASH/CREDIT CARD/CHEQUE
 Account Code :

To :
 Name : DARLY TEO
 Address :
 Contact No. : 9649 1991

Vehicle No. : SE 98 S
 Make / Model : LAMBORGHINI LP550-2 SLE
 Mileage : 24690 KM
 Vin : ZHWGE52Z1BLA10542

No.	Qty	Description	List Price	Amount
1	1	TOTAL FOR THE PARTS NEED TO REPLACE . (REFER TO THE ATTACHEMNT FOR MORE DETAILS ON PARTS REPLACE)	\$ 116,520.00	\$ 116,520.00
2	1	TOTAL FOR LABOUR CHARGES . (REFER TO THE ATTACHEMENT FOR THE LABOUR DESCRIPTIONS)	\$ 18,000.00	\$ 18,000.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
Remarks : For Cheque Payment Please make cheque payable to Etalia Autoworkz Pte Ltd OCBC Account : 588 132 993 001			TOTAL : GST (7%) : DEPOSIT : TOTAL DUE (SGD) :	\$ 134,520.00 \$ 9,387.00 \$ - \$ 143,907.00

Authorized Signatory
 For Etalia Autoworkz Pte Ltd