

SE98S , Lamborghini LP550-2 SLE , Second Supplementary Item Description

Parts Description		QTY	SGD \$
Front and Rear Brake Disc crooked when moving.			
1	Front Brake Disc <i>Warpped</i>	2	\$ 1,770.00 ✓
2	Rear Brake Disc <i>Warpped.</i>	2	\$ 2,400.00 ✓

Engine warning light on after start. Check and found ECU and wireness need to replace as recommended by factory.


1	Master ECU <i>{ Damaged</i>	1	\$ 3,500.00 ✓
2	Slave ECU	1	\$ 3,500.00 ✓

Extra item found after repair and start up vehicle.

1	Speed Sensor <i>Damaged</i> Reason : Unable to detect wheel speed.	1	\$ 275.00 ✓
2	Water Tank <i>Replaced</i> Reason : Water tank leaking after heat up.	1	\$ 475.00 ✓
3	Car Plate (Front & Rear) <i>New</i>	1	\$ 100.00 ✓
4	Front Left Hand Headlamp Cover <i>New</i> Reason : Missing item.	1	\$ 650.00 ✓
5	Front Emblem <i>New</i> Reason : Destroyed when accident.	1	\$ 880.00 ✓

PARTS TOTAL :	\$	13,550.00
7 % GST :	\$	948.50
GRAND TOTAL :	\$	<u>14,498.50</u>

Adrian Lij
4/3 10/12/18.



SE98S , Lamborghini LP550-2 SLE , Second Supplementary Labour Description

S/NO.	Labour Description	QTY	SGD \$
1	To supply labour to remove and replace front and rear brake disc inclusive of brake system bleeding.	1	\$ 500.00 350.
2	To supply labour to remove and replace master and slave ECU.	1	\$ 500.00 400.
3	To perform coding of ECU and check electrical errors after replacement with Lamborghini original tester.	1	\$ 900.00 750.
4	To remove and repair roof lining. Roof lining drop after straightening job due to twisted roof repair.	1	\$ 800.00 500.
5	To repair 1 pc of starter motor. To replace 1 pc of alternator. To skim commutator.	1	\$ 900.00 650.
6	To supply labour to install front windscreen with supply of silicone and gasket.	1	\$ 850.00 550.

SUB TOTAL : \$ 2,700.00

7% GST : \$ 189.00

GRAND TOTAL : \$ 2,889.00

Adrian L
L/S 10/12/18.