



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0912999

Date: 11 Apr 2018

Policy No: GA316866

Veh Reg No: SLU9658R

Make/Model: JAGUAR XJ 3.0S/C PL

LWB

Your Ref No: S8M00DL1

Claim Type: Own Damage

Accident Date: 09/04/2018



Not Authorised
Permy Bepaint 1.B.1 5days
Ex @1500

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
SPARE PARTS				
1 HEADLAMP RH		1 PC	1,900.00	✓
2 FRONT BUMPER		1 PC	1,700.00	✓
3 FRONT BUMPER SIDE RETAINER RH		1 PC	40.00	✓
4 FRONT BUMPER CLIPS X 15		15 PC	52.50	✓
5 FRONT BUMPER REINFORCEMENT		1 PC	510.00	X
6 FRONT BUMPER SPONGE		1 PC	240.00	X
7 FOGLAMP COVER RH		1 PC	170.00	?
8 FOGLAMP CHROME MOULDING RH		1 PC	230.00	X
9 FRONT FENDER RH		1 PC	1,120.00	✓
10 FRONT FENDER V6 LOGO		1 PC	204.00	✓
11 FRONT FENDER COWLING		1 PC	250.00	?
12 FRONT FENDER COWLING CLIPS X 8		8 PC	9.60	?
13 FRONT WHEEL BEARING WITH HUB RH		1 PC	320.00	?
14 FRONT KNUCKLE ARM RH		1 PC	420.00	?
15 FRONT LOWER ARM RH		1 PC	270.00	?
16 FRONT SIDE ARM NO. 1 RH - CHECK PRICE		1 PC	0.0000	?
17 FRONT SIDE ARM NO. 2 RH - CHECK PRICE		1 PC	0.0000	?
18 FRONT UPPER ARM RH		1 PC	250.00	?
19 FRONT TIE ROD RH		1 PC	85.00	?
20 FRONT TIE ROD BALL JOINT RH		1 PC	65.00	?
21 FRONT STEERING RACK		1 PC	4,300.00	?
22 FRONT SHOCKABSORBER RH		1 PC	440.00	?
23 FRONT SHOCK ABSORBER TOP MOUNTING		1 PC	95.00	?
				12,671.10

Special Nett

24 TYRE RHF - CHECK PRICE	1 PC	0.0000	70/12
25 SPORT RIM RHF	1 PC	1,280.00	X
			1,280.00

LABOUR

26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20/
27 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	500.00	?
28 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS.	1 PC	120.00	60/



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 11 Apr 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: -
Claim Type: Own Damage
Accident Date: 09/04/2018

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
29 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	280.00	7
30 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00	500
31 TO SPRAY FRONT BONNET, FRONT FENDER RH, FRONT BUMPER		1 PC	900.00	500
				2,740.00

Amount Before Excess S\$ 16,691.10

Add GST @ 7% 1,168.38

Total Amount payable S\$ 17,859.48

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND EIGHT HUNDRED FIFTY NINE AND CENTS FORTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

