

28/01/2001

REC. BY:

REF:

CO/MSG18006770/Kth

Special Instruction:

Surveyor
Maiman

Kenneth

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

msch

Date/Time:

12042018 147pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHV 8820Z

Insured:

WB 3691P

at Workshop m/s

Queen Miter

Tel:

6453 6111

of

Blk 176 Sin Ming Drive #02-03

Policy No:

J7873149TMV

Claim No:

555232.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10042018

CA / REV / REP. / REV 24 HRS Wp

13-042018

H.O.D. Endorsement:

Date/Time:

13042018 219pm

Person Contacted:

Henry

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHV 8820Z - NJA / INC 090701 / gl
6/6	6/6 1/1 Sup @ 30500 Confirm Ah Hg (Red @ 2997.45, 49%)
07/6/18	2300 revised to Lionel Tan via Maiman

REF: MSLG

ASSIGNMENT

Form Date: 13042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: SGV 8820Z
 at Workshop no: Guan Motor
 of: 176 Sim Ming Drive #02-03

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 0.5 days Res: Yes or No

Lump Sum: 2.0. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh ID: SGV 8820Z Yr Regn: 06 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Wish A) 1794

Colour: A. Black A/C: Insured / Std / NI / NA

Sp. Reading: 208354 T/Radio: Insured / Std / NI / NA

Eng No:

C/No: 7NE10 0369270

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal: 8 mm

Rear

R/Bal: 8 mm

L/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 10/4/18

D.O.I: 13/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

16/4 File pass to Catherine

[Signature]
 1/6/2018

RECEIVED 8 JUN 2018

Date/Time: File Pass to?

08/6 12:30

Date/Time: File Return to?



Prel. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

1. 2 x P1. 01

1. Photo

1. Other

1. Other

TOTAL

Add Fee:



Site Insp: \$



Interview: \$



Test: \$



Assessment: \$

Report Format:

MER-18

Lump Sum / I.B. 13

3050



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006770/Ktb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WB 5691P	Veh. Inspected	SGV 8820Z
Policy No.	27873149TMV	Coverage (\$)	0.00
Claim No.	555232	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	12/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/04/2018	Inspection Date	13/04/2018
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Apr 2018		12 Apr 2018 13:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GUAN HUAT CRANE SERVICE PTE.LTD., Co. Reg. No.: 200609810R								
Main Claimant:	SU WENHONG TERENCE, ID: S8111037I								
Vehicle Reg. No.:	SGV8820Z	Date of Loss:	10/04/2018 08:00 - :59 [129 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555232	Policy/Cover Note No.:	27873149TMV (Third Party Only) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	WB5691P	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/04/2018]								
Adj Asg. Remarks:	Please appoint MR KENNETH KONG to conduct the survey. Kindly contact AH HENG @ 6453 6111 to arrange for survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 07 Jun 2018

Preliminary Advice

Insured Vehicle No	: WB5691P	Accident Date	: 10/04/2018
TP Vehicle No	: SGV8820Z	Assignment Date	: 12/04/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 5
Date of Inspection	: 13/04/2018		
Inspection At	: Guan Huat Works		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,027.45
Revised Amount	:S\$	3,815.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,815.65
Lump Sum Repair	:S\$	3,050.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MOBANK00102 / 3114155 Avicore BPO Pte Ltd - HQ
ENTRY DATE & TIME: 10/04/2018 12:10
SUBMITTED BY: NUR AIN AINIA Dhiran

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the state of no accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/04/2018 12:10
Date Of Accident 10/04/2018 09:05
Exact Location Of Accident WHITLEY ROAD RIGHT TURN TO OUNEARN ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGV88202
Insured/Policyholder
Name Of Registered Owner SU WENHONG TERENCE
NRIC No S8111037I
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98760911
Alternative Phone No OFFICE-NOPHONE
Vehicle Particulars
Manufacturer TOYOTA
Model WISH
Exact Purpose for which vehicle was being used at time of accident PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5038685652-08
Cover Note Number
Driver
Name of Driver KUI SOD LO LI ZHANG
NRIC No S8075068H
Date Of Birth 14/09/1980
Occupation INDOOR
Date Of Driving Pass 14/02/2014
Driving Experience 4 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-98760911
Fax Number
Contact Number
Email Address NOEMAIL

Address 78 CARISBROOKE GROVE
 Postcode 558853
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SERANGOON NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 50 SERANGOON AVE 2 #01-02, POSTCODE: 556129, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4880999 - FAX NO: 84683561
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED FILES

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WB5691P
 Vehicle Make/Model/Colour KATO CRANE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LOH HOCK GUAN
 NRIC/Passport Number S1210384J
 Control Number 95733415
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 10th April 2018 at 8.03 am, I Leong Zhenyong Kuei Rose was at Whitley Rd waiting to turn to Bursat Timah Rd. However vehicle B WB5691P (big and long crane) turn first and hit at the front left side of my vehicle A 2GUB8202 while it was stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/PID No.:

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to invalidate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Age, wife, husband, job, etc. referred to the policy for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) assessing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/con be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to an insurer and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, litigation, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Name & Title


Driver's Signature
(if driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AMENDED NOTICE OF COMPLIANCE Pg. 1

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

This is to confirm that Kui See Lo Li Zheng,
NRIC/FIN S8075066H, has reported to the Police a non-injury traffic accident
which occurred at Whitley Road, right turn to Dunearn Road
on 10/04/2018 at 0803 am involving the following vehicles:

- SGV8820Z
- WB5691P

- 2 If this accident was reported to the Police within 24 hours of its occurrence,
Then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt T100444 Teo Jine XianDate: 10/04/2018Time: 0852hrsS/D Ref: 21Police Post/Unit: Serangoon NPC

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

CONFIDENTIAL

Version as of 15 Jan 2002

Work Order: R047548
 License: SGV8820Z
 Year: 08
 Date: 13.4.18 10:35

Factory Japan 2017.0.1 Copyright (c) 2016 Hunter Engineering : Toyota : Wish : E10 Series : ZNE10G

Front : Left

Actual	Before	Specified Range
-2°05'	-2°04'	-1°15' 0°15'
2°36'	2°36'	2°20' 3°50'
0°03'	0°07'	-0°05' 0°05'
13°32'	13°31'	10°35' 12°05'
11°27'	11°27'	9°20' 12°20'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°26'	-0°28'	-1°15' 0°15'
3°09'	3°09'	2°20' 3°50'
-0°06'	-0°03'	-0°05' 0°05'
11°39'	11°39'	10°35' 12°05'
11°13'	11°13'	9°20' 12°20'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-1°39'	-1°38'	-0°45' 0°45'
-0°32'	-0°32'	-0°45' 0°45'
1°53'	1°53'	
-0°03'	0°04'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°28'	-1°38'	-2°00' -1°00'
0°31'	0°32'	-0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°38'	-2°00' -1°00'
-0°08'	-0°08'	-0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°10'	-0°11'	-0°30' 0°30'
0°23'	0°24'	-0°03' 0°25'
0°20'	0°20'	
0mm	0mm	

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SGV8820Z

10-04-18

No.	Qty	List Items
1	1	Front bumper 472.80
2	1	Front bumper LH fog lamp
3	2	Front bumper side retainer
4	1	Front bumper inner reinforcement
5	1 set	Front bumper clips
6	1	Front LH fender
7	1	Front LH fender under shield
8	1 set	Front fender under shield clips
9	1	LH headlamp
10	1	Front LH shock absorber 488.90
11	1	Front LH lower arm
12	1	Front LH knuckle arm
13	1	Front LH wheel hub
14	1	Front LH wheel bearing
15		

Part	\$	1,077.50	✓
mgmt	\$	162.00	✓
nl	\$	114.00	✓
	\$	225.90	X
	\$	40.00	✓
	\$	686.00	✓
	\$	131.50	X
	\$	30.00	X
	\$	691.00	✓
	\$	693.10	✓
	\$	469.10	X
	\$	408.90	✓
	\$	182.50	✓
	\$	125.10	✓
	\$	5,036.60	
Less 25%	\$	1,259.15	
Total :	\$	3,777.45	

Special Nett Items

16	1	Front LH sports rims
----	---	----------------------

\$	Part	500.00	2800
Total :	\$	500.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To check wirings and lightings.
4	To remove, refix front LH under carriages.
5	To conduct computerise wheel alignment test.
6	To supply and apply anti rust treatment

\$	600.00	400
\$	700.00	400
\$	40.00	200
\$	250.00	1400
\$	80.00	600
\$	80.00	300
Total :	\$	1,750.00

Total Parts and Labour : \$ 6,027.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised

LT 83050t

Revey After Paint

4 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2018		12 Apr 2018 13:47 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GUAN HUAT CRANE SERVICE PTE.LTD., Co. Reg. No.: 200609810R								
Main Claimant:	SU WENHONG TERENCE, ID: S8111037I								
Vehicle Reg. No.:	SGV8820Z	Date of Loss:	10/04/2018 08:00 - :59 [129 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555232	Policy/Cover Note No.:	27873149TMV (Third Party Only) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	WB5691P	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/05/2018]								
Adj Asg. Remarks:	Please appoint MR KENNETH KONG to conduct the survey . Kindly contact AH HENG @ 6453 6111 to arrange for survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGV8820Z (555232)
[WB5691P]
TP
SU WENHONG TERENCE
Apr 10 2018 8:00AM
[GUAN HUAT CRANE SERVICE PTE.LTD.]
Guan Motor Works

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Letters/Correspondences

1 per page

No

Finalized On

MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Thumbnail

Print

1

12/04/18 13:43

Non Reporting Letter to OI

Load HTM

Assessment Reports

1 per page

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

07/06/18 14:30

Adjuster Immediate Advice

Load HTM

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

07/06/18 14:26

General View

Load JPG

2

07/06/18 14:26

General View

Load JPG

3

07/06/18 14:26

General View

Load JPG

4

07/06/18 14:26

General View

Load JPG

5

07/06/18 14:26

General View

Load JPG

6

07/06/18 14:26

General View

Load JPG

7

07/06/18 14:26

General View

Load JPG

8

07/06/18 14:26

General View

Load JPG

9

07/06/18 14:26

General View

Load JPG

10

07/06/18 14:26

General View

Load JPG

11

07/06/18 14:26

General View

Load JPG

12

07/06/18 14:26

General View

Load JPG

13

07/06/18 14:26

General View

Load JPG

14

07/06/18 14:26

Odometer Reading

Load JPG

15

07/06/18 14:26

General View

Load JPG

16

07/06/18 14:26

Chassis Number

Load JPG

17

07/06/18 14:28

Reinspection Photo

Load JPG

18

07/06/18 14:28

Reinspection Photo

Load JPG

19

07/06/18 14:28

Reinspection Photo

Load JPG

20

07/06/18 14:28

Reinspection Photo

Load JPG

21

07/06/18 14:28

Reinspection Photo

Load JPG

22

07/06/18 14:28

Reinspection Photo

Load JPG

23

07/06/18 14:28

Reinspection Photo

Load JPG

24

07/06/18 14:28

Reinspection Photo

Load JPG

25

07/06/18 14:28

Reinspection Photo

Load JPG

Documentation

1 per page

No

Finalized On

MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Thumbnail

Print

1

12/04/18 13:34

TPD SGV8820Z - PRI & GIA REPORT

Load PDF

2

12/04/18 13:34

Reply email from TP Lawyer & appoint KENNETH KONG

Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer. Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006770/KTBQ2

Date: 08/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27873149TMV

Claimant Vehicle No : SGV8820Z

Insured Vehicle No : WB5691P

Date of Loss: 10/04/2018

Nature of Claim: TP

Claim No: 555232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV8820Z**

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 1ZZ2923613

Reg. Date: 28/06/2007 (Man. Year: 2007)

Chassis No: ZNE100369270

Colour: Metallic Black

Odometer: 208354 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,277.45	2,765.65	1,511.80	35.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,050.00	700.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,027.45	3,815.65	2,211.80	36.70
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	6,027.45	3,050.00	2,977.45	49.40

INSPECTION

Date of Assignment: 12/04/2018

Date Inspected: 13/04/2018 Inspected At:

Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2018)	
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SGV8820Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,077.50 FL	*472.80 FL
2	1		*FRONT BUMPER LH FOG LAMP	Mtg Cracked	162.00 FL	*162.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	N/S Distorted	114.00 FL	*57.00 FL
4	1		*FRONT BUMPER INNER REINFORCEMENT	Repair	225.90 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
6	1		*FRONT LH FENDER	Buckled	686.00 FL	*686.00 FL
7	1		*FRONT LH FENDER UNDER SHIELD	Serviceable	131.50 FL	*- FL
8	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
9	1		*LH HEADLAMP	Cut	691.00 FL	*691.00 FL
10	1		*FRONT LH SHOCK ABSORBER	Bent	693.10 FL	*488.90 FL
11	1		*FRONT LH LOWER ARM	Serviceable	469.10 FL	*- FL
12	1		*FRONT LH KNUCKLE ARM	Bent	408.90 FL	*408.90 FL
13	1		*FRONT WHEEL HUB	Bent	182.50 FL	*182.50 FL
14	1		*FRONT WHEEL BEARING	Necessary	125.10 FL	*125.10 FL
15	1		*FRONT LH SPORTS RIMS	Dented	500.00 FS	*280.00 FS
					Sub Total (\$\$)	5,536.60 3,594.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,259.15 828.55
					Total Parts (\$\$)	4,277.45 2,765.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	600.00	400.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	700.00	400.00
3	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE,REFIX FRONT LH UNDER CARRIAGE	New	250.00	140.00
5	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
6	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	30.00
Gross Labour Cost (\$\$)			1,750.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >