

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE NO:SGD 6400K

Not Authorised
2/5 @ 2000h
3dy.
12/4/18
When photo taken repair

QTY	PARTICULAR	AMOUNT
1 PCS	REAR BUMPER	\$1,415.20
1 PCS	REAR BUMPER SIDE RETAINER O/S	\$66.80
1 SET	REAR BUMPER CLIPS	\$50.00
1 PCS	REAR BUMPER SPLASH SHIELD O/S	\$121.20
1 PCS	REAR FENDER O/S	\$1,105.30
1 PCS	REAR FENDER GLASS O/S	\$845.22
1 PCS	TAILAMP O/S	\$425.10
1 PCS	REAR SHOCK ABSORBER O/S	\$391.10
1 PCS	REAR WHEEL HUB BEARING O/S	\$645.20
1 PCS	REAR SPORT RIM O/S	\$680.00
	TO CHECK WIRING	\$50.00
	TO DISMANTLE & REFIX REVERSE SENSOR	\$80.00
	TO DISMANTLE & REFIX REAR FENDER GLASS O/S	\$120.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$150.00
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	\$300.00
	TO SPRAY RUST PROOFING	\$80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$680.00
	TO PUTTY & SPRAY PAINTING	\$800.00
	TOTAL	\$8,005.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1532
1225-6
2553-6
2044.