



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SB6Z

Mr Shaw Harold @ Shaw Vee Chung

10 Lady Hill Road  
Singapore 258677

62352077(O)

### Vehicle & Document Information

WIP No **22677**  
Reg No/Reg Date **SB6Z / 03/08/2015**  
Date In/Mileage **0**  
Chassis No **WDD2221652A182898**  
Engine No **27682430214851**  
Make/Model **MB/S 400 L BlueEFFICIENCY SE**  
Colour/Trim **024 474 Peridote Br/ 048 814 Leather Cap**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV04318	CRDVCH	11/04/2018/ 17:37	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN POLICY NO/ACC DATE : GA244783/1 // 06-04-2018 DRIVE IN: 09-04-2018 // TP CAR NO: SLA3603T (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00
S BPNSUB SUPPLY & TRANSFER 1PC REAR RIGHT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT				600.00
A BPILAB REMOVE & REPLACE REAR RIGHT DOOR & REPAIR REAR BUMPER AND REAR RIGHT FENDER				2400.00
A BPIRES RESPRAY REAR BUMPER, REAR RIGHT FENDER & REAR RIGHT DOOR			0.03	2200.00
M RH/R DISC WHEEL	1.00	788.73	00.00	788.73
M LH/R BUMPER GARNISH	1.00	109.57	00.00	109.57
M RH/R BUMPER GARNISH	1.00	109.57	00.00	109.57
M RH/R DOOR SHELL	1.00	3229.34	00.00	3229.34
M RH/R DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M RH/R DOOR ORNAMENTAL	1.00	193.24	00.00	193.24
M RH/R DOOR BOTTOM SEAL	1.00	61.35	00.00	61.35
M RH/R DOOR SIDE SEAL	1.00	28.10	00.00	28.10
M RH/R DOOR WINDOW GUIDE RAIL	1.00	376.15	00.00	376.15

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center

Confirmed & accepted by

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Nett **11,456.77**  
7% GST on **11456.77** **801.97**

Authorized signatory and company stamp

**Total Payable 12,258.74**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg