

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05764

Vehicle Insured : XD9117H
Accident Date : 09-Apr-2018

Date : 11-Apr-2018

Our Ref : 218067 (AXA) / CHAN

PAGE : 1

LIM HOOI KOW
8 KITCHENER LINK
#12-16
Singapore 207226

Not Authorized
Lim Hooi Kow
Recovery After Paint
7 days

ESTIMATED COST OF REPAIR FOR HONDA AIRWAVE 1.5A SGK3183U

1 pc	Rear o/s fender		<i>R</i> 970.20	✓
1 pc	Rear o/s fender inner shield		48.40	?
1 pc	Rear o/s fender inner trim		278.90	?
1 pc	Rear o/s fender wheel housing		<i>R</i> 352.40	X
1 pc	Rear o/s quarter glass moulding		<i>R</i> 59.10	✓
1 pc	Rear bumper fascia		<i>Bu</i> 912.60	✓
1 pc	Rear o/s bumper side retainer		<i>Dr's</i> 24.40	✓
1 pc	Rear o/s door		<i>R</i> 955.70	✓
2 pcs	Rear o/s door frame tape	@ S\$ 55.40	<i>R</i> 110.80	✓
1 pc	Rear o/s door glass regulator gear assy		481.70	?
1 pc	Rear o/s door inner lock		<i>R</i> 294.10	X
2 pcs	Rear o/s door hinge	@ S\$ 49.50	<i>R</i> 99.00	X
1 pc	Front o/s door		<i>R</i> 996.30	✓
2 pcs	Front o/s door frame tape	@ S\$ 70.40	<i>R</i> 140.80	✓
			5,724.40	
		Less 20% :	1,144.88	

1 pc Rear o/s quarter glass sealant

R 4,579.52 *kosn*
R 60.00 *sn*

To remove & refix rear o/s quarter glass

120.00 *sol*

To remove roof lining, front and rear seats, trim board and carpet

150.00 *100%*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XD9117H

Page : 2

To apply undersealing

100.00 *900*

To putty and spray replaced parts

1,400.00 *900*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,600.00 *1000*

Total : S\$ 8,009.52

=====

Singapore Dollars Eight Thousand and Nine and
Cents Fifty Two Only