

15/9/2018

INS. CASE OWNER:

Addline

CC 3/CT 180

06792, Swaz

LKK:

IDAC:

Surveyor:

ywk

DOI:

ASSIGNMENT

10-4-18

Date / Time:

10-4-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GEB 6919B

Name of Insured:

United Transport Services

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

1/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

um wei ye shawn

Driver Tel No.:

86680411

(V/L: YES / NO)

Claim No.:

SM1801847002

Policy No.:

SM1801847002

Make / Model:

KIA 2002

Place of Accident:

Orchard Rd

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:

WSP:

Tel:

Liability:

RMKS:

Emp 7.11

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/4

11/4/18

17/4/18

22/5/18

6/6/18

14/6/18

14/6/18 - 13/11/18 10:20:35 / 14/6/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

13/11/18 10:20:35 / 13/11/18 10:20:35

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Lee Gek

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

22

Repair Cost:

\$S

7000.00

Loss of Rental (LOR):

\$S

1118.20

(

10

days)

X 111.82

Loss of Use (LOU):

\$S

(\$

x

days)

Loss of Income (LOI):

\$S

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

\$S

7.00

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost:

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$S

8125.20

Global Sum \$S:

8100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

8100.00

Name 1:

SMRT Taxis Pte Ltd

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT

RECEIVED 20 JUN 2018
RECEIVED 22 MAY 2018

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

20/5/18 Confirm Lls \$7000.00 with 6 working days

TAX / 04/18/2046

LKK

Ching Teiping

GAB 67918

(20 - \$12537.83
6451.)

Date/Time. File Pass to?

☐

Prel. Report

1)

Date/Time. File Return to?

☐

Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation.

) \$ + RS. \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18006792/Swa3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6919B	Veh. Inspected	SHC 4723K	
Policy No.	DMCVSN17691311700	Coverage (\$)	0.00	
Claim No.	SNM18D01847C02	Excess (\$)	0.00	
Assign From		Assign Date	12/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/04/2018	Inspection Date	10/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**SMRT Accident Vehicle Repair Estimates****Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHC4723K
 Ref. No : TAX/04/18/2046
 Reg. Date : 04/03/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WOON YONG CHIANG (YUN YONGQIANG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 07/04/2018 07:35:00 PM
 Accident Reported Date / Time : 09/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 07/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095463
 Special Instruction to ARC, if any :



TOWED \$40 / GBB6919B - CHINA TAIPING - LKK
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
 LUMPSUM REPAIR

Prepared Date : 09/04/2018 02:38:51 PM

90692398 Woon. 0845 ✓

Recording Camera

☐
☒

Radio Antenna

☐
☒

1st witness

Date

10-4-18

2nd witness

Date

QC 18/4/18 18:49 PMS

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

18-4-2018

Vehicle Return Time:

17:50

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U005759207

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	1,000.00
Total Spray Painting Charges	: 2,772.00	1,000.00
Total Material Charges	: 10,934.08	4,256.88
Other Charges	: 2,450.00	760.00
TOTAL	: 17,508.08	7,016.88
Lum Sum Total	: 17,500.00	7,000.00
No. of Repair Days	: 8.00	6.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 09/04/2018 04:40:35 PM	10/04/2018 03:28:53 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/04/2018 04:35:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0580
Quotation Date : 24/4
Invoice Amount : 0.00

Invoice No :

Invoice Date :

Prepared Date : 4/9/2018 4:44:04 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	1,000.00 /
Total Labour	1,352.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR MEMBER,LH	180.00	0.00
TO RESPRAY REAR MEMBER,RH	180.00	0.00
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00
TO RESPRAY RIM	180.00	0.00
Total Spray Painting & Panel Beating	2,772.00	1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	40.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40.00 /
TO REMOVE / REFIT SEAT	120.00	50.00 /
TO ALIGN CHASSIS	350.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) <i>SN net</i>	250.00	250.00 /
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	60.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	150.00 /
TO REMOVE AND REFIT WIRE HARDESS	250.00	30.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	2,450.00	760.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ✓
52161-16010			BUMPER CLIPS	10	1.61 16.10	25.00	12.07	Replace	Replace	No ✓
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ✓
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	25.00	0.00	Replace	Not given	No X
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No X
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace S	No ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace S	No ✓
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace S	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00 120	0.00	120.00	Replace	Replace	No ✓
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Check	No X
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No X
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No X
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No ✓
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.68	Replace	Check	No X
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No ✓
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No ✓
64821-47030			TAILGATE LOWER WINDOW GLASS	1	721.30	25.00	540.97	Replace	Replace	No ✓
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No ✓
	COMMO N		SEALANT W/SCREEN	3	37.00 111	0.00	111.00	Replace	Replace	No ✓
68960-0W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.13	Replace	Check	No X
68950-0W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.13	Replace	Replace S	No ✓
68810-47010			TAILGATE DOOR HINGE LH/RH	2	58.30 116.60	25.00	87.45	Replace	Check	No X
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.08	Replace	Check	No X
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.78	Replace	Check	No X

6187.60

3130.39

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Check	No X
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.18	Replace	Check	No X
82184-47370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16	Replace	Check	No X
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No ✓
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No ✓
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No ✓
81271-53011		6505463	LICENSE PLATE LAMP	2	35.70 71.40	10.00	64.26	Replace	Check	No X
84840-28040	REAR		SWITCH ASSY, BACK DOOR OPENER	1	146.10	10.00	131.49	Replace	Check	No X
86790-47040			CAMERA ASSY, TELEVISION, RR	1	1,436.60	10.00	1,292.94	Replace	Check	No X
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No ✓
81006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace	No ✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Replace	No ✓
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace	No ✓
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Check	No X
58336-12090			REINFORCEMENT, RR	2	34.60 69.2	25.00	51.90	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Check	No X
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Check	No X
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.78	Replace	Check	No X
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.78	Replace	Check	No X
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
42611-47140		6505658	WHEEL, DISC	0	1,490.20	25.00	0.00	Replace	Not given	No X
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.58	Replace	Check	No X
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.58	Replace	Check	No X
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.58	Replace	Check	No X
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Check	No X
58490-47140B0			BOARD ASSY, RR RH	1	379.20	25.00	284.40	Replace	Check	No X
58427-47040			SPACER, RR FLOOR	1	130.60	25.00	97.95	Replace	Check	No X

9115.34 167.66

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No X
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Replace	No /
64740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Check	No X
64730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Check	No X
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.03	Replace	Check	No X
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Check	No X
61622-47030			TROUGH, BACK DOOR LH	1	110.90	10.00	99.81	Replace	Check	No X
61602-47091		6505476	FENDER RR/LH	1	766.80	100.00	0.00	Replace	Repair	No R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.08	Replace	Check	No X
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No /
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.98	Replace	Check	No X
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Check	No X
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Check	No X
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Replace	Repair	No R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Check	No X
TOTAL MATERIALS								13,667.65	5,321.11	
TOTAL MATERIALS(Discounted)								10,934.08	4,256.88	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

5321.11

- 207

4256.88

+ 1000.00

+ 1760.00

7016.88

US \$7000/-

27128.84

Substation
30/4/18

SMRT Accident Vehicle Repair Estimates

Ching Taping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4723K
 Ref. No : TAX/04/18/2046
 Reg. Date : 04/03/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WOON YONG CHIANG (YUN YONGQIANG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 07/04/2018 07:35:00 PM
 Accident Reported Date / Time : 09/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 07/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095463
 Special Instruction to ARC, if any :
 TOWED \$40 / GBB6919B
 Prepared Date : 09/04/2018 02:38:51 PM


*Sebastian
10/4/18*

- hup Sun Repair
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U005759207

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 2,772.00	0.00
Total Material Charges	: 12,963.83	12,963.83
Other Charges	: 2,450.00	0.00
TOTAL	: 19,537.83	0.00
Lum Sum Total	: 19,550.00	0.00
No. of Repair Days	: 8.00	0.00
Prepared / Adjusted By	:	6 days
Arc / Surveyor Sign Off Date	: 09/04/2018 04:40:35 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/04/2018 04:35:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 4/9/2018 4:44:04 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00 ?	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00 ?	0.00
TO RESPRAY REAR MEMBER,LH	180.00 ?	0.00
TO RESPRAY REAR MEMBER,RH	180.00 ?	0.00
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY TROUGH BACK DOOR LH	180.00 ?	0.00
TO RESPRAY RIM	180.00	0.00 X
Total Spray Painting & Panel Beating	2,772.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 40
TO REMOVE / REFIT SEAT	120.00	0.00 50
TO ALIGN CHASSIS	350.00 ?	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	0.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 150
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	2,450.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ✓ CRK
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No ✓ NCC
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ✓ SCR
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No ✓
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No ✓
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ✓ BT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No ✓
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓ DMG
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓ NCC
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No ✓
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No ✓
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓ NCC
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓ NCC
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No ✓
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No ✓ DT
76801-47070-BO			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace	No ✓
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No ✓ NCC
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No ✓ NCC
64821-47030			TAILGATE LOWER WINDOW GLASS	1	721.30	25.00	540.97	Replace	Replace	No ✓ CRK
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No ✓ NCC
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No ✓ NCC
68960-0W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.12	Replace	Replace	No ✓
68950-0W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.12	Replace	Replace	No ✓
68810-47010			TAILGATE DOOR HINGE LH/RH	2	58.30	25.00	87.45	Replace	Replace	No ✓
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No ✓ JM

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace ✓	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace ✓	No
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17	Replace	Replace ✓	No
82184-47370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16	Replace	Replace ✓	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace ✓ NCC	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NCC	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace ✓ NCC	No
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace ✓ NCC	No
81271-53011		6505463	LICENSE PLATE LAMP	2	35.70	10.00	64.26	Replace	Replace ✓	No
84840-28040	REAR		SWITCH ASSY, BACK DOOR OPENER	1	146.10	10.00	131.49	Replace	Replace ✓	No
86790-47040			CAMERA ASSY, TELEVISION, RR	1	1,436.60	10.00	1,292.94	Replace	Replace ✓	No
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace ✓ CRK	No
81006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace ✓ CRK	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NCC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NCC	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace ✓	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace ✓	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace ✓	No
58336-12090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Replace ✓	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace ✓	No
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace ✓	No
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.77	Replace	Replace ✓	No
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.77	Replace	Replace ✓	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace ✗	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace ✗	No
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.57	Replace	Replace ✓	No
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.57	Replace	Replace ✓	No
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.57	Replace	Replace ?	No
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
58490-47140B0			BOARD ASSY, RR RH	1	379.20	25.00	284.40	Replace	Replace	No
58427-47040			SPACER, RR FLOOR	1	130.60	25.00	97.95	Replace	Replace	No
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace	No
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace	No
64740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Replace	No
64730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace	No
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace	No
61622-47030			TROUGH, BACK DOOR LH	1	110.90	10.00	99.81	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No
62720-47031	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace	No
65638-47021	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace	No
			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No
52562-47010										
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No
65637-47021	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace	No
TOTAL MATERIALS								16,204.96	16,204.79	
TOTAL MATERIALS(Discounted)							12,963.83	12,963.83		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

800.00		552.00		343.95	104.70	54.15	
800.00	-	552.00	1,352.00	12.07	104.70	88.57	
				171.67	141.66	126.74	
200.00	180.00	178.00		154.27	66.67	1,117.65	
200.00	180.00	178.00		180.00	49.27		
100.00	180.00	80.00		120.00	385.87		
200.00	180.00	178.00		71.10	378.67		
200.00	180.00	178.00		71.10	181.12		
		180.00		755.92	181.12		
900.00	900.00	972.00	2,772.00	22.05	87.45		
				22.05	11.77		
80.00	350.00	80.00		540.97	265.05		
40.00		160.00		22.05	185.17		
50.00		70.00		111.00	524.16		
250.00		60.00		333.07	64.26		
60.00		90.00		45.22	131.49		
150.00		220.00		38.92	1,292.94		
30.00		70.00		45.60	451.57		
50.00		90.00		38.92	34.57		
30.00		90.00		715.27	90.82		
30.00		90.00		208.17	51.90		
30.00		120.00		7.80	37.00		
		100.00		21.60	500.77		
		60.00		7.80	173.10		
800.00	350.00	1,300.00	2,450.00	21.60	14.77		
				37.00	107.77		
				7.80	130.57		
				21.60	130.57		
					172.57		
					147.60		
					284.40		
800.00	-	552.00	1,352.00		97.95		
900.00	900.00	972.00	2,772.00		509.70		
800.00	350.00	1,300.00	2,450.00		487.27		
3,318.86	7,615.13	2,029.85	12,963.83		230.25		
5,818.86	8,865.13	4,853.85	19,537.83		230.25		
					23.02		
19,537.83					493.56		
5,818.86					99.81		
8,865.13					126.07	575.10	
					105.97		
					23.02		
					502.02	575.10	
					105.97		
				4,148.57	9,518.91	2,537.31	16,204.79
				80.00	80.00	80.00	240.00
				3,318.86	7,615.13	2,029.85	12,963.83



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18006792/Swa3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-06-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6919B	Veh. Inspected	SHC 4723K	
Policy No.	DMCVSN17691311700	Coverage (\$)	0.00	
Claim No.	SNM18D01847C02	Excess (\$)	0.00	
Assign From		Assign Date	10/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U005759207	Colour	MAROON	
Odometer	298072	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	FALKEN	6 mm	
L/H Front Tyre	195/65R15	FALKEN	6 mm	
R/H Rear Tyre	195/65R15	FALKEN	6 mm	
L/H Rear Tyre	195/65R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/04/2018	Inspection Date	10/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4723K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER LIP REAR (DISC 25%)	SCRATCHED	228.90	171.67
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.92
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	CRACKED	721.30	540.97
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR STAY RH (DISC 25%)	DAMAGED	241.50	181.13
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.92
1	SPOILER REAR (DISC 25%)	CRACKED	953.70	715.27
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	CRACKED	46.10	34.58
1	BOX, DECK FLOOR, RR (DISC 25%)	CRACKED	649.70	487.28
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	DAMAGED	157.40	141.66
1	3RD BRAKE LAMP (DISC 10%)	CRACKED	231.30	208.17
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @ \$37.00 (SN)	NECESSARY	111.00	111.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65555 8888 (SN)	NECESSARY	21.60	21.60

Report Ref No. CC3/CTI18006792/Swa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPE SEAL, RR RH	NOT NECESSARY	65.70	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	TAILGATE DOOR STAY LH	NOT NECESSARY	241.50	-
2	TAILGATE DOOR HINGE LH/RH @ \$58.30	NOT NECESSARY	116.60	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	TAILGATE, BOARD ASSY	NOT NECESSARY	246.90	-
1	WIRE, BACK DOOR, NO.1	NOT NECESSARY	582.40	-
2	LICENSE PLATE LAMP @ \$35.70	NOT NECESSARY	71.40	-
1	SWITCH ASSY, BACK DOOR OPENER	NOT NECESSARY	146.10	-
1	CAMERA ASSY, TELEVISION, RR	NOT NECESSARY	1,436.60	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
2	REINFORCEMENT, RR @ \$34.60	NOT NECESSARY	69.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	CUSHION, SPARE WHEEL	NOT NECESSARY	230.80	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
1	PROTECTOR, SPARE	NOT NECESSARY	143.70	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL, DISC	NOT NECESSARY	1,490.20	-
1	MEMBER SUB-ASSY, RR LH	NOT NECESSARY	174.10	-
1	MEMBER SUB-ASSY, RR RH	NOT NECESSARY	174.10	-
1	BOX, DECK FLOOR, COVER LH	NOT NECESSARY	230.10	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	196.80	-
1	BOARD ASSY, RR RH	NOT NECESSARY	379.20	-

Report Ref No. CC3/CTI18006792/Swa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPACER, RR FLOOR	NOT NECESSARY	130.60	-
1	BOX, RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	PANEL ASSY, DECK LH	NOT NECESSARY	307.00	-
1	PANEL ASSY, DECK RH	NOT NECESSARY	307.00	-
1	TAIL LAMP BRACKET, LH	NOT NECESSARY	30.70	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	-
1	TROUGH, BACK DOOR LH	NOT NECESSARY	110.90	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
1	SOLAR FILM (SN)	NECESSARY	250.00	250.00
			20,854.84	5,571.13
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FENDER RR/LH AND FENDER RR/RH.		1,352.00	1,000.00
	SPRAY PAINT.		2,772.00	1,000.00
	TOWING CHARGE.		80.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO REMOVE / REFIT SEAT.		120.00	50.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		240.00	150.00
	TO REMOVE AND REFIT WIRE HARDESS.		250.00	30.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	50.00
	TO TEST AND REFIT REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00

Report Ref No. CC3/CT118006792/Swa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSPECT LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,324.00	2,510.00
GRAND TOTAL			27,178.84	8,081.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC3/CT18006792/Swa3s2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.