



ASSIGNMENT

From: Date: 23042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFS 906R

at Workshop m/s Performance

of 303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Gamy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 2-B-2 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Gamy

Veh No: SFS906R. Yr Regn: 2012 March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i CC 1992

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 107156 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA XG12010DW34274

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PUB) / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 23/4/18 @ 150

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/7/18 Confirm 2-B-2 \$9650.50 with 5 working days.

(Red = \$4410.61 35.7%)

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ + RS. \$

2) Fields

3) Others

4)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC3/III18006796/wb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 12-04-2018	
			Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3071J		Veh. Inspected	SFS 906R
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	12/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	10/04/2018		Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401599M GST Reg. No M2-0020081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747700

260, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63195528 (AfterSales)  
63195533/530 (Motorrad)  
64796502 (AfterSales)  
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

11 APR 2018

Estimate No. : b1 46553  
Date Estimated : 11/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Tan Chee Kiong  
161A Punggol Central  
#05-81

Singapore 821161

## - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS906R	DW34274	23/03/2012	520iA	0

## DESCRIPTION

## VALUE

To replace front bumper, right front fender and attachment  
include knocking cause by the accident

1700 2,550.00

Painting front bumper, right front fender.

1730 1,923.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To replace right headlight including program  
and conduct tests for proper function.

451 531.00

To replace right front rim including balancing. (1x)

84? 94.00

To replace right front tyre Pirelli 225/55/17

111 x 362.50

To check steering geometry and conduct wheel alignment  
according to BMW specification (1X)

451 531.00

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

150 177.00

Sundries. Nu

? 150.00

Total Labour 1: 6,436.50

## DESCRIPTION

## QTY PRICE

## VALUE

ALLOY RIM 8JX17 V SPOKE 236  
HUB CAP WITH CHROME EDGE (BMW)  
FRT RH FENDER  
FRT BUMPER CARRIER  
FRT BUMPER TOP IMPACT ABSORBER  
FRT BUMPER RH SPACER  
FRT BUMPER TRIM PRIMED (PDC)  
EMBLEM GROMMET  
BMW EMBLEM

1 881.20  
1 24.30  
1 863.35  
1 684.75  
1 48.00  
1 9.45  
1 1,277.55  
2 0.80  
1 69.50

Rx 881.20  
m x 24.30  
bt 863.35  
x 684.75  
x 48.00  
x 9.45  
de 1,277.55  
m x 0.80  
m 69.50



303, Alexandra Road  
Sine Darby Performance Centre  
Singapore 119941  
Tel. 43182100 (Sales & Admin)  
43180111 (AfterSales)  
Fax. 44747770

287, Kampong Arang Road  
East Coast Centre  
Singapore 438185  
Tel. 63190888 (AfterSales)  
Fax. 63448771

115, Alexandra Road  
Sims Darby Business Centre  
Singapore 159544  
Tel. 43180518 (AfterSales)  
43180513/532 (Motorrad)  
Fax. 44786001 (AfterSales)  
44786004 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 46553  
Date Estimated : 11/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS906R	DW34274	23/03/2012	520iA	0

## DESCRIPTION

RH BI-XENON HEADLIGHT  
DECOUPLING RING PDC TORQUE CONVERTER  
BUMPER PDC SENSOR (A90 SOPHISTOGRAU)

QTY	PRIC	VALUE
1	2,631.15	2,631.15
4	5.05	20.20
2	368.80	737.60

Total Parts	:	<u>7,248.65</u>
-------------	---	-----------------

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (illegal modification(s)) is allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature: \_\_\_\_\_

Date:

Client's C.O. / S.O. / P.O. / Estimated Date of Birth: 11/1/1990  
 Registration: 25/4/18 @ 11:50  
 Surveyor's Name: Taufik  
 Surveyor's Tel: 97495749  
 Acquisition Date: 11/1/1990  
 Surveyor's Email: taufik@inter.net  
 Surveyor's Signature: 5 days

Labour 1	:	6,436.50
Parts	:	7,248.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	957.96
Grand Total	:	<u>14,643.11</u>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***

**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M3-0020581-X



## SUPPLEMENTARY

Estimate No. : b1 46553  
Date Estimated : 11/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Tan Chee Kiong  
161A Punggol Central  
#05-81

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 821161

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFS906R	DW34274	23/03/2012	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# FRT RH 1 SIDE PANEL BRACKET *	32.15	1.00		32.15 <i>ht</i>
# RIVET *	0.45	5.00		2.25 <i>ht</i>
# HEADLIGHT GASKET SET *	31.55	1.00		31.55 <i>ht</i>

Total Labour :	
Total Parts :	65.95
Total Labour & Parts :	65.95

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg No. 1874215BW GST Reg No. M2-002081-8



## FINAL REPORT

Estimate No. : b1 46553  
Date Estimated : 11/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Tan Chee Kiong  
161A Punggol Central  
#05-81

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 821161

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFS906R	DW34274	23/03/2012	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front RH fender and attachments include knocking out dents caused by the accident	1700.00		1,700.00	/
To spray paint front bumper and front RH fender	1730.00		1,730.00	/
To carry out body cavity preservation. (Per panel).	100.00		100.00	/
To replace RH bi xenon headlight include programming and conducting tests for proper function	451.00		451.00	/
To remove and install front RH rim include balancing (1x)	83.00		83.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	/
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	/
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# FRT RH 1 SIDE PANEL BRACKET *	32.15	1.00		32.15
FRT RH FENDER	863.35	1.00		863.35
FRT BUMPER TRIM PRIMED (PDC)	1,277.55	1.00		1,277.55
BMW EMBLEM	69.50	1.00		69.50
# RIVET *	0.45	5.00		2.25
# HEADLIGHT GASKET SET *	31.55	1.00		31.55
RH BI-XENON HEADLIGHT	2,631.15	1.00		2,631.15

### # SUPPLEMENTARY ITEMS

Total Labour :	4,745.00
Total Parts :	4,907.50
Total Labour & Parts :	9,652.50
Deduction for Excess :	
Total Repair Costs less Excess:	9,652.50
GST @7%:	675.68
Grand Total :	10,328.18

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	0957G
<b>Vehicle Details</b>	
Vehicle No.:	SFS906R
Vehicle to be Exported:	No
Intended De-registration Date:	24 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	A4080068N20B20B
Chassis No.:	WBAXG12010DW34274
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$43,538.00
Original Registration Date:	23 Mar 2012
First Registration Date:	23 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$43,538.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2022
PARF Rebate Amount:	\$28,299.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$82,003.00
COE Rebate Amount:	\$32,017.00
<b>Total Rebate Amount:</b>	<b>\$60,316.00</b>

The information contained herein is correct as at 24 Apr 2018

OK



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

**SGCARMART CONNECT**  
BUYING SELLERS & BUYERS

bmw 520 Price Range Depreciation 2012 Vehicle Type Search Advanced Search

Home » Used Cars » Direct Owners » BMW 5 Series 520i

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle

**BRAND NEW**

MORE THAN 750 FLEET UNIT

87000000 88000000 89000000 90000000

CURREN



CLEAR

-9

ON ALL



Compare

BMW 5 Series 520i

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$80,000
Depreciation	\$15,120 /yr View models with similar depreciation
Reg Date	09-Mar-2012 (3yrs 10mths 12days COE left)
Manufactured	2011
Mileage	-
Transmission	Auto
Engine Cap	1,997 cc
Road Tax	\$1,210 /yr
Power	135.0 kW (181 bhp) View specs of the BMW 5 Series Sedan (2010-2017)
Curb Weight	1,610 kg
Features	SRS Airbags, 8 Speed Transmission With Sports Paddle Shift, Traction Control, Keyless Engine Start/Stop, Selectable Sports Or Normal Mode.
Accessories	CD Audio With GPS And Bluetooth, Reverse Camera, Parking Sensors, Auto Light Sensors, Keyless Entry/Start, Day Running Lights.
Description	PML Unit, Beautiful Black Unit With Tip Top Condition On Both Exterior And Interior, Well Maintained And Taken Care. Always Park Under The Shelter.
COE	\$78,000
OMV	\$42,816
ARF	\$42,816
Dereg Value	\$58,047 as of today (change)
No. of Owners	1
Type of Veh	Luxury Sedan
Category	PARF Car, Direct Owner Sale
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 29-Mar-2018 | Last Updated on: 15-Apr-2018  
Tags: BMW 520i, 2012 BMW 520i, BMW, 520i, Used BMW

Upfront Payment

» more Financial Info

Transfer Fee \$25



Seller Information

Contact Person(s) Vincent Ong  
Contact No. 81233365  
Enquiry ☐ Contact Seller

**USEFUL FORMS**

- » Indemnity form
- » Receipt
- » M01
- » Sales agreement
- » Hand-over form

Instructions on how to complete a seller to end-consumer deal  
Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Make sure of this car condition with STA Evaluation.  
Vehicle Evaluation

View Received Message

This mail is associated with :

**\*SFS906R (MCT18040277)  
[SHD3071J]**

TP  
TAN CHEE KIONG  
Apr 10 2018 5:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 21/08/2018 12:31 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10828.18) - SFS906R - Claim Handler: Zuhaidah Bte Samsuri

Approved:10828.18.

<b>DOCUMENTS SUMMARY</b>
There are no documents.



W

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref:

Our Ref:

Date: 11 July 2018

Subject: **ACCIDENT INVOLVING VEHICLES SFS906R & SHD3071J ON 10.04.2018**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 10328.18
Loss of use	: S\$ 500.00 (S\$ 100.00 x 5 days )
Total	: S\$ 10828.18

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors  
Limited  
1600-Cali-BMW  
(1800-2255-2639)

www.pml.com.sg

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales  
6319 0527  
Fax 6479 6624

280  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales  
6319 0668  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.  
107401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

**Teng Wai Khan**  
Customer Service Manager, Body & Paint

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SFS 906 R & SHD 307 J ON 10/4/18.

I, Tan Chee Kiong owner of Vehicle Registration No. SFS 906 R hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: Tan Chee Kiong (Date) 11/4/18  
NRIC No.: 570409576

In the presence of:



Name: \_\_\_\_\_ (Date) \_\_\_\_\_  
NRIC No.: \_\_\_\_\_



In service since 1987

INTERNATIONAL INSURANCE PTE LTD

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III - Direct Settlement (PODS)

India Ref: MLT1914077  
Claimant Ref: SFS 906R

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 10,328.18 (repair cost), S\$ 500.00 (loss of Use rental), S\$ NIL (search fee), vehicle no. SFS 906R that was damaged pursuant to the accident which occurred on 10/4/18 (date) at Jellicoe Road (location) involving vehicle no. SHD 30717 (insured vehicle). This is pursuant to the inspection conducted on 23/4/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tan Chee Kiong ("the third party claimant") of vehicle no. SFS 906R to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SFS 906R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 10,828.18 to Performance Motors Limited

Dated this 21 day of 8 2018.

#### CLAIMANT:

Signature:

Signed by "the workshop"  
(with chop)

Name:

Address:

#### WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

Address:

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |  
S(408933)



INDIA INTERNATIONAL INSURANCE PTE LTD

CO. REG. NO.: 198703792K

64 CECIL STREET #04/#05/#06-02 IOB BUILDING SINGAPORE 049711 TEL: 6347 6100 FAX: 6224 4174 • 6225 7743 WEB: www.ii.com.sg

POSTAL ADDRESS: ROBINSON ROAD P.O. BOX NO. 738 SINGAPORE 901458

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401553W GST Reg. No M2-0020081-X

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

289, Kampong Arang Road  
East Coast Centre  
Singapore 439180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. : B1 1261710

Date IN : 23/04/2018

Cust. Svc. Advisor: Gary Poh Chai Hoon

Page No. : 1 of 2

Invoice Number : 1979502 / WSB

Invoice Date : 26/06/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

### - CUSTOMER INFORMATION -

Mr Tan Chee Kiong  
161A Punggol Central  
#05-81

Singapore 821161

### - INVOICE TO - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS906R	DW34274	23/03/2012	520IA	107156

### ----- LABOUR 1 -----

To replace front bumper and front right fender including  
to remove and install body parts in order to carry out  
painting job.

To respray front bumper and front right fender.

To carry out body cavity preservation.

To replace right Bi-Xenon headlight including program  
and conduct tests for proper function.

To remove and install front right wheel rim including  
balancing.

To check steering geometry and conduct wheel alignment  
according to BMW specification

To check electrical wiring systems at the front section  
for proper function including adjustments of headlights.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 10.4.2018. 3RD PARTY CAR : SHD3071J.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO  
CONSULTANTS PTE LTD ON 23.4.2018 AT 11.50 AM.  
AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON  
17.4.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X5. THE AMOUNT IS SUBJECTED  
TO INSURANCE COMPANY CONFIRMATION.

NETT  
1,700.00

1,730.00

100.00

451.00

83.00

451.00

150.00

80.00

0.00

0.00

Total Labour 1: **4,745.00**

### ----- PARTS -----

FRT RH FENDER

FRT BUMPER TRIM PRIMED (PDC)

BMW EMBLEM

RH BI-XENON HEADLIGHT

HEADLIGHT GASKET SET

RIVET

FRT RH 1 SIDE PANEL BRACKET

Qty	Retail Price
1	863.35
1	1,277.55
1	69.50
1	2,631.15
1	31.55
5	0.45
1	32.15

NETT

863.35

1,277.55

69.50

2,631.15

31.55

2.25

32.15



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438100  
Tel. 63190888 (AfterSales)  
Fax. 62449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1261710	Page No. : 2 of 2
Date IN : 23/04/2018	Invoice Number : 1979502 / WSB
Cust. Svc. Advisor: Gary Poh Chai Hoon	Invoice Date : 26/06/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Total Parts : 4,907.50

Labour Charges : 4,665.00	Total Labour & Parts Charges : S\$ 9,652.50
Parts Charges : 4,907.50	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 9,652.50
	GST @ 7% : S\$ 675.68
	Invoice Total Amount Include GST : S\$ 10,328.18

Computer generated invoice. No signature is required. Amount Payable Include GST : S\$ 10,328.18

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING




































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Apr 2018 <a href="#">Edit Reg</a>		23 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$9,652.50</b> <a href="#">Edit Estimates</a>	<b>S\$9,652.50</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>TAN CHEE KIONG</b> , ID: S7040957G								
Vehicle Reg. No.:	<b>SFS906R</b>	Date of Loss:	10/04/2018 17:00 - :59 [72 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18040277</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHD3071J</b>	Policy No. (Claimant):	B27306295SMP						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Zuhaidah Bte Samsuri</b> - 6347 6070]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 23/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (21/08/2018): Alert - Adj Mandate Approved (S\$10828.18) - SFS906R - Claim Handler: Zuhaidah Bt...</li> <li>III_SG (17/08/2018): Alert - Adj Mandate Maintained - SFS906R - Claim Handler: Zuhaidah Bte Samsuri</li> <li>III_SG (17/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SFS906R - Claim Handler: Zuhaidah Bte Sa...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SFS906R (MCT18040277)  
[SHD30713]  
TP  
TAN CHEE KIONG  
Apr 10 2018 5:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
2	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
3	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
13	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
14	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
15	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
16	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
17	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
18	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
19	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
20	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
21	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
22	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
23	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
24	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
25	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
26	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
27	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
28	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
29	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
30	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
31	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
32	16/08/18 16:43	General View		Load JPG	<input checked="" type="checkbox"/>					
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	12/04/18 18:01	TP ESTIMATE		Load PDF						
2	12/04/18 18:01	TP GIA REPORT		Load PDF						
3	24/04/18 18:31	TP ESTIMATE- MARKED		Load PDF						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	20/08/18 11:19	LOD	 Load PDF	
5	29/08/18 10:20	WORKSHOP INVOICE	 Load PDF	
6	29/08/18 10:20	AUTHORISATION TO ACT FORM	 Load PDF	
7	29/08/18 10:20	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/04/18 08:37	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18006796/T1WB3Q2

Date: 29/08/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SFS906R

Insured Vehicle No: SHD3071J

Date of Loss: 10/04/2018

Nature of Claim: TP

Claim No: MCT18040277

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFS906R

Make & Model: BMW 520i, 2.0 (A)

Reg. Date: 23/03/2012 (Man. Year: 2011)

Colour: Black

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: A4080068N20B20B

Chassis No: WBAXG12010DW34274

Odometer: 107156 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,464.60	4,987.50	2,477.10	33.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,286.50	4,665.00	1,621.50	25.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,751.10</b>	<b>9,652.50</b>	<b>4,098.60</b>	<b>29.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>962.58</b>	<b>675.68</b>	<b>286.90</b>	<b>29.81</b>
<b>Nett Amount (S\$)</b>	<b>14,713.68</b>	<b>10,328.18</b>	<b>4,385.50</b>	<b>29.81</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		<b>500.00</b>		
	<b>Nett Liability (S\$)</b>	<b>10,828.18</b>		

### INSPECTION

Date of Assignment: 23/04/2018

Date Inspected: 23/04/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
<b>Parts:</b> 143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFS906R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 8JX17V SPOKE 236	Repair	881.20 FS	*- FS
3	1		*HUB CAP WITH CHROME DEGE (BMW)	Not Necessary	24.30 FS	*- FS
4	1		*FRT RH FENDER	Bent	863.35 FS	*863.35 FS
5	1		*FRT BUMPER CARRIER	Not Necessary	684.75 FS	*- FS
6	1		*FRT BUMPER TOP IMPACT ABSORBER	Not Necessary	48.00 FS	*- FS
7	1		*FRT BUMPER RH SPACER	Not Necessary	9.45 FS	*- FS
8	1		*FRT BUMPER TRIM PRIMED (PDC)	Deformed	1,277.55 FS	*1,277.55 FS
9	2		*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
10	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
11	1		*RH BI-XENON HEADLIGHT	Cracked	2,631.15 FS	*2,631.15 FS
12	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
13	2		*BUMPER PDC SENSOR (A90 SOPHISTOGRAU)	Not Necessary	737.60 FS	*- FS
14	1		*FRT RH 1 SIDE PANEL BRACKET	Bent	32.15 FS	*32.15 FS
15	5		*RIVET	Necessary	2.25 FS	*2.25 FS
16	1		*SET HEADLIGHT GASKET	Necessary	31.55 FS	*31.55 FS
<b>Total Parts (\$\$)</b>					<b>7,464.60</b>	<b>4,987.50</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER ,RIGHT FRONT FENDER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	2,550.00	1,700.00
2	PAINTING FRONT BUMPER ,RIGHT FRONT FENDER	New	1,923.00	1,730.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REPLACE RIGHT HEADLIGHT INCLUDING PRORAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
5	TO REPLACE RIGHT FRONT RIM INCLUDING BALANCING	New	94.00	83.00
6	TO REPLACE RIGHT FRONT TYRE PIRELLI 225/55/17	New	362.50	0.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTON FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			6,286.50	4,665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >