

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)932 (LOW)
7/5 10am

GST REG. NO : M2 - 0020081 - X

11 APR 2018

E S T I M A T EEstimate No. : b1 46560
Date Estimated : 11/04/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Li Cheng
318B Anchorvale Link
#15-261

Singapore 542318

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM4458B	5H46146	30/03/2017	216d G TOURER	0

DESCRIPTIONTo replace rear bumper including attachments etc and
to knock out dented area caused by accident~~850~~ 1,700.00

To paint rear bumper

~~934~~ 1,038.00To remove and install boot compartment carpet and garnish
to facilitate repairs.~~X~~ 271.00To check electrical wiring systems and lightings at the
rear section for proper function.~~150~~ 177.00

Sundries.

~~?~~ 80.00Total Labour 1: **3,266.00**DESCRIPTIONRR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
REAR BUMPER TRIM STRIP (CHROM)
REAR BUMPER PANEL PRIMED (LINES PDC
REAR BUMPER TOWING FLAP EYE PRIMED
DECOUPING RING PDC TORQUE CONVERTER
Bracket

QTY	PRIC	VALUE
1	60.00	? 60.00
1	60.00	? 60.00
1	423.80	? 423.80
1	59.25	? 59.25
1	65.90	? 65.90
1	65.90	? 65.90
1	105.65	? 105.65
1	966.25	X 966.25
1	41.80	X 41.80
4	5.05	? 20.20
1	35.80	? 35.80

Total Parts : **1,904.55**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46560	Page No. : 2 of 2
Date Estimated	: 11/04/2018	
Prepared By	: Merina Chia San San	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM4458B	5H46146	30/03/2017	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 07/05/18 @ 16:00 Excess \$S _____

Surveyor's Name R. K. K. Sign _____

Surveyor's Tel 95010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	3,266.00
Parts	:	1,904.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	361.94
Grand Total	:	<u>5,532.49</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **