

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875



Date : 11/04/2018
TP Vehicle No. : SFD-3661-E
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : TAN CHENG HONG
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5080254098-01
Vehicle No. : SLD-9997-B
Make & Model : HONDA VEZEL 1.5X A

Accident Date: 11/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE	\$953.30
1	TAILGATE LOCK	\$176.60
1	REAR WINDSCREEN MOULDING	\$280.00
1	EMBLEM LOGO	\$50.70
1	EMBLEM VEZEL	\$52.90
1	RAER BUMPER	\$762.70
1	REAR BUMPER SIDE RETAINER RH	\$51.50
1	REAR BUMPER SIDE RETAINER LH	\$51.50
1	END PANEL	\$465.70
1	END PANEL SMART BUZZER	\$189.50
1	REAR FENDER RH REPAIR	\$0.00
1	REAR FENDER LH REPAIR	\$0.00
Sub Total		\$3,034.40
Discount 20% on Parts		(\$606.88)
		\$2,427.52

Special Nett

1	REVERSE SENSOR	\$250.00
1	REAR WINDSCREEN SEALANT	\$80.00
Sub Total		\$330.00

Labour & Misc

LABOUR TO FACILIATE REPAIR	\$1,000.00
TO SPRAY PAINT ON AFFECTED AREAS	\$1,000.00
TO RUST PROOF AFFECTED AREA	\$80.00
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$50.00
TO REINSTALL REAR WINDSCREEN	\$150.00
Sub Total	\$2,280.00

Sub Total \$5,037.52

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Date : 11/04/2018
TP Vehicle No. : SFD-3661-E
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

Owner : TAN CHENG HONG
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5080254098-01
Vehicle No. : SLD-9997-B
Make & Model : HONDA VEZEL 1.5X A

Accident Date: 11/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	GST 7%	\$352.63	
	Total	\$5,390.15	