



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlomme@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

16/4/18 10:30

**SURVEYOR COPY**

M/S : BILLY ASWIN  
 BLK 443B FAJAR ROAD #17-84

SINGAPORE 672443

ATTN:  
 Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 10/04/2018  
 TP Veh Reg No: SJV4870U

LKL  
 1ccant in

10.30 Am

Estimate No: MC0913000  
 Date: 11 Apr 2018  
 Policy No: PNPV2017-00003123  
 Veh Reg No: SGG6316E  
 Make/Model: HYUNDAI GETZ 1.1 5M

Not Authaiter  
 C/L by B7  
 Presony After Pain

## Estimate Repair Cost to Vehicle No :SGG6316E

3-5/4/18

| Description                                                                                                                                                    | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|---------------|
| <b>SPARE PARTS</b>                                                                                                                                             |          |                   |               |
| 1 HEADLAMP RH                                                                                                                                                  | 1 PC     | 288.40            | —             |
| 2 HEADLAMP LOWER BEAM RH                                                                                                                                       | 1 PC     | 10.20             | X             |
| 3 FRONT BUMPER                                                                                                                                                 | 1 PC     | 303.90            | —             |
| 4 FRONT BUMPER SIDE RETAINER RH                                                                                                                                | 1 PC     | 10.20             | —             |
| 5 FRONT BUMPER CLIPS                                                                                                                                           | 15 PC    | 30.00             | —             |
| 6 FRONT BUMPER PAD                                                                                                                                             | 1 PC     | 25.70             | —             |
| 7 FRONT BUMPER TOW COVER                                                                                                                                       | 1 PC     | 8.00              | X             |
| 8 FRONT BUMPER LOWER AIR GRILLE                                                                                                                                | 1 PC     | 61.90             | X             |
| 9 FRONT BUMPER REINFORCEMENT                                                                                                                                   | 1 PC     | 178.20            | X             |
| 10 FRONT BUMPER SPONGE                                                                                                                                         | 1 PC     | 68.60             | X             |
| 11 FRONT GRILLE                                                                                                                                                | 1 PC     | 16.30             | X             |
| 12 FRONT GRILLE EMBLEM                                                                                                                                         | 1 PC     | 23.30             | X             |
| 13 FRONT GRILLE CHROME MOULDING LH & RH                                                                                                                        | 2 PC     | 51.20             | X             |
| 14 FRONT GRILLE MESH                                                                                                                                           | 1 PC     | 27.50             | X             |
| 15 RADIATOR SUPPORT PANEL                                                                                                                                      | 1 PC     | 718.00            | X             |
| 16 FRONT BUMPER TOP BEAM                                                                                                                                       | 1 PC     | 80.20             | X             |
| Special Nett                                                                                                                                                   | Less 20% | 1,901.60          | 1,521.28      |
| 17 NUMBER PLATE                                                                                                                                                | 1 PC     | 35.00             | X             |
| 18 COOLANT                                                                                                                                                     | 1 PC     | 30.00             | X             |
|                                                                                                                                                                |          | 65.00             | 65.00         |
| <b>LABOUR</b>                                                                                                                                                  |          |                   |               |
| 19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. | 1 PC     | 40.00             | 200           |
| 20 TO REMOVE AND REPLAGE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.                                             | 1 PC     | 100.00            | X             |
| 21 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.    | 1 PC     | 600.00            | 4300          |
| 22 TO SPRAY FRONT BUMPER, FRONT BONNET, FRONT FENDER RH, RADIATOR SUPPORT PANEL                                                                                | 1 PC     | 600.00            | 400           |
|                                                                                                                                                                |          | 1,340.00          | 1,340.00      |

Handwritten signature: *Handwritten signature*  
 E mail: *Handwritten email address*  
 19/4/18 10.00



## AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : BILLY ASWIN  
BLK 443B FAJAR ROAD #17-84  
  
SINGAPORE 672443

Estimate No: MC0913000  
Date: 11 Apr 2018  
Policy No: PNPV2017-00003123  
Veh Reg No: SGG6316E  
Make/Model: HYUNDAI GETZ1.1 5M

ATTN:  
Your Ref No: -  
Claim Type: Third Party  
Accident Date: 10/04/2018  
TP Veh Reg No: SJV4870U

### Estimate Repair Cost to Vehicle No :SGG6316E

| Description | Quantity | List Price           | Amount       |
|-------------|----------|----------------------|--------------|
|             |          | <u>S\$</u>           | <u>S\$</u>   |
|             |          | Total                | S\$ 2,926.28 |
|             |          | Add GST @ 7%         | 204.84       |
|             |          | Total Amount Payable | S\$ 3,131.12 |

TOTAL: SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED THIRTY ONE AND CENTS TWELVE ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

