



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : BILLY ASWIN
BLK 443B FAJAR ROAD #17-84

SINGAPORE 672443

ATTN:

Your Ref No: -

Claim Type: Third Party

Accident Date: 10/04/2018

TP Veh Reg No: SJV4870U

Estimate No: MC0913000

Date: 11 Apr 2018

Policy No: PNPV2017-00003123

Veh Reg No: SGG6316E

Make/Model: HYUNDAI GETZ1.1 5M

*Not Notaire
61 km @ ?
Resony After Rain*

3-5 days

Estimate Repair Cost to Vehicle No :SGG6316E

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	<i>Br</i> 288.40	<i>✓</i>
2 HEADLAMP LOWER BEAM RH	1 PC	10.20	<i>?</i>
3 FRONT BUMPER	1 PC	<i>Br</i> 303.90	<i>✓</i>
4 FRONT BUMPER SIDE RETAINER RH	1 PC	<i>Br</i> 10.20	<i>✓</i>
5 FRONT BUMPER CLIPS	15 PC	<i>Br</i> 30.00	<i>✓</i>
6 FRONT BUMPER PAD	1 PC	<i>Br</i> 25.70	<i>✓</i>
7 FRONT BUMPER TOW COVER	1 PC	<i>Sn</i> 8.00	<i>X</i>
8 FRONT BUMPER LOWER AIR GRILLE	1 PC	<i>Sn</i> 61.90	<i>X</i>
9 FRONT BUMPER REINFORCEMENT	1 PC	178.20	<i>?</i>
10 FRONT BUMPER SPONGE	1 PC	68.60	<i>?</i>
11 FRONT GRILLE	1 PC	<i>Sn</i> 16.30	<i>X</i>
12 FRONT GRILLE EMBLEM	1 PC	<i>Sn</i> 23.30	<i>X</i>
13 FRONT GRILLE CHROME MOULDING LH & RH	2 PC	<i>Sn</i> 51.20	<i>X</i>
14 FRONT GRILLE MESH	1 PC	<i>Sn</i> 27.50	<i>X</i>
15 RADIATOR SUPPORT PANEL	1 PC	718.00	<i>?</i>
16 FRONT BUMPER TOP BEAM	1 PC	80.20	<i>?</i>
		1,901.60	
	Less 20%	380.32	1,521.28
Special Nett			
17 NUMBER PLATE	1 PC	<i>Sn</i> 35.00	<i>X</i>
18 COOLANT	1 PC	30.00	<i>?</i>
		65.00	65.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>200</i>
20 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	<i>?</i>
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	<i>?</i>
22 TO SPRAY FRONT BUMPER, FRONT BONNET, FRONT FENDER RH, RADIATOR SUPPORT PANEL	1 PC	600.00	<i>400</i>
		1,340.00	1,340.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : BILLY ASWIN
BLK 443B FAJAR ROAD #17-84

SINGAPORE 672443

Estimate No: MC0913000
Date: 11 Apr 2018
Policy No: PNPV2017-00003123
Veh Reg No: SGG6316E
Make/Model: HYUNDAI GETZ1.1 5M

ATTN:
Your Ref No: -
Claim Type: Third Party
Accident Date: 10/04/2018
TP Veh Reg No: SJV4870U

Estimate Repair Cost to Vehicle No :SGG6316E

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 2,926.28
		Add GST @ 7%	204.84
		Total Amount Payable	S\$ 3,131.12

TOTAL: SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED THIRTY ONE AND CENTS TWELVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LKK Auto Consultants hence notify the Repairer:

- To resurvey before/after repair
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: