

KIM KEAT MOTOR CO
 Blk 10 Ang Mo Kio Industrial Park 2A
 Avenue 5 #05-34 AMK Autopoint
 Singapore 568047
 Tel:64833167 Fax:64835764

Not Authorized
clump @ ?
Resurvey After Paint
4 days

10 April 2017

AXA Insurance Pte Ltd
 Survey Dept.

Re: Quotation for damaged to FBE4196K

Item	Description of Parts	Qty	Amount	
1.	MirrorRH	1pc	45.00	
2.	Mirror LH	1pc	45.00	
3.	Shield Visor	1pc	85.00	
4.	Cowl Top	1pc	385.00	
5.	Panel LH	1pc	40.00	
6.	Panel RH	1pc	40.00	
7.	Meter Comp.	1Pc	485.00	
8.	Handle Bar LH	1pc	55.00	
9.	Handle Bar RH	1pc	55.00	
10.	Brake Lever	1pc	16.00	
11.	Stay Bracket	1pc	85.00	
12.	Headlamp Assy	1pc	235.00	
13.	Fork Tube L & R	2pcs	280.00	
14.	Lower Case LH	1pc	135.00	
15.	Fork Seal L & R	2set	45.00	
16.	Steering Stem	1pc	155.00	
17.	Steering Bearing Assy	1set	45.00	
18.	Fender Front	1pc	85.00	
19.	Cowl Mid Outer RH	1pc	125.00	
20.	Cowl Mid Inner RH	1pc	165.00	
21.	Signal Lamp Front RH	1pc	45.00	
22.	Cowl Mid Outer LH	1pc	125.00	
23.	Cowl Mid Inner LH	1pc	165.00	
24.	Signal Lamp Front LH	1pc	45.00	
25.	Cowl Inner Front	1pc	85.00	
26.	Cowl Lower LH	1pc	75.00	
27.	Cowl Lower RH	1pc	75.00	
28.	Fuel Tank Assy	1pc	485.00	
29.	Gear Pedal	1pc	65.00	X
30.	Footrest Bar Rear LH	1pc	30.00	X
31.	Side Stand	1pc	45.00	X
			Total	\$ 3846.00
			Less 10%	- 384.60
			Sub-total	\$ 3461.40
Nett Item				
32.	Handle Grip	1pair	35.00	
33.	Volt Meter	1pc	55.00	
34.	Number Plate Front	1pc	10.00	
35.	Fork Oil	1bottle	10.00	
36.	Transport Fee		30.00	
37.	Labour		280.00	200
			Grand Total	\$ 3881.40

LKK Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____