

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

01-12-18

Date Of Accident : 12-04-2018

OUR REF : GY 2779J/T/18

STIB TECHNOLOGIES PTE LTD

Blk 111 North Bridge Road

#27-01

Singapore 179098

Adrian

Nett Value: 6.2K

Date in/out: 12/04/18 04/05/18

TPLCR
Xiao Tony

ESTIMATE BILL ON VEH. NO. : GY 2779I

MODEL : DAIHATSU EXTOL

CHASSIS NO. : JDAS221V001002559

LIST ITEM

Tail Gate	Distorted		790.10	✓
Tail Gate Lock	Twisted		48.40	✓
Tail Gate Lock Motor	new		61.60	+
Tail Gate Lock Striker	Bent		19.80	✓
Tail Gate Lock Cable	new		29.40	+
Tail Gate Weather Stripe	lt		61.80	✓
Tail Gate Stopper	3 new	2pcs @ 9.80	19.60	+
Tail Gate Absorber		2pcs @ 47.40	94.80	+
Tail Gate Outer Garnish	2 bend		47.40	✓
Tail Gate Inner Trim Board	3 new		161.80	+
Tail Gate Inner Trim Board Clips		12pcs @ 2.90	34.80	+
Tail Gate Hinge	new	2pcs @ 31.60	63.20	+
Sticker "Extol"	new		19.80	✓
Tail Lamp Assy	RA cracked	2pcs @ 69.10	138.20	69.10
Tail Lamp Sealant	new	2pcs @ 11.80	23.60	+

Tail Lamp Clips	<i>new</i>	4pcs @ 3.90	15.60 <i>7.80</i>
Tail Lamp Base Panel	<i>RH Distorted</i>	2pcs @ 29.00	58.00 <i>29</i>
Rear Bumper	<i>Distorted</i>		314.60 ✓
Rear Bumper Bracket	<i>Bent</i>	2pcs @ 54.60	109.20 ✓
Rear Bumper Side Attachment	<i>new</i>	2pcs @ 11.80	23.60 ✓
Rear Bumper Tow Cover	<i>behind</i>		28.00 ✓
Rear Bumper Clips	<i>new</i>	8pcs @ 1.80	14.40 ✓
Rear Mudflap - <i>O/S</i>	<i>Distorted</i>		23.80 ✓
Mudflap Clips	<i>new</i>	3pcs @ 1.80	5.40 ✓
Mudflap Bracket	<i>Bent</i>		16.80 ✓
Rear End Panel (Outer)	<i>} Distorted</i>		462.80 ✓
Rear End Panel (Inner)			384.00 ✓
Rear Wiper Motor	<i>new</i>		587.00 ✗
Rear Floor Panel	<i>Distorted</i>		682.00 ✓
Rear Sub Chassis Member	<i>Pyri</i>		547.00 ✗
Rear Fender - RH	<i>Distorted</i>		680.00 ✓
Rear Fender Protector	<i>behind</i>		23.40 ✓
Rear Wheel Housing Panel - RH	<i>Pyri</i>		591.60 ✗
Exhaust Silencer	<i>Pyri</i>		583.20 ✗
Exhaust Silencer Hook	<i>new</i>	2pcs @ 63.90	127.80 ✗
Front Bumper	<i>Pyri</i>		380.00 ✗
Front Bumper Clips	<i>new</i>	10pcs @ 5.00	50.00 <i>30</i>
Tail Gate Green Sticker	<i>new</i>		51.00 <i>25(SN)</i>
Rear Windscreen Glass Rubber	<i>new</i>		281.75 ✓
			7,655.25

4172.95

Less Discount 10%:

765.53

354700

SN. 25

6,889.73

SPECIAL NETT ITEM

Rear Number Plate

Bent

35.00 ✓

Rear Tyre - RH

cut

200

~~190.00~~ 150 (SN)

Front Number Plate

New

35.00 ✗

70 km/h Sticker

New

~~150.00~~ 15**LABOUR CHARGE**

Towing.

~~80.00~~ 60

To Check and Reconnect Snap Wiring.

~~120.00~~ 30

To Tuff Coat Affected Areas.

~~280.00~~ 120

To Remove & Refix Rear Windscreen Glass.

3730

~~180.00~~ 120

To Adjust Chassis Alignment On Car O Liner.

380.00 ✗

To Respray Affected Areas.

~~1,800.00~~ 1400

To Remove & Refix Exhaust Pipe.

120.00 ✗

To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.

~~2,800.00~~ 2000

13,059.73

GST 7%:

914.18

AMOUNT DUE:**13,973.91****LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 7502
4/s 6K
16 Days.