

ASS. REC. BY:

REF: CS/ET118006826/Kvb n2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time:

13042018 11:36am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 966X

Insured:

SKS 830P

at Workshop m/s

Trans Cab

Tel:

6287 6666

of

No. 2 AMK St 63

Policy No:

Claim No:

SKS830P / RH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-04-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 13042018

Person Contacted:

Candy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 966X - X
	SKS 830P - X
16/4/18	Email preli revised to Pei Li

Kenneth

Q

Date:

Vehicle: IN / OUT

A diagram showing a 2x2 grid. The top row contains two triangles pointing downwards. The bottom row contains the labels 'N/S' and 'O/S'. Below the grid is a curved line with an arrow pointing to the right.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14	File pass to Corbett
16/4/18	L12p & 135d (Reel 19, 237.43, 937)

RECEIVED 11 APR 25

TOTAL

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18006826/Kvb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 13-04-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 830P	Veh. Inspected	SHD 9669X
Policy No.		Coverage (\$)	0.00
Claim No.	SKS830P/RH	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/04/2018	Inspection Date	13/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SKS830P/RH

Our ref: CS/EG118006826/Kvb

Date: 16/4/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHD 9669X


We thank you for your instruction on 13/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/4/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$20,587.43
Revised Estimate Amount	: S\$1,350.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 13 April, 2018 11:23 AM
To: 'admin-d@lkkauto.com'
Subject: OI : SKS830P / TP : SHD9699X/LKK / DOA : 11/04/2018
Attachments: SHD9699X - ESTIMATE n SAS.pdf

Dear Ashley,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 9699X	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	CANDY KONG @ 6287 6666	SKS830P/RH	ROHAINI	DOA: 11/04/2018 WP (NR)

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Attached are estimate and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 16 April 2018 2:35 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SKS830P / TP : SHD9699X/LKK / DOA : 11/04/2018
Attachments: PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHD 9669X
Date of survey: 13/4/2018
Number of days:1.5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 13 April 2018 12:04 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: SKS830P / TP : SHD9699X/LKK / DOA : 11/04/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 13 April, 2018 11:23 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SKS830P / TP : SHD9699X/LKK / DOA : 11/04/2018

Dear Ashley,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
----	---------------------	-------------	-------------------	---------	-----	---------

1	SHD 9699X	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	CANDY KONG @ 6287 6666	SKS830P/RH	ROHAINI	DOA: 11/04/2018 WP (NR)
---	-----------	---	---------------------------	------------	---------	----------------------------

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Attached are estimate and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9669X

Vehicle to be Exported: Yes

Intended De-registration Date: 12 Apr 2018

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: Z20S1461097K

Chassis No.: KL1LA69RJBB123352

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,030.00

Original Registration Date: 04 Mar 2013

First Registration Date: 04 Mar 2013

Transfer Count: 0

Actual ARF Paid: \$14,030.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Mar 2021

PARF Rebate Amount: \$9,821.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$67,858.00

COE Rebate Amount: \$24,505.00

Total Rebate Amount: \$34,326.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Apr 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9669X**AAD1804-125***Not Authenticated
C/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9699X

KL1LA69RJB123352

CHEVROLET

EPICA 2.0

11.4.2018

ERGO**PART****LIST**

1	1	Rear Bumper	\$	<i>Avail</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>✓</i> 239.94	X
3	1	Rear Bumper Centre Absorber	\$	<i>✓</i> 260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>✓</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>✓</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>✓</i> 119.74	} X
7	1	Rear Bumper Reflectors LH	\$	<i>✓</i> 119.74	
8	1	Rear Bumper Tow Hook Cover	\$	<i>✓</i> 93.00	
9	1	Rear End Panel Outer	\$	<i>✓</i> 623.76	
10	1	Rear End Panel Inner Trim	\$	<i>✓</i> 263.84	
11	1	Rear Luggage Floor Panel	\$	<i>✓</i> 973.00	
12	1	Rear Luggage Floor Panel Insulator	\$	<i>✓</i> 63.50	
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>✓</i> 378.00	
14	1	Bootlid	\$	<i>✓</i> 973.00	
15	1	Bootlid inner trim board	\$	<i>✓</i> 400.00	
16	1	Bootlid Weatherstrip	\$	<i>✓</i> 344.28	} X
17	1	Bootlid Lock - Top	\$	<i>✓</i> 466.56	
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>✓</i> 120.62	
19	1	Bootlid Logo	\$	<i>✓</i> 138.84	
20	1	Bootlid 'EPICA LT' Badge	\$	<i>✓</i> 119.84	
21	1	Bootlid Reflector Centre	\$	<i>✓</i> 217.97	
22	1	Bootlid Reflector RH	\$	<i>✓</i> 128.40	
23	1	Bootlid Reflector LH	\$	<i>✓</i> 128.40	
24	1	Rear Tail Lamp RH	\$	<i>✓</i> 479.30	
25	1	Rear Tail Lamp LH	\$	<i>✓</i> 479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>✓</i> 1,110.00	} X
27	1	Rear Fender RH	\$	<i>✓</i> 1,145.00	
28	1	Rear Fender Inner Trim RH	\$	<i>✓</i> 418.44	
29	1	Rear Fender LH	\$	<i>✓</i> 1,145.00	

Trans-cab Auto Services Pte Ltd

AAD1804-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9669X

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44	X
----	---	---------------------------	----	------------------	---

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00	X
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00	
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00	} X
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00	
6	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00	
7	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00	
8	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00	
9	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00	
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00	
11	1	Spare Tyre	\$	<i>Sn</i> 180.00	
12	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74	

TOTAL	\$	1,000.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	<i>2001</i> 3,500.00
----	----------------------

To Check Electrical Lighting Concerned.

\$	170.00 <i>101</i>
----	-------------------

To Rust-Proofing Of The Affected Areas.

\$	<i>nn</i> 170.00 X
----	--------------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00 <i>2001</i>
----	----------------------

To reinstall rear bumper parking sensor.

\$	170.00 <i>601</i>
----	-------------------

Trans-cab Auto Services Pte Ltd**AAD1804-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9669X

To transfer of end panel fittings and conduct
water seepage test. \$ *nn* 170.00 X

To transfer of boot fittings and conduct water
seepage test. \$ *nn* 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

To check steering geometry and computer
wheel alignment \$ *nn* 220.00 X

\$ **8,150.00**

TOTAL \$ 20,587.43

Repair Days

10 Days
1 1/2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18006826/Kvbn2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 18-04-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 830P	Veh. Inspected	SHD 9669X
Policy No.		Coverage (\$)	0.00
Claim No.	SKS830P/RH	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB123352	Colour	WHITE / RED
Odometer	464595	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	7 mm
L/H Front Tyre	195/65 R15	GITI	7 mm
R/H Rear Tyre	195/65 R15	GITI	6 mm
L/H Rear Tyre	195/65 R15	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/04/2018	Inspection Date	13/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1.500 Working Days
-------------------------------------	--------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9669X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED / CRACKED	1,202.00	1,202.00
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	68.76	68.76
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	623.76	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	263.84	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	BOOTLID	TO REPAIR SEE LABOUR	973.00	-
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	344.28	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NOT NECESSARY	120.62	-
1	BOOTLID LOGO	NOT NECESSARY	138.84	-
1	BOOTLID "EPICA LT" BADGE	NOT NECESSARY	119.84	-
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-

Report Ref No. CS/EG18006826/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,270.74	-127.08
			11,436.69	1,143.68
	SPECIAL NETT ITEMS			
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,000.74	44.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM,REAR END PANEL OUTER,REAR LUGGAGE FLOOR		3,500.00	200.00
	PANEL,BOOTLID,BOOTLID LOCK-TOP,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH.			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,200.00	200.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00

Report Ref No. CS/EG18006826/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			8,150.00	470.00
GRAND TOTAL			20,587.43	1,657.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CS/EG18006826/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.