

23/03/2003

ASS. REC. BY:

REF:

CS / SMD18006829 / Kad3⁷²

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMD

Date/Time: 13042018 11:04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 1954T

Insured:

at Workshop m/s

Cheng Hoe Motor

Tel: 6481 2001

of

Blk 10 Amk Ind Park 2A #D1-04

Policy No:

Claim No:

CMTD180544 / THE

Sum Insured:

Excess:

\$250.00

Make of Veh:

D.O.A. 08042018

(Client's Record)

CA

/ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13042018 11:17am

Person Contacted:

Dorlyn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 1954T - X
	Revert Am email

ASS. REC. BY:

REF: Som /

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 873k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 1954TYr Regn: 0216Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hando Vezelc.c. 1896Colour: M. P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 15764

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI

1106P75

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 215/80R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 8/4/18D.O.I. 13/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/4 File pass to Customer11/3 83056.60 Car frame & body (Red 1954T, 672)

RECEIVED 12 MAR 2019

12/3/2019

Data/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: ODLump Sum / (B.I.) (\$ 3056.60)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18006829/Krb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 13-04-2018



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLA 1954T
Policy No.	Coverage (\$)	0.00
Claim No. CMTD1801544/THE	Excess (\$)	250.00
Assign From GRACE TEO	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 08/04/2018	Inspection Date 13/04/2018
Survey held at CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047	

5a. Remarks


A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Your Ref: CMTD1801544/THEDate: 16 April 2018Our Ref: CS/SMO18006829/KrbThe Motor Claims Department
SOMPO INSURANCE COMPANY PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLA 1954T .We thank you for the instruction on 13/04/2018Please be informed that we had conducted the inspection of the abovementioned vehicle 13/04/2018 at the premises of m/s: CHENG HOE MOTOR PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$ <u>3,251.60</u> .
Revised Estimate Amount	: S\$ <u>2,927.10</u> .
"Check" Items (Estimated)	: S\$ <u> </u> .
Total Repair Amount	: S\$ <u>2,927.10</u> .
Pre-Accident Value	: S\$ <u>73,000.00</u> .
COE/PARF value	: S\$ <u>41,344.00</u> .
Nett Value	: S\$ <u>31,656.00</u> .

Description of Damage:
The vehicle sustained damages
at the front n/s portion.
We have authorize repair.Yours faithfully
KENNETH
Automotive Assessor

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 13 April, 2018 11:04 AM
To: CHENG HOE MOTOR PTE LTD (AMK); CHENG HOE MOTOR PTE LTD (HQ); admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma
Subject: CMTD1801544/THE - SLA1954T(OD) ACC ON 08/04/2018
Attachments: ESTIMATE.PDF; IC.JPG; SLA1954T OD SOMPO DOA 08042018.pdf

Our Claim Reference : CMTD1801544/THE

Hi Dorlyn,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Authorisation will be further advised upon survey.

Excess - \$250.00

Aside to **LKK AUTO**,

Please assist to conduct motor survey on Own Damage basis as repair estimate attached.

Please revert with your preliminary report upon completion of survey to my colleague, Thelma Choo.

Authorise if consistent.

Excess applicable – \$250.00

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sampo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: CHENG HOE MOTOR PTE LTD (AMK) [<mailto:chmamk@singnet.com>]
Sent: Thursday, April 12, 2018 3:22 PM
To: Henry, Irene James; Claims - Motor Survey; CHENG HOE MOTOR PTE LTD (HQ)
Subject: ARRANGE OD SURVEY FOR SLA1954T (DOA: 08/04/2018)

Hi,

Kindly help out to arrange for surveyor to survey your insured vehicle
SLA1954T traffic accident on 08/4/2018.

Quotation & relevant documents as per attach.

Thank you.

Rgds,
Dorlyn Li (Ms)
CHENG HOE MOTOR PTE LTD (AMK)
No. 10 Ang Mo Kio Ind Park 2A
#01-04
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6481 2001
Fax : 6482 1296
Email : chmamk@singnet.com

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, April 16, 2018 3:41 PM
To: 'Teo, Grace'; 'Choo, Thelma'
Cc: SUR
Subject: RE: CMTD1801544/THE - SLA1954T(OD) ACC ON 08/04/2018
Attachments: SLA 1954T OD.pdf

Dear Thelma,

Enclosed preliminary revised for **SLA 1954T**.
Repair day : 4 Days

We have authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, April 13, 2018 11:19 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801544/THE - SLA1954T(OD) ACC ON 08/04/2018

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Friday, 13 April, 2018 11:04 AM
To: CHENG HOE MOTOR PTE LTD (AMK) <chmamk@singnet.com>; CHENG HOE MOTOR PTE LTD (HQ) <chmotor@singnet.com>; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>
Subject: CMTD1801544/THE - SLA1954T(OD) ACC ON 08/04/2018

Our Claim Reference : CMTD1801544/THE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7961G
Vehicle Details	
Vehicle No.:	SLA1954T
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4026979
Chassis No.:	RU11106975
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,977.00
Original Registration Date:	24 Feb 2016
First Registration Date:	24 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$9,977.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2026
PARF Rebate Amount:	\$7,482.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$33,862.00
Total Rebate Amount:	\$41,344.00

The information contained herein is correct as at 09 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 11:40
Date Of Accident	08/04/2018 18:30
Exact Location Of Accident	VIVO CITY CARPARK LEVEL 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA1954T
Insured/Policyholder	
Name Of Registered Owner	ZHENG LIJUN
NRIC No	S8677961G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96218620
Alternative Phone No	OTHERS-96218620

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01002296
Cover Note Number	24/02/2018 - 23/02/2019

Driver

Name of Driver	ZHENG LIJUN
NRIC No	S8677961G
Date Of Birth	26/07/1986
Occupation	INDOOR
Date Of Driving Pass	28/07/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96218620
Fax Number	
Contact Number	OTHERS-96218620
Email Address	NOEMAIL

Address	BLK 8A BOON TIONG RD #19-77
Postcode	164008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG THE PATHWAY WHEREBY MOTOR CAR SLJ7077M HAD MADE A SUDDEN REVERSE INFRONT OF MY VEHICLE. AS SUCH, HIS VEHICLE REAR RH PORTION HAD COLLIDED ONTO THE FRONT LH PORTION OF MY VEHICLE. (I WISH TO STATE THAT I FELT PAIN ON MY RH ELBOW ON THIS MORNING AND WILL SEEK FOR MEDICAL TREATMENT LATER ON).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ7077M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

A: SLA1954T
(w/ 2 passengers:
1) Graham Lee - M
2) Vivvilee - F)

B: SLJ 7077M

Location: Vivo City Carpark
level 4



Vehicle No: SLA 19547 (sonaps)
Date & Time: 08/04/2018 @ 1830 (upadny)
I was driving along the pathway whereby motor car SLJ7077M had made a sudden reverse in front of my vehicle. As such, his vehicle rear RH portion had collided onto the front LH portion of my vehicle.
(I wish to state that i felt pain on my RH elbow on this morning and will seek for medical treatment later on.)
Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time: 1/12/2014

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

01/2017, SkanskaPlanForm_V3 () Claim Own Policy (x) Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

SKETCH PLAN


VEHICLE NO.: SLA1954T
INSURER: Jompo
DATE & TIME: 08/04/18 @ 1830

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:

9-4-2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Danyan (AMK) 0910418

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO 201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555 FAX: 62213302
 ATTN: Motor Claim Department

Claim No: ES1890383
 Estimate No: ES1890383/AMK
 Date: 12 Apr 2018
 Policy No: D18MTPV01002296
 Veh Reg No: SLA1954T
 Make/Model: HONDA VEZEL 1.5X
 CVT
 Chassis No: RU11106975
 Engine No: L15B4026979
 Reg. Date: 24/02/2016

WS Ref: OD/SOMPO/AMK
 Claim Type: Own Damage
 Accident Date: 08/04/2018

Estimate Repair Cost to Vehicle No : SLA1954T

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 FRONT BUMPER	240.00	1 PC	240.00	✓
2 FRONT BUMPER REINFORCEMENT	195.00	1 PC	195.00	✓
3 FRONT BUMPER LOWER SPOILER	140.00	1 PC	140.00	✓
4 FRONT BUMPER LH FOG LAMP COVER	22.00	1 PC	22.00	✓
5 FRONT BUMPER LH SIDE RETAINER	15.00	1 PC	15.00	✓
6 FRONT BUMPER CLIP	2.00	5 PC	10.00	✓
7 FRONT BUMPER CENTRE LOWER GRILLE	55.00	1 PC	55.00	✓
8 FRONT OUTER TEMPERATURE SENSOR BRACKET	14.00	1 PC	14.00	✓
9 HEADLAMP LH	840.00	1 PC	840.00	✓
10 HEADLAMP LH LOWER BRACKET	28.00	1 PC	28.00	✓
11 FRONT GRILLE HOUSING	195.00	1 PC	195.00	✓
12 FRONT GRILLE OUTER GARNISH	150.00	1 PC	150.00	✓
13 FRONT GRILLE CHROME	28.00	2 PC	56.00	✓
14 FRONT GRILLE LOGO	18.00	1 PC	18.00	✓
15 RADIATOR LH SIDE GARNISH	28.00	1 PC	28.00	✓
			2,006.00	
	Add 10%		200.60	2,206.60
Labour				
16 REMOVE & REFIX FRT BUMPER & LOWER SPOILER, GRILLE, LH HEADLAMP; KNOCKING & REPAIR FRT LH FENDER & REALIGN THE SAME	450.00	1 LA	450.00	400
17 PUTTY & RESPRAY FRT BUMPER & REINFORCEMENT, FRT LH FENDER & ALL AFFECTED AREAS	500.00	1 LA	500.00	450
			950.00	
	Add 10%		95.00	1,045.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Authorised
 I.B.I
 Repairing B4 paint
 EX 2501
 4 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 **FAX:** 62213302
ATTN: Motor Claim Department

WS Ref: OD/SOMPO/AMK
Claim Type: Own Damage
Accident Date: 08/04/2018

Claim No: ES1890383
Estimate No: ES1890383/AMK
Date: 12 Apr 2018
Policy No: D18MTPV01002296
Veh Reg No: SLA1954T
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11106975
Engine No: L15B4026979
Reg. Date: 24/02/2016

Estimate Repair Cost to Vehicle No : SLA1954T

3156.60

Total	S\$ 3,251.60
Add GST @ 7%	227.61
Total Amount payable	S\$ 3,479.21

VEHICLE LYING AT:
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408711

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG HOE MOTOR PTE LTD

BLK 10 #01-04

ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296

ATTN : WEI LING/DORLYN

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201804-07604

DATE : 13/04/2018

CUSTOMER ID : CHE002

VEH REG. NO. : SLD1954T

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H71101-T7J-H00ZZ	FR BUMPER	U1	1	240.00	240.00
			HI.1-C5			
2	H71130-T7A-000ZZ	REINFORCEMENT FR	U1	1	195.00	195.00
	RU1		HI.1-H9			
3	H71102-T7W-A00	FR BUMPER LOWER	U1	1	140.00	140.00
	RU1		HI.2-F12			
4	H71106-T7J-H00	FOG GARNISH L.H	U1	1	22.00	22.00
			HI.2-H9-B			
5	H71198-T7A-000	SPACER FR L.H	U1	1	15.00	15.00
	RU1		HI.2-G8-A			
6	H91505-TM8-003	CLIPS	U1	5	2.00	10.00
	GM2		HI.2-D13-37			
7	H71103-T7J-H00	BUMPER LOWER GRILLE	U1	1	55.00	55.00
			HI.1-B5-D			
8	H91555-T7A-J01	CLIP, AMBIENT SENSOR BRACKET	U1	1	14.00	14.00
			I.2-M47-D			
9	H33150-T7S-E11	HEAD LAMP L.H	U1	1	840.00	840.00
	HRV-RU1		HI.1-D2			
10	H71190-T7A-000	BRACKET, L. FR BUMPER	U1	1	28.00	28.00
	RU1		HI.2-G9-B			
11	H71121-T7A-000	FR GRILLE	U1	1	195.00	195.00
	RU1		HI.1-C3			
12	H71122-T7A-000	GRILLE OUTER GARNISH	U1	1	150.00	150.00
	RU1		HI.1-D5			
13	H71123-T8N-T00/50	FR GRILLE CHROME RH	U1	1	28.00	28.00
			HI.2-G8-G			
14	H71128-T8N-T00	FR GRILLE CHROME L.H	U1	1	28.00	28.00
			HI.2-G8-G			
15	H75700-TA0-A00	"H" EMBLEM	U1	1	18.00	18.00
	RU1		I.2-M34			
16	H71116-T7A-000	AIR GUIDE L.H FRT BU	U1	1	28.00	28.00
	RU1		HI.2-F3-C			

CONTINUE NEXT PAGE

ORIGINAL

[Handwritten signature]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18006829/Kcd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 13-03-2019



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLA 1954T
Policy No.	D18MTPV01002296	Coverage (\$)	0.00
Claim No.	CMTD1801544/THE	Excess (\$)	250.00
Assign From	GRACE TEO	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11106975	Colour	M.P. WHITE
Odometer	15764	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/04/2018	Inspection Date	13/04/2018
Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047		

5a. Remarks

A)THE MARKET VALUE IS S\$73,000.00 (EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1954T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP)	BUCKLED / CRACKED	240.00	240.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	195.00	195.00
1	FRONT BUMPER LOWER SPOILER (WCP)	CRACKED	140.00	140.00
1	FRONT BUMPER LH FOG LAMP COVER (WCP)	DENTED	22.00	22.00
1	FRONT BUMPER LH SIDE RETAINER (WCP)	DISTORTED	15.00	15.00
5	FRONT BUMPER CLIP @\$2.00 (WCP)	NECESSARY	10.00	10.00
1	FRONT BUMPER CENTRE LOWER GRILLE (WCP)	DENTED	55.00	55.00
1	FRONT OUTER TEMPERATURE SENSOR BRACKET (WCP)	CRACKED	14.00	14.00
1	HEADLAMP LH (WCP)	MTG CRACKED	840.00	840.00
1	HEADLAMP LH LOWER BRACKET (WCP)	CRACKED	28.00	28.00
1	FRONT GRILLE HOUSING (WCP)	DENTED	195.00	195.00
1	FRONT GRILLE OUTER GARNISH (WCP)	CRACKED	150.00	150.00
2	FRONT GRILLE CHROME @\$28.00 (WCP)	NECESSARY	56.00	56.00
1	FRONT GRILLE LOGO (WCP)	NECESSARY	18.00	18.00
1	RADIATOR LH SIDE GARNISH (WCP)	CRACKED	28.00	28.00
	COST PLUS 10%		200.60	200.60
			2,206.60	2,206.60
LABOUR				
	REMOVE & REFIX FRT BUMPER & LOWER SPOILER,GRILLE,LH HEADLAMP;KNOCKING & REPAIR FRT LH FENDER & REALIGN THE SAME.		450.00	400.00
	PUTTY & RESPRAY FRT BUMPER & REINFORCEMENT,FRT LH FENDER & ALL AFFECTED AREAS.		500.00	450.00
			950.00	850.00
GRAND TOTAL			3,156.60	3,056.60
RECOMMENDED COST OF REPAIRS				3,056.60
LESS EXCESS				-250.00
NETT LIABILITY				2,806.60

Report Ref No. CS/SMO18006829/Kcd3n2

KSC
KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.