

ASS. REC. BY:

REF: CS / FCU 8006834 / Rlvbnz

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

CWS Joanne Yong

of

FCL

Date/Time:

22/04/2018 3:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 7878T

Insured:

SHA 4717P

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Rd

Policy No:

Claim No:

D18002841MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10042018

CA / REV / REP. / REV 24 HRS DS

02-03-2018

H.O.D. Endorsement:

Date/Time:

13/04/2018 11:04am

Person Contacted:

Caroline

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate | Kevin |
|-----------|--|-------------|
| | SKQ 7878T - X | |
| | SHA 4717P - C13/AXA11025237/Hedcl | Def: 061211 |
| 3/5/18 | Email preli revised to FCI | |
| 22/5/18 | Final fig \$ 3220.30 (Red 2514.90, 447) confirmed by email | |

052 sent 22/05/18



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002841MFSH
Our Ref: CS/FCI18006834/R1vb

Date : 3/5/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKQ 7878T


We thank you for your instruction on 22/4/2018

Please be informed that we had conducted the inspection of the above mentioned
2/5/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED
and have the following to report:-

| | |
|--------------------------|---------------|
| Workshop Estimate Amount | : S\$5,665.70 |
| Revised Estimate Amount | : S\$1,987.05 |
| "Check" Items Amount | : S\$882.20 |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ |
| Nett Value | : S\$ |

Description of Damage:

The vehicle sustained damages at the
n/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|--|--------------------------------------|
| Date | 11-04-2018 | Our Ref No. D18002841MFSH |
| Accident Date | 10-04-2018 | Claim Type. Third Party |
| Insured Vehicle | SHA4717P | Third Party Vehicle. SKQ7878T |
| Survey Location | 303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE | |
| Contact Person. | CAROLINE | |
| Contact No. | 63190174/0 | Fax No. 64794601 |
| Survey Type | DIRECT SETTLEMENT: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|-------------------------------|--------------------------------|
| Cc : Workshop | PERFORMANCE MOTORS LIMITED | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | JOANNEY | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 3 May 2018 12:26 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002841MFSH/1, SKQ 7878T
Attachments: SKQ 7878T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKQ 7878T
Date of survey: 2/5/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 13 April 2018 11:07 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002841MFSH/1

Dear Sir / Madam,

Thank you for your email.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 April, 2018 3:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002841MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 22 May 2018 10:27 AM
To: PBSP; Rasul (LKKAuto)
Cc: SUR
Subject: RE: FINAL REPORT / SKQ7878T

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$3,220.30 before GST

Repair days: 3 days

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 18 May 2018 5:26 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: FINAL REPORT / SKQ7878T

Dear Caroline,

Please provides us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Friday, 18 May 2018 5:06 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKQ7878T

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,206.30

Total Labour & Parts : 3,220.30

Repair days: 3

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401959W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

11 APR 2018

| | |
|-----------------------------------|-------------------|
| Estimate No. : b1 46547 | Page No. : 1 of 2 |
| Date Estimated : 10/04/2018 | |
| Prepared By : Kevin Leong Wai Kit | |

| | |
|---|--|
| - ESTIMATE REPAIR FOR - Tan Li Xin, Zeena 6A Denham Close Singapore 589553 | - ACCOUNT - 40000 Cash Sales - Service Singapore |
|---|--|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|---------|---------|
| SKQ7878T | V886095 | 24/08/2017 | 218iA/2 | 0 |

| DESCRIPTION | VALUE |
|---|---------------------------------|
| To replace front bumper, front left fog lamp trim & all attachments cause by accident | ✓ 850 2,550.00 |
| Painting on front bumper assembly | ✓ 934 1,038.00 |
| To check electrical wiring systems at the front section for proper function. | ✓ 150 177.00 |
| Sundries. | ✓ ? 80.00 <i>new</i> |

Total Labour 1: 3,845.00

| DESCRIPTION | QTY | PRIC | VALUE |
|-------------------------------------|-----|--------|--------|
| FRT BUMPER TOP MOUNT | 1 | 361.65 | 361.65 |
| FRT LH LOWER DEFORMATION ELEMENT | 1 | 82.65 | 82.65 |
| GRILLE AIR INLET MIDDLE | 1 | 130.95 | 130.95 |
| FRT SHOCK ABSORBER | 1 | 50.15 | 50.15 |
| CLOSED GRID LH (SPORT) | 1 | 126.25 | 126.25 |
| FRT BUMPER PANEL PRIMED SRA (SPORT) | 1 | 927.45 | 927.45 |
| SET MOUNTING PDC/PMA SENSOR FRT | 1 | 30.35 | 30.35 |
| LH COVER SPRAY NOZZLE PRIMED | 1 | 38.00 | 38.00 |
| DECOUPLING RING PDC TORQUE CONVERTE | 4 | 5.05 | 20.20 |
| (DG/SL) ADHESIVE SET K6 | 1 | 53.05 | 53.05 |

Total Parts : 1,820.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197481559K GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

| | |
|-----------------------------------|-------------------|
| Estimate No. : b1 46547 | Page No. : 2 of 2 |
| Date Estimated : 10/04/2018 | |
| Prepared By : Kevin Leong Wai Kit | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|---------|---------|
| SKQ7878T | V886095 | 24/08/2017 | 218iA/2 | 0 |

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 02/05/18 @ 16:20 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Title _____

RESURVEY PARTS PHOTO BY SUPERVISOR Yes / No _____ F/M/L Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

| | | |
|--------------------|---|-----------------|
| | | 5735.20 |
| Labour 1 | : | 3,845.00 |
| Parts | : | 1,820.70 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 396.60 |
| Grand Total | : | 6,062.30 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46547
Date Estimated : 10/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tan Li Xin, Zeena
6A Denham Close

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 589553

| REGN NO | CHASS S NO | REGN DATE | MODEL | M LEAGE |
|---|----------------|------------|---------|---------|
| SKQ7878T | V886095 | 24/08/2017 | 218iA/2 | 0 |
| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT | |
| To replace front bumper and attachments include knocking out dents caused by the accident | 850.00 | | 850.00 | |
| To spray paint front bumper | 934.00 | | 934.00 | |
| To check electrical wiring systems at the front section for proper function. | 150.00 | | 150.00 | |
| Sundries. | 80.00 | | 80.00 | |

| DESCRIPTION | INIT PRICE | QTY | DISC. % | NETT |
|-------------------------------------|------------|------|---------|--------|
| CLOSED GRID LH (SPORT) | 126.25 | 1.00 | | 126.25 |
| FRT BUMPER PANEL PRIMED SRA (SPORT) | 927.45 | 1.00 | | 927.45 |
| SET MOUNTING PDC/PMA SENSOR FRT | 30.05 | 1.00 | | 30.05 |
| # PLAQUE 82MM * | 69.50 | 1.00 | | 69.50 |
| (DG/SL) ADHESIVE SET K6 | 53.05 | 1.00 | | 53.05 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|----------|
| Total Labour : | 2,014.00 |
| Total Parts : | 1,206.30 |
| Total Labour & Parts : | 3,220.30 |
| Deduction for Excess : | |
| Total Repair Costs less Excess: | 3,220.30 |
| GST @7%: | 225.42 |
| Grand Total : | 3,445.72 |

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46547
Date Estimated : 10/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tan Li Xin, Zeena
6A Denham Close

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 589553

| REGN NO | CHASSIS NO | REGN DATE | MODEL | M LEAGE |
|-------------|----------------|------------|---------|---------|
| SKQ7878T | V886095 | 24/08/2017 | 218iA/2 | 0 |
| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT | |

| DESCRIPTION | INIT PRICE | QTY | DISC. % | NETT |
|-----------------|------------|------|---------|-----------------|
| # PLAQUE 82MM * | 69.50 | 1.00 | | 69.50 <i>ML</i> |

| | |
|------------------------|-------|
| Total Labour : | |
| Total Parts : | 69.50 |
| Total Labour & Parts : | 69.50 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|-----------------------------|---|
| FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI18006834/R1vbn2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 24-05-2018 |  |
| | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHA 4717P | Veh. Inspected | SKQ 7878T |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | D18002841MFSH | Excess (\$) | 0.00 |
| Assign From | JOANNE YONG | Assign Date | 12/04/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | BMW 218I COUPE | c.c | 1499 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | WBA2F12010V886095 | Colour | RED |
| Odometer | 3481 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 225/45 R17 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 225/45 R17 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 225/45 R17 | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 225/45 R17 | BRIDGESTONE | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 10/04/2018 | Inspection Date | 02/05/2018 |
| Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |
| 5a. Remarks | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7878T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRT BUMPER TOP MOUNT (SN) | SERVICEABLE | 361.65 | - |
| 1 | FRT LH LOWER DEFORMATION ELEMENT (SN) | SERVICEABLE | 82.65 | - |
| 1 | GRILLE AIR INLET MIDDLE (SN) | SERVICEABLE | 130.95 | - |
| 1 | FRT SHOCK ABSORBER (SN) | SERVICEABLE | 50.15 | - |
| 1 | CLOSED GRID LH (SPORT)(SN) | SCRATCHED | 126.25 | 126.25 |
| 1 | FRT BUMPER PANEL PRIMED SRA (SPORT)(SN) | DEFORMED | 927.45 | 927.45 |
| 1 | SET MOUNTING PDC/PMA SENSOR FRT (SN) | NECESSARY | 30.35 | 30.05 |
| 1 | LH COVER SPRAY NOZZLE PRIMED (SN) | NOT NECESSARY | 38.00 | - |
| 4 | DECOUPLING RING PDC TORQUE CONVERTE (SN) | NOT NECESSARY | 20.20 | - |
| 1 | (DG/SL) ADHESIVE SET K6 (SN) | NECESSARY | 53.05 | 53.05 |
| 1 | PLAQUE 82MM (ADDITIONAL)(SN) | NECESSARY | 69.50 | 69.50 |
| 1 | SUNDRIES (SN) | NECESSARY | 80.00 | 80.00 |
| | | | 1,970.20 | 1,286.30 |
| LABOUR | | | | |
| | TO REPLACE FRONT BUMPER,FRONT LEFT FOG LAMP TRIM & ALL ATTACHMENTS CAUSED BY ACCIDENT. | | 2,550.00 | 850.00 |
| | PAINTING ON FRONT BUMPER ASSEMBLY. | | 1,038.00 | 934.00 |
| | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION. | | 177.00 | 150.00 |
| | | | 3,765.00 | 1,934.00 |
| GRAND TOTAL | | | 5,735.20 | 3,220.30 |
| RECOMMENDED COST OF REPAIRS | | | | 3,220.30 |

Report Ref No. CS/FC118006834/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.