

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0139/2018
DATE : 12-APR-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 68277660
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : MR CHANG CHEE MENG STANLEY
ADDRESS : BLK 636 JURONG WEST ST 65
#11-358
S(640636)
TELEPHONE NO : 83233618

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-YP9992Y
VEHICLE NO : SLX1949M
MODEL CODE : FDRARGWJ11ESAA----
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2017
ENGINE NO : MR20519608W
CHASSIS NO : SJNFB AJ11U2217626
MILEAGE : 345 KM
DATE IN : 12/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 27/03/2018

CCR

DIS

* SPOT CLAIM
get car only

7 day

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX1949M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240.00
3 RS	SUPPLY & INSTALL REVERSE SENSOR - SUPPLEMENTARY	110.00	110.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100.00
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
6 UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
7 ZZ/001	REPAIR BOTH REAR FENDER AND RENEW END PANEL, REAR BUMPER AND TAILGATE	1200.00	875.00
8 ZZ/002	S/PAINT REAR PORTION AND BUMPER (2 TONE)	1400.00	1100.00
9 ZZ/003	CHECK LIGHTING	48.00	48.00
10 ZZ/004	SUPPLY AND RENEW REAR NO. PLATE(SMART PLATE WITH CASING) LONG		
11 ZZ/005	R/I REAR DVR TO ASSIST REPAIR	120.00	120.00
12 ZZ/006	TRANSFER TAILGATE MECHANICAL PARTS	80.00	80.00
13 ZZ/007	VEHICLE TOW IN BY A.A W/O T145341 ON 27.03.2018 @ 2140HRS		
TOTAL LABOUR CHARGES		4128.00	3183.00
ADDITIONAL DISCOUNT(5.00%)			159.15
FINAL LABOUR CHARGES			3023.85

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX1949M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	MLDG-RR BMPR LH - SUPPLEMENTARY	85087-HV00A	183.60			OK
2	MLDG-RR BMPR RH - SUPPLEMENTARY	85086-HV00A	102.00			OK
3	ANTENNA-SMART KEYLESS	285E5-JK60A	53.50			X
4	ANTENNA ASSY-DO	285E7-JK60A			64.40	X
5	EMBLEM	90892-4EA0A	87.00			OK
6	EMBLEM-REAR	90890-4EA0A	59.70			OK
7	FINISHER BACK DOOR LOWER	90901-4EA0A	316.50			X
8	STRIKER-TAIL GA	90570-4EA0A	31.70			OK
9	A LOCK LIFT	90502-4EA1B	116.70			OK
10	WEATHER STRIP	90830-4EA0B	158.70			OK
11	DOOR BACK	K0100-HV0MA	2936.80			OK
12	A FIN BACK TAILGATE NO PLATE FINISHER	90810-4EU0H	336.00			OK
13	GLASS-TAIL GATE	90300-HV00A	930.00			OK
14	RETAINER-BUMPER RH	79184-4EA0A	23.80			OK
15	RETAINER-BUMPER LH	79185-4EA0A	23.80			OK
16	GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	OK
17	GROMMET BUMPER \$2.50 EA X 04	63846-5V000	10.00			OK
18	BRACKET-BUMPER RH	85220-4EA0A	35.90			OK
19	BRACKET-BUMPER LH	85221-4EA0A	35.90			OK
20	STAY ASSY-REAR RH	H5210-4EAMA	126.00			OK
21	STAY ASSY-REAR LH	H5211-4EAMA	126.00			X
22	REINF-BUMPER RR	H5030-4EAMA	619.20			OK
23	ENERGY ABSORBER	85090-HV00A	126.40			OK
24	CANOE RIVET BUMPER \$6.50 EA X 02	76882-0M000	13.00			OK
25	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20			OK

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX1949M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	FINISHER-REAR BUMPER TOW	85071-HV00A	16.80			OK
27	FASCIA RR BMPR	85022-HV30A	1574.70			OK
28	SPACER LH FLOOR	84979-4EA0A	84.00			X
29	CLIP END PANEL/FINISHER \$1.20 EA X 04	01553-05323	4.80			OK
30	CLIP-FINISHER \$1.20 EA X 04	01554-00181	4.80			OK
31	PLATE-LUGGAGE	84992-4EA0A	63.50			OK
32	PANEL-REAR UPPE	G9110-HV0MA	482.60			OK
33	GROMMET FENDER PROTECTOR	01281-00831	1.50			OK
34	CLIP PROTECTOR \$1.20 EA X 05	01553-05131	6.00			OK
35	PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40			X
36	PROTECTOR-REAR LH FENDER	76749-4EA0A	186.40			X
37	CLIP ARC/BUMPER \$1.20 EA X 04	01553-05933	4.80			OK
38	FENDER ARC RH REAR	93828-4EA0A	483.00			X
39	CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60			X
40	GROMMET C/LAMP \$1.90 EA X 02	76848-35F00	3.80			X
41	WASHER SEALING C/LAMP \$25.70 EA X 04	76848-83P00	102.80			X
42	LAMP COMB RR,RH TAILAGTE	26550-HV55A	215.90			OK
43	LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90			OK
44	LAMP COMB RR,RH	26550-HV00A	323.70			OK
45	LAMP COMB RR,LH	26555-HV00A	323.70			X
46	RUBBER-DUM	G2716-89900	60.20			OK
47	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
48	SUNDRIES - CLIPS	NPN			20.00	OK
49	REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG	RLP			60.00	OK

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX1949M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
	SUB TOTAL		8953.60	0.00	164.40	
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1790.72	0.00	0.00	
	GRAND TOTAL		7162.88	0.00	164.40	
	ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-5.00%)		358.14	0.00	8.22	
	OVERALL TOTAL		6960.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLX1949M

NETT ITEM 8953.60
LESS 20.00%) -1790.72
NETT AMOUNT 7162.88
ADDITIONAL DISCOUNT(5.00%) -358.14
FINAL AMOUNT 6804.74

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 164.40
LESS .00%) 0.00
SPECIAL NETT AMOUNT 164.40
ADDITIONAL DISCOUNT(5.00%) -8.22
FINAL AMOUNT 156.18

TOTAL LABOUR CHARGES 3023.85
TOTAL SPARE PARTS CHARGES 6960.92

TOTAL CHARGES 9984.77
ADD 7 % GST 698.93

GRAND TOTAL 10683.70

23/04//2018

INS/IC/LAW/0139/2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
Singapore 048581

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLX1949M
POLCY NO. : -

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>		
1	MLDG-RR BMPR RH	\$102.00 NETT
2	MLDG-RR BMPR LH	\$183.60 NETT
3	SUPPLY & INSTALL REVERSE SENSOR	\$110.00
4		
5		
6		
7		

TOTAL \$ 395.60

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD

Lawrence Teo
Insurance Claim Dept

Cc: Surveyor