

AS - REC BY:

REF:

CS/F118006845/Dc b n 2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): WS Eileen Lee of F11 Date/Time: 12/04/2018 527pmEstimated Cost: - Bill to: -OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJN 9264D Insured: SHC 8468Xat Workshop m/s Teamwork Garage Tel: 6844 2475of 53 Ubi Ave 1 #01-24Policy No: - Claim No: D18002829 MFSHSum Insured: - Excess: -Make of Veh: - D.O.A. 11-04-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 15/04/2018 Person Contacted: Sue Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJN 9264D - NA / INC 18006642 / 24	DA: 11/04/2018
	SHC 8468X - NBA / INC 13012393 / y1	DA: 08/07/13

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of:

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **83N 9264D**Date: **2009 March**Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1595

Colour:

Brown

A/C

Insured / Std / NI / NA

Sp Reading

224989

T/Radio: Insured / Std / NI / NA

Eng/Ho:

R16A14003625

Chassis

JHMFD462098201012Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Free / Jammed / Leaked / Burnt orBrake: ☒ Free / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Henkook

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

11/04/2018

D.O.I:

24/04/2018

Survey held at

Tiamwork Page ubiDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or**Rear**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SHC 8468X**03/12/18 for repair 1/5 950/- with 2 days of repair (Red 7168.28, 88%)****RECEIVED 05 DEC 2018**

Date/Time, File Pass to?



: Prelim. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + P.S. (S)

) Photos:

) Others:

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

TPLum Sum / I.B.E (\$ **950/-**)**160****50****50****24****284**

MOTOR SURVEY ASSIGNMENT

Date	11-04-2018	Our Ref No. D18002829MFSH
Accident Date	11-04-2018	Claim Type. Third Party
Insured Vehicle	SHC8468X	Third Party Vehicle. SJN9264D
Survey Location	BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	SUE	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TEAMWORK GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1459M
Vehicle Details	
Vehicle No.:	SJN9264D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L 5AT
Primary Colour:	Brown
Manufacturing Year:	2008
Engine No.:	R16A14003625
Chassis No.:	JHMFD46209S201012
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,139.00
Original Registration Date:	05 Mar 2009
First Registration Date:	05 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$25,139.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Mar 2019
PARF Rebate Amount:	\$12,569.00
Intended COE Rebate Details	
COE Expiry Date:	04 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,460.00
COE Rebate Amount:	\$111.00
Total Rebate Amount:	\$12,680.00

The information contained herein is correct as at 04 Dec 2018

OK



Pte Ltd

First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number SJN9264D
Make / Model HONDA/CIVIC
Chassis number JHMFDA62095201012
Accident date 11 April 2018
Reference 1804-14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>distorted</i>	638.30 ✓
2	REAR BUMPER LOWER BRACKET <i>SVL</i>	37.50 X
2	REAR BUMPER RETAINER <i>SVL</i>	39.60 X
1	REAR END PANEL <i>NN</i>	531.00 X
1	REAR END PANEL TOP GARNISH <i>NN</i>	160.80 X
2	REAR TAILLAMP <i>NN</i>	542.88 X
2	REAR TAILLAMP SEALER <i>NN</i>	40.00 X
2	REAR FENDER INNER TRIM <i>NN</i>	395.10 X
1	BOOTLID <i>NN</i>	710.70 X
1	BOOTLID OUTER KEY LOCK <i>NN</i>	297.00 X
1	BOOTLID WEATHERSTRIP <i>NN</i>	114.00 X
1	BOOTLID EMBLEM LOGO -H <i>NN</i>	45.00 X
1	BOOTLID EMBLEM -CIVIC <i>NN</i>	39.90 X
1	BOOTLID EMBLEM - 1.6 <i>NN</i>	41.00 X
1	BOOTLID EMBLEM - I-VTEC <i>NN</i>	44.90 X
2	BOOTLID LAMP <i>NN</i>	350.16 X
1	BOOTLID LOCK <i>NN</i>	295.90 X
1	BOOTLID LOCK STRIKER <i>NN</i>	155.00 X
2	BOOTLID HINGE <i>NN</i>	88.90 X
2	BOOTLID STOPPER <i>NN</i>	20.00 X
1	SPARE TYRE TOP BOARD <i>NN</i>	297.70 X
		4885.34
		Less 20%
		977.06
		Subtotal
		3908.28
		Balance C/F
		3908.28
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
		Balance B/F
		3908.28
1 SET	REAR BUMPER CLIP <i>NN</i>	80.00 30/-
1 SET	REAR FENDER INNER TRIM CLIP <i>NN</i>	70.00 X
1 SET	REAR REVERSE SENSOR <i>shifted</i>	400.00 220/-
1	JOINT SEALANT <i>NN</i>	150.00 X
		Subtotal
		700.00
		Balance C/F
		4608.28
S/No	LABOUR AND MISCELLANEOUS CHARGES	
		Balance B/F
		4608.28
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 NN
2	CHECK REAR LINING, TRIM AND GARNISH	200.00 NN
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND STRAIGHTEN REAR EXHAUST	150.00 NN
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 NN
6	PANEL BEATING ON AFFECTED AREAS	1400.00 200/-
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 200/-
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 NN
		Subtotal
		3510.00
		Grand total
		8118.28

638.30
510.64

250.00

440.00

1200.64

45950.00

24/04/2018 @ 1530m
Not Antenna 2 days.
215mm

Ryan LKK Auto



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006845/Dcbr2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8468X	Veh. Inspected	SJN 9264D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002829MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	12/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMF46209S201012	Colour	BROWN	
Odometer	224989	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	5 mm	
L/H Front Tyre	205/55 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2018	Inspection Date	24/04/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 9264D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	638.30	638.30
2	REAR BUMPER LOWER BRACKET	SERVICEABLE	37.50	-
2	REAR BUMPER RETAINER	SERVICEABLE	39.60	-
1	REAR END PANEL	NOT NECESSARY	531.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	160.80	-
2	REAR TAILLAMP	NOT NECESSARY	542.88	-
2	REAR TAILLAMP SEALER	NOT NECESSARY	40.00	-
2	REAR FENDER INNER TRIM	NOT NECESSARY	395.10	-
1	BOOTLID	NOT NECESSARY	710.70	-
1	BOOTLID OUTER KEY LOCK	NOT NECESSARY	297.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	114.00	-
1	BOOTLID EMBLEM LOGO-H	NOT NECESSARY	45.00	-
1	BOOTLID EMBLEM-CIVIC	NOT NECESSARY	39.90	-
1	BOOTLID EMBLEM-1.6	NOT NECESSARY	41.00	-
1	BOOTLID EMBLEM-I-VTEC	NOT NECESSARY	44.90	-
2	BOOTLID LAMP	NOT NECESSARY	350.16	-
1	BOOTLID LOCK	NOT NECESSARY	295.90	-
1	BOOTLID LOCK STRIKER	NOT NECESSARY	155.00	-
2	BOOTLID HINGE	NOT NECESSARY	88.90	-
2	BOOTLID STOPPER	NOT NECESSARY	20.00	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	297.70	-
	LESS 20% DISCOUNT		-977.06	-127.66
			3,908.28	510.64
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	70.00	-
1	SET REAR REVERSE SENSOR (SN)	SHORTED	400.00	220.00
1	JOINT SEALANT (SN)	NOT NECESSARY	150.00	-
			700.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	CHECK REAR LINING, TRIM AND GARNISH.	NOT NECESSARY	200.00	-
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND STRAIGHTEN REAR EXHAUST.	NOT NECESSARY	150.00	-
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.		1,400.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			3,510.00	440.00
	GRAND TOTAL		8,118.28	1,200.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CS/FC118006845/Dcbrn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.