



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFR9899Z
Make & Model : B.M.W., 730LI AT ABS D/AB 2WD 4DR NAV HID
Year of Manufacture : 2010
SR, WBAKB22030CN74762

Estimation No. : E18040040
DOA : 09/04/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid X Repair - BT	1.00	2,140.00	2,140.00 1887.35
2	Rear bootlid logo -	1.00	87.10	87.10 58.50
3	Rear bootlid emblem - 730LI -	1.00	76.30	76.30 60.63
4	Rear bootlid weather strip X	1.00	76.30	76.30
5	Rear bootlid lock X	1.00	552.90	552.90
6	Rear bootlid lamp (LH) X	1.00	0.00	0.00
7	Rear bootlid lamp (RH) X	1.00	0.00	0.00
8	Rear bumper - re	1.00	1,605.80	1,605.80 1495.45
9	Rear bumper clip -	10.00	5.00	50.00
10	Rear bumper retainer (LH) =	1.00	265.60	265.60 130.70
11	Rear bumper retainer (RH) =	1.00	265.60	265.60 130.70
12	Rear bumper bracket (LH) X	1.00	135.00	135.00
13	Rear bumper bracket (RH) X	1.00	135.00	135.00
14	Rear bumper reinforcement X	1.00	937.60	937.60 781.30
15	Rear bumper sponge X	1.00	107.00	107.00
16	Rear reverse sensor X	4.00	300.00	1,200.00
17	Rear bumper lock sensor X	1.00	145.00	145.00
18	Rear bumper reflector (LH) X	1.00	55.00	55.00
19	Rear bumper reflector (RH) X	1.00	55.00	55.00
20	Rear bumper lower garnish X	1.00	0.00	0.00 1190.00 270
21	Rear bumper air duct (LH) X	1.00	0.00	0.00
22	Rear bumper air duct (RH) X	1.00	0.00	0.00
23	Tail lamp (LH) X	1.00	0.00	0.00 1080.00
24	Tail lamp (RH) X	1.00	0.00	0.00 1080.00 684

Supp:

- * inner centre bracket / CNA
- * reinforcement garnish / CNA
- * rear bumper lower clip
- * number plate garnish / CNA
- * exhaust heat shield / BUC.

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFR9899Z
Make & Model : B.M.W., 730LI AT ABS D/AB 2WD 4DR NAV HID
Year of Manufacture : 2010
Estimation No. : E18040040
DOA : 09/04/2018

No	Description	Qty	U/P	Amt
25	Tail lamp clip (LH) X	2.00	5.00	10.00
26	Tail lamp clip (RH) X	2.00	5.00	10.00
27	Rear fender inner trim (LH) X	1.00	353.60	353.60
28	Rear fender inner trim (RH) X	1.00	353.60	353.60
29	Rear fender inner trim clip (LH) X	10.00	5.00	50.00
30	Rear fender inner trim clip (RH) X	10.00	5.00	50.00
31	Rear end panel X - Bnc.	1.00	1,035.40	1,035.40
32	Rear end panel top garnish X	1.00	170.00	170.00
33	Rear end panel top garnish clip X	10.00	5.00	50.00
34	Exhaust pipe X Repair.	1.00	2,350.00	2,350.00
35	Exhaust pipe mounting X - TN IPC.	2.00	48.00	96.00
36	Exhaust pipe gasket X	1.00	96.70	96.70
Amt				S\$ 12,514.50
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 12,514.50

Section: Special Nett Items

37	Rear number plate X	1.00	50.00	50.00
38	Rear end panel sealant X	1.00	80.00	80.00
Amt				S\$ 130.00
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 130.00

Section: Labour Items

39	To R&R accident affected areas	1.00	1,000.00	1,000.00
40	To putty & respray accident affected areas	1.00	900.00	900.00

Continue on next page...

600.
300
400
600.



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFR9899Z
Make & Model : B.M.W., 730LI AT ABS D/AB 2WD 4DR NAV HID
Year of Manufacture : 2010
Estimation No. : E18040040
DOA : 09/04/2018
SR,WBAKB22030CN74762

No	Description	Qty	U/P	Amt
41	To rust proof accident affected areas	1.00	30.00	30.00
42	To R&R rear boot mechanism	1.00	80.00	80.00
43	To R&R rear luggage compartment	1.00	200.00	200.00
44	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
45	To check wiring layout of tail lamp	1.00	80.00	80.00
46	To R&R exhaust pipe assy	1.00	180.00	180.00
47	To check for water seepage	1.00	80.00	80.00
48	To do wheel alignment	1.00	180.00	180.00

Amt S\$ 2,810.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 2,810.00

6.
3-4 days (3-53 pm)

lumpsum repair.

After repair photos.

Amo Qiang - 82880282

13/4/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 12,514.50

Special Nett Items Subtotal S\$ 130.00

Labour Items Subtotal S\$ 2,810.00

Total S\$ 15,454.50



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SFR9899Z Estimation No. : E18040048
Make & Model : B.M.W., 730LI AT ABS D/AB 2WD 4DR NAV HID DOA : 09/04/2018
Year of Manufacture : 2010
SR,WBAKB22030CN74762

No	Description	Qty	U/P	Amt
Section: List Items				
1	inner centre bracket CRA	1.00	391.80	391.80 141
2	Reinforcement garnish CRA	1.00	288.50	288.50 165
3	Number plate garnish CRA	1.00	87.90	87.90
4	Exhaust heat shield BUC	1.00	157.20	157.20
Amt				S\$ 925.40
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 925.40

P = 9706.80 - 5%

= 9221.46

SN: 0

L: 1520.00

10741.46

* 1/2 \$ 8600 @ 6 repair
days

List Items Subtotal S\$ 925.40
Total S\$ 925.40