

ASS. REC. BY:

REF: CS/FCL18006860/Avbnz Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCL Date/Time: 12042018 4:48pm

Estimated Cost: _____ Bill to: _____

OD / TPVWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 8075S Insured: SHC 89386at Workshop m/s T & C Tel: 9007 5148of Blk 1 Kaki Bukit Ave 6 #01-68Policy No: _____ Claim No: D18002848M7SH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09042018
(Client's Record)

CA / REV / REP. / REV 24 HRS' Wp

H.O.D. Endorsement: _____

Date/Time: 12042018 5:21pm Person Contacted: Ah Chan Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>GBC 8075S - X</u>
	<u>SHC 89386 - CS/FCL16021357 / Right3rd</u> DLA: 06/11/16
<u>18/4/18</u>	<u>Informed FCI pending workshop est by email</u>
<u>5/10/18</u>	<u>Adrian confirmed LS \$2400 (Red 3951.40, 629)</u>
<u>8/10/18</u>	<u>Email preli revised to FCI</u>

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GRC 807SS Yr Regn: 13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen Berlingo C.G. 1560Colour: white A/C: Insured / Std / NI / NASp. Reading: 66400 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF77F9HECDS 671604

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Lead

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/04/18Survey held at Paya UbiDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP 1st Cap. Tand C

RECEIVED 09 OCT 2010

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 9/10 - typistReport Format: CWSLump Sum / I.B.I: (\$) 2400/-Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 145Transportation: Survey held at rda5031

Photos

Others

TOTAL

226



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE. 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002848MFSH
Our ref: CS/FCI18006860/Avb

Date : 8/10/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBC 8075S


We thank you for your instruction on 12/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/4/2018 at the premises of M/s T & C AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$6,351.40
Revised Estimate Amount	: S\$2,400.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	12-04-2018	Our Ref No. D18002848MFSH
Accident Date	09-04-2018	Claim Type. Third Party
Insured Vehicle	SHC8938G	Third Party Vehicle. GBC8075S
Survey Location	NO. 1 KAKI BUKIT AVENUE 6 #01-68 AUTOBAY	
Contact Person.	MR CHAI	
Contact No.	0/ 90075148	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	T&C AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	R. S. SOLOMON LLC	TP Solicitor Fax No. 68177499
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 8 October 2018 2:44 PM
To: 'Claim Workflow System'
Cc: 'EILEENLEE@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18002848MFSH/1, GBC 8075S
Attachments: GBC 8075S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBC 8075S
Date of survey: 17/4/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 April 2018 2:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002848MFSH/1, GBC 8075S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBC 8075S on 17/4/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 12 April 2018 5:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002848MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 12 April, 2018 4:48 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18002848MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 18 April 2018 2:00 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002848MFSH/1, GBC 8075S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBC 8075S on 17/4/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 12 April 2018 5:23 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002848MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 April, 2018 4:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002848MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3362G
Vehicle Details	
Vehicle No.:	GBC80755
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2018
Vehicle Make:	CITROEN
Vehicle Model:	BERLINGO 1.6 MT ABS AB 2WD 6DR PANEL VAN
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	10JBEB0055000
Chassis No.:	VF77F9HECDJ671604
Maximum Power Output:	-
Open Market Value:	\$17,327.00
Original Registration Date:	27 Nov 2013
First Registration Date:	27 Nov 2013
Transfer Count:	1
Actual ARF Paid:	\$867.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,503.00
COE Rebate Amount:	\$28,491.00
Total Rebate Amount:	\$28,491.00

The information contained herein is correct as at 08 Oct 2018

OK

GBC80755

Tand C

TP1st Cap

Citizen Berlingo

Voron

VF77F9HECDJ67/664

Rear Bumper Deformed

699 ✓

Rear Side Bumper x02 ^{LH} Behind

185 x 2 = 370 185

30 ✓

Rear Bumper Clips

new

45 x 2 = 90 x

Rear Bumper Side Holder x02

new

315.40 ✓

Rear Bumper Reinforcement.

Best

~~230(SN)~~ 200(SN)

Reverse Sensor Deformed

1077 +

Rear LH Door

2

118 ✓

Rear LH Door Hinge.

LH

40(SN) ✓

Rear LH Door Glass Sealant

new

10(SN) +

70km/h Sticker

316 ✓

Trillings LH

cracked

596 ✓

Rear End Panel

Dented

60(SN) ✓

Rear End Panel Sealant New

GBC8075 S.

Panel Beating
Spray Painting.
Wiring.

To undersend

To remove reverse sensor

To transfer rear door fittings.

To remove rear door glass

~~1000~~ 500

~~800~~ 250

~~50~~ 30

150 X

~~100~~ 50

150 X

100 X

6351.40

list: 2141.40

10% 1927.26

S.N: 260

Labour: 830

total 3077.26

2/s: 2.4K. ✓

0.5 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Blank box for signature and date.

CI

EQ Insurance Company Limited
 5 Maxwell Road #17-06 Tower Block MND Complex Singapore 069110
 Tel 65 6223 9433 / fax 65 6224 2903 / www.eqinsurance.com.sg
 reg no. 1378-00490-N

eqnsurance
Your Life's Friends



**TAX INVOICE
 Debit Note**

Page 1 of 1

GST Reg.No. M2-0029383-5

Number 10/MN0656739
 Transaction/Due date 23/06/2017

57

Spinacas Eats Pte Ltd
 2 Haig Avenue
 #01-06 Haig Grove
 Singapore 438840

Type of Policy	COMMERCIAL VEHICLE PRIVATE (SCH I)
Policy Number	DMCPHQ17-003517
Period of Cover	from 14/06/2017 to 26/05/2018
Vehicle Registration no.	GBCA0755
Insured's Name & Address	Spinacas Eats Pte Ltd 2 Haig Avenue #01-06 Haig Grove Singapore 438840
Branch/Territory	Singapore/Singapore
Account/Agency	A000342/A000342 Abwin Pte Ltd

	Singapore Dollar
Premium	SGD1,325.35
STANDARD RATED GST 7.00%	SGD92.77
	SGD1,418.12
Total Due	SGD1,418.12

This is a computer-generated document and it does not require a signature.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006860/Avbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8938G	Veh. Inspected	GBC 8075S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002848MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	12/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN BERLINGO	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF77F9HECDJ671604	Colour	WHITE	
Odometer	66400	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	LEAO	6 mm	
L/H Front Tyre	195/65 R15	LEAO	6 mm	
R/H Rear Tyre	195/65 R15	LEAO	6 mm	
L/H Rear Tyre	195/65 R15	LEAO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2018	Inspection Date	17/04/2018	
Survey held at	51 UBI AVE 1,#01-25 PAYA UBI IND.PARK S (408933)			
Repairer	T & C AUTOMOTIVE			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8075S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	699.00	699.00
2	REAR SIDE BUMPER @\$185.00	N/S DEFORMED	370.00	185.00
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER @\$45.00	NOT NECESSARY	90.00	-
1	REAR BUMPER REINFORCEMENT	BENT	315.40	315.40
1	REAR LH DOOR	NOT NECESSARY	1,077.00	-
1	REAR LH DOOR HINGE	NOT NECESSARY	118.00	-
1	TAILLAMP LH	CRACKED	316.00	316.00
1	REAR END PANEL	DENTED	596.00	596.00
	LESS 10% DISCOUNT		-	-214.14
			3,611.40	1,927.26
SPECIAL NETT ITEMS				
1	REAR LH DOOR GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	70KM/H STICKER (SN)	NOT NECESSARY	10.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
			390.00	260.00
LABOUR				
	PANEL BEATING.		1,000.00	500.00
	SPRAY PAINTING.		800.00	250.00
	WIRING.		50.00	30.00
	TO UNDERSEAL.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO TRANSFER REAR DOOR FITTINGS.	NOT NECESSARY	150.00	-
	TO REMOVE REAR DOOR GLASS.	NOT NECESSARY	100.00	-
			2,350.00	830.00
GRAND TOTAL			6,351.40	3,017.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00



Report Ref No. CS/FCI18006860/Avbn2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, with a stylized flourish at the end.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.