

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : M & L FURNISHING

Singapore

ATTN:

Your Ref No: 18/FC/TP-077 (04)

Claim Type: Third Party

Accident Date: 09/04/2018

TP Veh Reg No: SHD4448A

Estimate No: EST0004055

Date: 12 Jul 2018

Policy No: GA216971

Veh Reg No: GZ6437P

Make/Model: MITSUBISHI L300

Chasis No: JMAJNP15V6A001344

Engine No: 4D56LC0772

Reg. Date: 17/07/2006

Estimate Repair Cost to Vehicle No :GZ6437P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
List Price			
1 REAR GATE INNER RUBBER	<i>1pc</i> 1 PC	197.50	
		197.50	
	Less 20%	39.50	158.00
Total			S\$ 158.00
GST Amount			S\$ 11.06
Total Amount Payable			<u>S\$ 169.06</u>

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

List -
-20%