

Mei Kwan (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 22 June, 2018 12:20 PM
To: Mei Kwan (LKKAUTO)
Cc: Admin A
Subject: FW: Direct Settlement - Accident Involving GBB757R (OI : EQI - DM18HO00963/JT) AND SHA7153X (TP : LKK REF - CC3/EQI18006864/K1pa3) on 11.04.2018
Attachments: LKK RESURVEY PHOTO.pdf; TP GIA REPORT.pdf; TP ESTIMATE - MARKED.pdf; LKK SURVEY PHOTO.pdf; Preliminary Advice.pdf; GBB757R.PDF
Categories: HMK

Dear Mei Kwan,

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, April 18, 2018 2:05 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBB757R (OI : EQI - TBA) AND SHA7153X (TP : LKK REF - CC3/EQI18006864/K1pa3) on 11.04.2018

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHA 7153X at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)