

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 3352D

DATE 12/4/2018 14:37

MAKE :

MODEL : HYUNDAI i40

LKK/Kalwin

abyP

Lke

ALG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Wheel Hup-Cap (LH) <i>hup</i>			\$ 150.70
	<i>Rear Bumper x repair</i>			\$ 150.70
	<i>Rear LH fender x repair</i>			\$ 30.14
	SUB TOTAL			\$ 120.56
	LESS 20%			
	DISCOUNTED TOTAL			
	Rear Bumper Rubber Mat <i>x 11</i>			\$ 50.00
	Rear Bumper Advertisement Logo <i>all</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>all</i>		\$ 100.00	\$ 200.00
				\$ 300.00
	Labour Charge			
	Panel Beating- Repair Fender			\$ 500.00 <i>200</i>
	Spray Painting Charge-Bumper/Fender			\$ 500.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>x 11</i>
	Tuff Kote			\$ 50.00 <i>x 11</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>x 11</i>
	Rear Wheel Alignment			\$ 80.00 <i>x 11</i>
	TOTAL LABOUR			\$ 1,300.00
	ESTIMATE TOTAL			\$ 1,720.56

Kalwin LKK
12/4/18 1500hrs
2 Pys
P/P
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be used and is subject to final approval by insurance company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.