

Surveyor:

REF: CS1 / MS118006901 / D9622

Special Instruction:

Rm20126.10

ASSIGNMENT (Office)

From (Person): Christina Wong of MS2H Date/Time: 13042018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: City Adjusters

Workshop: Yi Tat Car Workshop

OD/FP Re-inspection / (Evaluation)

To Inspect Vehicle No: WC 7463C Insured: FU 2037A

at Workshop m/s Yi Tat Car Workshop Tel:
of No. 26 Jin Teretui & Tmn Johor Jaya

Policy No: Claim No: MSC/V/13-000166

Sum Insured: Excess:

Make of Veh: D.O.A. 1008 2017
(Client's Record)

Do Not Finalize

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 15 days)

Date/Time: Submit Final Fig , days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	WC 7463C - X
	FU 2037A - NJA / ENCE9006880 / K1
	DOT 300809
25/4/18	Photos provided hardly any damage seen. collision with m/qcar so should not be so badly damaged. To submit RM 6571.48 with 3 days of exp. RM 1178.71 (RM 12947.39, 64%) 4
*	pls take note this case is claim "RM"

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 26 APR 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

150

1) Date/Time 26/4/17 File Pass to [Signature]

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 13 April, 2018 11:07 AM
To: assignments; Christina Wong
Subject: FW: Our Ref:MSC/v/18-000166 Your Ref:WC7463C-Please do paper survey
Attachments: 12042018165913-0001.pdf

Dear Christina,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Christina Wong [mailto:Christina_Wong@sg.msig-asia.com]
Sent: Friday, 13 April 2018 10:59 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Our Ref:MSC/v/18-000166 Your Ref:WC7463C-Please do paper survey

Hi Veron

Our OI is motor bike FU2037A

There will be another two attachment the TP survey report and photos, please do a paper survey.

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor) Direct line +65 6643 1311 | Direct fax +65 6225 7402 |
christina_wong@sg.msig-asia.com

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on

-----Original Message-----

From: ApeosPort-VI C5571 [mailto:24Flr_CLP-Mtr@sg.msig-asia.com]
Sent: Thursday, 12 April, 2018 4:59 PM

To: Christina Wong <Christina_Wong@sg.msg-asia.com>
Subject: Scan Data from FX-126223

Number of Images: 10
Attachment File Type: PDF

Device Name: ApeosPort-VI C5571
Device Location:

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2018 13:51
Date Of Accident	10/08/2017 02:00
Exact Location Of Accident	JALAN JOHOR BAHRU - KOTA TINGGI
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FU2037A
Insured/Policyholder	
Name Of Registered Owner	MUHD NUR HAKIM BIN MOHD
NRIC No	S9541508C
Email Address	MUHDNURHAKIM16@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96527344
Alternative Phone No	OFFICE-96527344

Vehicle Particulars

Manufacturer	KAWASAKI
Model	KR150-149CC (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMT-16-974367
Cover Note Number	

Driver

Name of Driver	MUHD NUR HAKIM BIN MOHD
NRIC No	S9541508C
Date Of Birth	16/11/1995
Occupation	INDOOR
Date Of Driving Pass	04/07/2016
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96527344
Fax Number	
Contact Number	OFFICE-96527344
Email Address	MUHDNURHAKIM16@GMAIL.COM

called OI
5-15pm - 22/3/18
Told him Traffic Police
in Johor Bahru find
him RM300/- and
he paid the FINE
he said so far nothing
Told we will settle
TP claim on his behalf.
OK with OI

Address	488 SEGAR ROAD #10-564
Postcode	S670488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	WC7463C (PRIVATE CAR)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. LOST POLICE REPORT, WAS TOLD BY MSIG OFFICER THAT POLICE REPORT WILL BE RETRIVE BY MSIG. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC7463
Vehicle Make/Model/Colour	SALOON
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

16 MAR 2018

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going straight at a junction and the light was amber I was trying to catch up with the traffic when a car from the opposite lane is turning right I couldn't stop in time and I hit the front bumper of the vehicle.

midanor hakiim lb @ gmail . com

DECLARATION

I/We declare the foregoing particulars are true in every respect.

۱۰۰

Policyholder's Signature
Date & Time:

【文】

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 559545
Tel: 6560 3312 Fax: 6569 0722
E-mail: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

City Adjusters & Investigators Sdn. Bhd. (Co.Reg.No:829614)

No. 59-3 (2nd Floor), Jalan USJ 21/10, Taman Seafield Jaya, 47630 Subang Jaya, Selangor Darul Ehsan.

Tel: +603-8023 7166 Fax: +603-8023 0736

Gst Reg No: 000275308544

THIRD PARTY CLAIM VEHICLE ASSESSMENT SURVEY REPORT

MAYFLOWER ACME TOURS SDN BHD
18 Jalan Segambut Pusat
51200, Kuala Lumpur, Wilayah Persukutuan.

Our File No : C-TPD41834-KR(DI)10/2017

Date : 13/10/2017

HANDLING INSURER

Handling Insurer : Not Applicable
Date Of Loss : 10/08/2017

Vehicle No : FU2037A
Nature Of Claim : TP

Claim No : N/A

CLAIMANT INFORMATION

Claimant : MAYFLOWER ACME TOURS SDN BHD
Address : 18 Jalan Segambut Pusat
51200, Kuala Lumpur, Wilayah Persukutuan.

Insurance Co:
Policy No :

VEHICLE IDENTIFICATION SUMMARY

Reg No :	WC7463C	Wing Mirror :	Yes
Make & Model :	NISSAN - Almera 4 Dr. Sedan 1.5 Lit V [Jan15 -]	Clock :	Yes
Reg. Date :	22/10/2015 [Manf. Year: 2014]	Radio :	Yes
Colour :	Metallic Silver	Seat Belt :	Yes
Body Type :	4 Door Saloon	Lamps :	Yes
Market Value :	42,000.00	Trailer :	No
Sum Insured :	51,000.00		
Seating Cp :	5		
Engine :	HR15974538C		
Chassis No :	PN88BAN171CA96522		
Odometer :	64187 KM		
AirCond :	Yes		

CONDITION OF VEHICLE & TYRE AT THE TIME OF SURVEY

General Condition :	Good	Steering :	Serviceable	Foot Brake :	Serviceable
Paint Work :	Good	Hand Brake :	Serviceable	Engine Modification :	No
				Pre-Accident Damage :	No

Front Tyre Size :	195/55R15	Rear Tyre Size :	195/55R15
Front Left Side :	Silverstone - 6mm	Rear Left Side :	Silverstone - 6mm
Front Right Side :	Silverstone - 6mm	Rear Right Side :	Silverstone - 6mm

CLAIM SUMMARY

	Repairer's	Adjuster's	Difference	Diff %
--	------------	------------	------------	--------

Parts	0.00	15,366.10	5464.98	0	0%
Miscellaneous Items	0.00	445.00	25.00	0	0%
Paint Work Material	0.00	700.00		0	0%
MET & Panel Labour	0.00	2,166.50	381.50	0	0%
Paint Labour	0.00	1,298.50		0	0%
Towing	0.00	150.00	NH	0	0%
			6571.44 RM		

Gross Total (RM)	0.00	20,126.10	0.00	0%
------------------	------	-----------	------	----

Net Amount (RM)	0.00	20,126.10	0.00	0%
-----------------	------	-----------	------	----

Date Of Assignment: 09/10/2017 Est. Period Of Repair: 15 Days
Date Inspected: 09/10/2017 Present Location :

Recomm'ed Reserve(RM): 20,126.10 Inspected At: YI TAT CAR WORKSHOP
No 26 Jalan Teratal 8 Taman Johor Jaya
81100 Johor Bahru Johor.

Adjuster : SAHRIZAL BIN ABD WAHID

Manager : SAHRIZAL BIN ABD WAHID

Note: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to our best of our ability knowledge but an other liability under any circumstances is hereby expressly excluded.

REFERENCE DETAILS

MRC Version : MRCDBP6.0
TTS Code : TC020
TPS Code : NS116 (NISSAN Almera 4 Dr. Sedan 1.5 Lit V [Jan15 -])

PARTS

No. Part No.	Part Description.	Qty	Src	Condition	Adj's Price	Disc(%)	Depr(%)	Nett
Front Panel								
1	F510M-7W8MA Bonnet	1	F	Buckled	1,378.00	10.00	0.00	1,240.20 <i>HN</i>
2	65401-3B80A Bonnet Hinge LH	1	F	Bent	90.10	10.00	0.00	81.09 <i>HN</i>
3	65400-3B80B Bonnet Hinge RH	1	F	Bent	90.10	10.00	0.00	81.09 <i>HN</i>
4	65601-3B80B Bonnet Lock	1	F	Jammed	174.90	10.00	0.00	157.41 <i>HN</i>
5	62225-3B80A Bumper Bracket Front LH	1	F	Bracket Cracked	47.70	10.00	0.00	42.93 <i>HN</i>
6	62224-3B80A Bumper Bracket Front RH	1	F	Bracket Cracked	47.70	10.00	0.00	42.93 <i>HN</i>
7	62257-7W80A Bumper Front Fog Lamp Finisher LH (Mid Model V VL)	1	F	Tom	212.00	10.00	0.00	190.80 <i>HN</i>
8	62256-7W80A Bumper Front Fog Lamp Finisher RH (Mid Model V VL)	1	F	Tom	212.00	10.00	0.00	190.80 <i>HN</i>
9	62660-7W80A Bumper Front Lower Cover	1	F	Tom	280.90	10.00	0.00	252.81 <i>HN</i>
10	62090-7W80A Bumper Front Shock Absorber	1	F	Broken	318.00	10.00	0.00	286.20 <i>HN</i>
11	62022-7W82H Bumper Front Cover (Mid Model V VL)	1	F	Tom	742.00	10.00	0.00	667.80 <i>HN</i>
12	F2030-3AW8H Bumper Reinforcement Front	1	F	Bent	924.32	10.00	0.00	831.89 <i>HN</i>
13	26155-8993A Fog Lamp Front LH	1	F	Broken	890.40	10.00	0.00	801.36 <i>HN</i>
14	26150-8993A Fog Lamp Front RH	1	F	Broken	890.40	10.00	0.00	801.36 <i>HN</i>
15	F2530-3HAAH Front Panel Lower	1	F	Bent	530.00	10.00	0.00	477.00 <i>HN</i>
16	62310-8A13A Grille Front (Upper)	1	F	Tom	1,036.80	10.00	0.00	934.92 <i>HN</i>
17	62310-3AA5A Grille Front	1	F	Tom	413.40	10.00	0.00	372.06 <i>HN</i>
18	92110-3BL0A Air Conditioning Condenser (Assembly)	1	F	Pierced	0.00	10.00	0.00	0.00 <i>HN</i>
19	26060-1A10E Headlamp Assy LH	1	F	Housing Broken	742.00	10.00	0.00	667.80 <i>HN</i>
20	26010-1A10E Headlamp Assy RH	1	F	Housing Broken	742.00	10.00	0.00	667.80 <i>HN</i>
21	21460-1HS0A Radiator	1	F	Pierced	1,802.00	10.00	0.00	1,621.80 <i>HN</i>
22	21499-7W81A Radiator Air Intake Duct LH	1	F	Tom	50.88	10.00	0.00	45.79 <i>HN</i>
23	21498-7W81A Radiator Air Intake Duct RH	1	F	Tom	50.88	10.00	0.00	45.79 <i>HN</i>
Undercarriage								
24	54501-1HJ0A Suspension Arm Front LH	1	F	Bent	508.80	10.00	0.00	457.92 <i>HN</i>
25	40300-2MF1E Wheel Rim Alloy (15x5.5j)	1	F	Bent	530.00	10.00	0.00	477.00 <i>HN</i>
26	54401-1HJ0A Suspension Crossmember Front	1	F	Bent	932.80	10.00	0.00	839.52 <i>HN</i>
Front Fender & Susp. LH								
27	39101-3BL0A Driveshaft Front LH (A/T Transmission)	1	F	Bent	932.80	10.00	0.00	839.52 <i>HN</i>
28	F3101-3BLMB Fender Front LH	1	F	Buckled	720.80	10.00	0.00	648.72 <i>HN</i>
29	63843-7W81A Fender Front Liner LH	1	F	Cut	169.60	10.00	0.00	152.64 <i>HN</i>
30	40015-1HH0A Knuckle Arm Front LH	1	F	Bent	1,270.94	10.00	0.00	1,143.85 <i>HN</i>
31	54303-3BL0A Shock Absorber Front LH	1	F	Bent	339.20	10.00	0.00	305.28 <i>HN</i>

F:Franchise, O:OEM, U:Used, N:Nett

Total Before Discount (RM) :
- Parts Discount 10.00 % :
Total Parts (RM) :

17,073.40
(1,707.34)
15,366.10

6072.21

5464.98

MISCELLANEOUS

No.	Part Description.	Qty	Src	Adj's Price	Nett
1	Underseal Materials	1	Q	40.00	40.00
2	Road Wheel Alignment	1	Q	35.00	35.00
3	Road Wheel Balancing	1	Q	25.00	25.00
4	Road Test	1	Q	30.00	30.00
5	Radiator Coolant	1	Q	20.00	20.00
6	Number Plate Front	1	Q	25.00	25.00
7	Electronic Diagnosis	1	Q	120.00	120.00
8	Air-Cond Gas (R134A)	1	Q	120.00	120.00
9	Air Cond System Checking	1	Q	30.00	30.00

Total :-**445.00**

25.00

LABOUR

S.NO	Particular	Type	MET	Panel	Paint	Total
01-New(TTS)						
1	Bonnet	New(TTS)	0.30	0.40	5.40	06.10 <i>HN</i>
2	Bumper Front	New(TTS)	1.40	0.00	5.10	06.50 <i>✓</i>
3	Bumper Front R&R	New(TTS)	0.80	0.00	0.00	00.80 <i>✓</i>
4	Bumper Front Reinforcement Panel	New(TTS)	0.40	0.00	0.00	00.40 <i>HN</i>
5	Front Panel	New(TTS)	3.40	0.00	0.00	03.40 <i>HN</i>
6	Front Panel Assembly	New(TTS)	3.90	2.30	2.80	09.00 <i>HN</i>
7	Front Panel Upper	New(TTS)	3.00	1.20	2.60	06.80 <i>HN</i>
8	Headlamp Assembly LH (Its)	New(TTS)	1.20	0.00	0.00	01.20 <i>✓</i>
9	Headlamp Assembly RH (Its)	New(TTS)	1.20	0.00	0.00	01.20 <i>✓</i>
10	Fender Front LH	New(TTS)	1.10	0.40	6.40	07.90 <i>HN</i>
02-OPINION						
11	Chassis Member Front LH Front Section	Repair	* 2.00	* 2.10	* 2.20	06.30 <i>HN</i>
12	Chassis Member Front RH Front Section	Repair	* 2.80	* 2.10	* 2.20	07.10 <i>HN</i>
13	Crossmember Front	Repair	* 3.60	* 1.00	* 2.40	07.00 <i>HN</i>
14	Engine and Suspension R&R	Repair	* 6.80	* 0.00	* 0.00	06.80 <i>HN</i>
15	Headlamp Panel LH	Repair	* 2.20	* 0.90	* 2.40	05.50 <i>HN</i>
16	Headlamp Panel RH	Repair	* 2.20	* 0.90	* 2.40	05.50 <i>HN</i>
17	Chassis Member Front & Inner Fender LH	Repair	* 3.10	* 4.80	* 2.60	10.50 <i>HN</i>
18	Chassis Member Front Closing LH	Repair	* 0.00	* 2.00	* 2.20	04.20 <i>HN</i>
19	Chassis Member Front Closing Section LH	Repair	* 0.00	* 1.80	* 2.10	03.90 <i>HN</i>
20	Fender Front Inner LH	Repair	* 3.10	* 4.40	* 2.50	10.00 <i>HN</i>
21	Fender Front Inner Reinforcement LH	Repair	* 1.10	* 2.00	* 2.20	05.30 <i>HN</i>
22	Fender Front Inner Section LH	Repair	* 0.40	* 1.90	* 2.30	04.60 <i>HN</i>
23	Fender Front Inner Upper LH	Repair	* 0.30	* 1.20	* 2.20	03.70 <i>HN</i>

LABOUR - Summary

	MET	Panel	Paint	Others	Total
Total Combined (TTS) (18%)	16.09	04.07	09.40		29.56
Total Overlap Hrs (-)	10.94	01.35			12.29
Total Opinion Hrs (82%)	27.60	25.10	27.70		80.40

Total Hrs Without (Overlap)	32.80	27.90	37.10		97.80
-----------------------------	-------	-------	-------	--	-------

Job Allowance				00.50	0.50 <i>✓</i>
CP				00.70	0.70 <i>✓</i>

Labour Rate (In RM)	35.00	35.00	35.00	35.00	99.00 <i>1090</i>
---------------------	-------	-------	-------	-------	-------------------

Labour Cost (Rate*Hrs) (In RM)	1,148.00	976.50	1,298.50	42.00	3,465.00 <i>X 35.00</i>
-----------------------------------	----------	--------	----------	-------	-------------------------

RM 381.50

<< END OF ESTIMATE >>

Narratives

BRIEF CIRCUMSTANCES OF ACCIDENT

The accident occurred due to the subject motorcar was said to have been collided by a motorcycle at its front section.

SOURCE OF PARTS PRICE

We have recommended the parts pricing based on MRC DATABASE wherein a discount of 10% have been applied.

CONSISTENCY OF DAMAGES

Our visual inspection of the subject vehicle upon sighting the police report No: TRAFIK JOHOR BAHRU(S)/018027/17 revealed that the damage noted is consistent with the reported accident.



Your Ref: MSC/V/18-000166

Date: 02nd May 2018

Our Ref: CS1/MSG18006901/Dqbs2

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Bldg

Singapore 048581

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

WC 7463C

INSURED VEHICLE: FU 2037A

ACCIDENT DATE: 10/08/2017

We thank you for your instruction on 13/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of WC 7463C from M/s City Adjusters & Investigators Sdn. Bhd.
- b) Singapore Accident Statement of Vehicles FU 2037A.
- c) Colour damaged vehicle photographs of WC 7463C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: WC 7463C
Make & Model	: Nissan – Almera 4
Year of Registration	: 2015
Chassis Number	: PN8BBAN171CA96522
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 7463C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	NOT NECESSARY	1,378.00	-
1	BONNET HINGE LH	NOT NECESSARY	90.10	-
1	BONNET HINGE RH	NOT NECESSARY	90.10	-
1	BONNET LOCK	NOT NECESSARY	174.90	-
1	BUMPER BRACKET FRONT LH	BRACKET CRACKED	47.70	47.70
1	BUMPER BRACKET FRONT RH	BRACKET CRACKED	47.70	47.70
1	BUMPER FRONT FOG LAMP FINISHER LH (MID MODEL V VL)	TORN	212.00	212.00
1	BUMPER FRONT FOG LAMP FINISHER RH (MID MODEL V VL)	TORN	212.00	212.00
1	BUMPER FRONT LOWER COVER	TORN	280.90	280.90
1	BUMPER FRONT SHOCK ABSORBER	BROKEN	318.00	318.00
1	BUMPER FRONT COVER (MID MODEL V VL)	TORN	742.00	742.00
1	BUMPER REINFORCEMENT FRONT	NOT NECESSARY	924.32	-
1	FOG LAMP FRONT LH	BROKEN	890.40	890.40
1	FOG LAMP FRONT RH	BROKEN	890.40	890.40
1	FRONT PANEL LOWER	NOT NECESSARY	530.00	-
1	GRILLE FRONT (UPPER)	TORN	1,038.80	1,038.80
1	GRILLE FRONT	TORN	413.40	413.40
1	AIR CONDITIONING CONDENSER (ASSEMBLY) (NPA)	NOT NECESSARY	-	-
1	HEADLAMP ASSY LH	HOUSING BROKEN	742.00	742.00
1	HEADLAMP ASSY RH	HOUSING BROKEN	742.00	742.00
1	RADIATOR	NOT NECESSARY	1,802.00	-
1	RADIATOR AIR INTAKE DUCT LH	NOT NECESSARY	50.88	-
1	RADIATOR AIR INTAKE DUCT RH	NOT NECESSARY	50.88	-
1	SUSPENSION ARM FRONT LH	NOT NECESSARY	508.80	-
1	WHEEL RIM ALLOY (15X5.5J)	NOT NECESSARY	530.00	-
1	SUSPENSION CROSSMEMBER FRONT	NOT NECESSARY	932.80	-
1	DRIVESHAFT FRONT LH (A/T TRANSMISSION)	NOT NECESSARY	932.80	-
1	FENDER FRONT LH	NOT NECESSARY	720.80	-

Report Ref No. CS1/MSG18006901/Dqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER FRONT LINER LH	CUT	169.60	169.60
1	KNUCKLE ARM FROM LH	NOT NECESSARY	1,270.94	-
1	SHOCK ABSORBER FRONT LH	NOT NECESSARY	339.20	-
	LESS 10% DISCOUNT		-1,707.32	-674.69
			15,366.10	6,072.21
	SPECIAL NETT ITEMS			
1	UNDERSEAL MATERIALS (SN)	NOT NECESSARY	40.00	-
1	ROAD WHEEL ALIGNMENT (SN)	NOT NECESSARY	35.00	-
1	ROAD WHEEL BALANCING (SN)	NOT NECESSARY	25.00	-
1	ROAD TEST (SN)	NOT NECESSARY	30.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	20.00	-
1	NUMBER PLATE FRONT (SN)	BENT	25.00	25.00
1	ELECTRONIC DIAGNOSIS (SN)	NOT NECESSARY	120.00	-
1	AIR-COND GAS (R134A) (SN)	NOT NECESSARY	120.00	-
1	AIR COND SYSTEM CHECKING (SN)	NOT NECESSARY	30.00	-
			445.00	25.00
	LABOUR			
	PAINT WORK MATERIAL.		700.00	700.00
	MET & PANEL LABOUR. }		2,166.50	381.50
	PAINT LABOUR. }		1,298.50	-
	TOWING.	NOT NECESSARY	150.00	-
			4,315.00	1,081.50
	GRAND TOTAL		20,126.10	7,178.71
	RECOMMENDED COST OF REPAIRS			7,178.71

Report Ref No. CS1/MSG18006901/Dqbs2

NOTE: THIS CASE IS CLAIM IN RM

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.