

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: BC.50867.1115.CLA.DC.mc

Date: 09th May 2018

Our Ref: CS1/LAW18006903/Dvbs2

M/s Benedict Chan & Company 14 Fort Road Singapore 439075

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBB 8945L INSURED VEHICLE: GY 4644B ACCIDENT DATE: 14/01/2014

We thank you for your instruction on 13/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBB 8945L from M/s JAS Appraisal Services.
- b) Survey report by RT Appraisal Pte Ltd.
- c) Singapore Accident Statement of Vehicles GBB 8945L.
- d) Colour damaged vehicle photographs of GBB 8945L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number Make & Model : GBB 8945L : Toyota Hiace

Year of Registration

: 2010

Chassis Number

: JTFHT02P000060419

Engine Capacity

: 2982 cc

- We recommend that the repairs of the entire damage require about <u>3 (Three)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.