

ASS. REC. BY:

REF: CS/MSG18007909 / Gvber Special Instruction:

Surveyor
MafimenASSIGNMENT (Office)

From (Person): Elaing Ngu of Msth Date/Time: 13042018 634pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 2228S Insured: GT 1240D

at Workshop m/s Boon Automobile Tel: 0181 0801

of Bk 5033 AMX Ind Park 2 #01-267

Policy No: A29007663TMV Claim No: 555428

Sum Insured: Excess:

Make of Veh: D.O.A. 12042018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpl

17-04-2018 @ after 10 am - 2pm

H.O.D. Endorsement:

Date/Time: 14042018 1213pm Person Contacted: Mr. Ng Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	YP 2228S - X
	GT 1240D - NA / ZNC10079651 / W1 DOP: 021010
12/6/18	@ 329pm Repairer said pending for parts prices.
27/7/18	@ 406pm Mr Ng said est not ready
21/12/18	LS \$ 3800 Confirmed by email (Ref 8218.62, 68)

21572005

York

REF: MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Boon Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: Yp22285 Yr Regn: May 16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: ISUZU NH C.C. 2999
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 25056 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JAANHR85EF7100568
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195 / 75 R15
 R: 165 R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 17-04-18
 Survey held at w/s 1pm
 Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
12/4 w/s will give GIA & Estimate later.

RECEIVED 24 DEC 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 24/12 - typist

Report Format : Merimen

Lump Sum / I.B.I. (\$) 3800 1/2

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS. _____ \$

Photos

Others

TOTAL

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2018		13 Apr 2018 18:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CALDRON HARDWARE ENTERPRISE , Co. Reg. No.: 36924700X								
Main Claimant:	PEEL & SEAL TRADING , Co. Reg. No.: 53013106D								
Vehicle Reg. No.:	YP2228S	Date of Loss:	12/04/2018 13:00 - :59 [23 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555428	Policy/Cover Note No.:	A29007663TMV (Third Party Only) Coverage: 01/10/2017 - 30/09/2018						
Vehicle Reg. No. (Insured):	GT1240D	Policy No. (Claimant):							
		Excess:							
Repairer:	Boon Automobile Service (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-267, 569536 Ang Mo Kio - Tel: 64820801								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/04/2018]								
Driver/Custodian (Insured):	YONG LING TIAN SAMUEL (YANG LINTIAN) () , NRIC: S7412823H, Tel: +6591705498								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***YP2228S (555428)**
[GT1240D]
TP
PEEL & SEAL TRADING
Apr 12 2018 1:00PM
[CALDRON HARDWARE ENTERPRISE]
Boon Automobile Service

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/04/2018 12:33 PM.
To MSIG_ENSM
Subject TP SURVEY YP 2228S

Dear Elaine,

Please be informed that we have inspected YP 2228S the vehicle on 17/4/2018 .

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	YP2228S		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	With Power Tailgate		
Vehicle Scheme :	Normal		
Vehicle Make :	ISUZU		
Vehicle Model :	NHR85AUE4A R1		
Chassis No. :	JAANHR85EF7100568		
Propellant :	Diesel		
Engine No. :	4JJ12J0218		
Engine Capacity :	2999 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	4500 kg		
Unladen Weight :	2260 kg		
Year Of Manufacture :	2015		
Original Registration Date :	03 May 2016		
Lifespan Expiry Date :	02 May 2036		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$39,317.00		
COE Expiry Date :	02 May 2026		
Road Tax Expiry Date :	02 May 2019		
Inspection Due Date :	02 May 2019		
Intended Transfer Date :	28 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$371.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2018 08:35
Date Of Accident	12/04/2018 13:15
Exact Location Of Accident	UBI ROAD 1 / UBI AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP2228S
Insured/Policyholder	
Name Of Registered Owner	PEEL & SEAL TRADING
Co Reg No	NA 53013/06D
Email Address	SAMUELNJG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97263946

Vehicle Particulars

Manufacturer	ISUZU
Model	NHR85AUE4AR1
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28936548 MKC
Cover Note Number	

Driver

Name of Driver	NEO JING GUAN, SAMUEL
NRIC No	S8916065J
Date Of Birth	10/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	12/08/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97263946
Fax Number	
Contact Number	
EMail Address	SAMUELNJG@GMAIL.COM

Address	BLK 332 HOUGANG AVENUE 5 #03-216
Postcode	530332
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT1240D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YONG LING TIAN SAMUEL
NRIC/Passport Number	S7412823H
Contact Number	91703498
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was negotiating a right turn at USI road 1. However, the other driver was bearing the red light & came crashing into my vehicle. The other Driver has given an admission of guilt for bearing the red light.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Vehicle → GT 12407

Owner → S7412 82314

I/C → Yong Ling Tian Samuel

Vehicle → YP 2228 S

Driver → Neo Jeng Guan Samuel

I/C → SS96065J

we writing this letter, due to the driver of YP 2228 S not having an active ~~license~~, we are writing this to certify that the cause of the accident is because Mr Samuel Yong, Driver of vehicle GT 12407 beat the red light. Driver of YP 2228 S, has the right of way. In addition, there is no injury to the accident, & both parties will try to settle ~~Both driver~~ this privately. If the cost exceeds expectation, Mr Samuel Neo, driver of YP 2228 S, will file an insurance coverage within 48 hours. Accident happened on 12 April, 1:15pm. We certify that the above information is true.

S7412 82314

Yong Ling Tian Samuel

SS96065J

Neo Jeng Guan Samuel

Boon Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2
#01-267 Singapore 569536
Tel: 64820801 Email: CS.Boonauto@gmail.com

To: MSIG INSURANCE (SINGAPORE) PTE LTD
Date: 17-04-2018
Our Ref: DC-20181204YP2228S

Vehicle No.: YP2228S
Accident Date: 12-04-2018
Name of Owner: PEEL & SEAL TRADING
Insurance Co.: MSIG
Model: ISUZU NHR85AUE4AR1
Chassis No.: JAANHR85EF7100568

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATED COST FOR REPAIR VEHICLE NO. YP2228S

List Item:	
1 1pc	Front Grille / CR
2 1pc	Headlamp RHS / D's
3 1pc	Headlamp cover protector rubber garnish X
4 1pc	Headlamp lower moulding X
5 1pc	Headlamp lower finisher X
6 6pcs	Headlamp lower finisher clip 6pcs 3.20 X
7 1pc	Front indicator lamp RHS / Cut
8 1pc	Side lamp / D's
9 1pc	Side mirror with arm / Cut
10 1pc	Side mirror with arm cover cap / M's
11 1pc	Front panel / MC
12 1pc	Front Side panel X MC Repair / M's
13 4pc	Side panel clips / MC
14 1pc	NH Logo sticker / MC
15 1pc	Emblem Izusu / MC
16 1pc	Front Bumper / BT
17 1pc	Front Bumper Bracket Left & Right 80each LH - BT, RH X NN
18 4pcs	Front bumper fastener screw 5each / MC
19 1pc	Front Corner Panel X MC Repair
20 1pc	Front Door RHS X MC Repair
21 1pc	Front Door Pillar X
22 1pc	Windscreen Nozzle / M's
23 1pc	Windscreen Nozzle Wiper X NN
24 1set	Windscreen Sealant
25 1pc	Windscreen molding / MC
26 1pc	Inner Seal

List Price	
\$ 290.00	/
\$ 240.00	/
\$ 95.00	X
\$ 53.00	X
\$ 55.00	X
\$ 19.20	X
\$ 57.00	/
\$ 120.00	/
\$ 42.00	/
\$ 38.00	/
\$ 540.00	/
\$ 360.00	/
\$ 20.00	/
\$ 55.00	/
\$ 92.00	/
\$ 498.00	/
\$ 160.00	80
\$ 20.00	/
\$ 138.00	X
\$ 890.00	X
\$ 960.00	X
\$ 28.00	X
\$ 34.00	X
\$ 100.00	/
\$ 88.00	/
\$ 65.00	/
Total	\$ 5,057.20 2733
Less 15%	\$ 758.58
Balance	\$ 4,298.62 2323.05

Labour charges:

1 Towing charges	\$ 150.00 X
2 To check electrical lighting concerned	\$ 80.00 30 X NN
3 To rust-proofing of the affected areas	\$ 200.00 60
4 To remove and refit front windscreen glass	\$ 250.00 120
5 To remove and refit interior fittings, trimmings. Garnish and others to enable repair	\$ 280.00 60
6 To place vehicle on jig bench and correct front chassis frame, door pillar & structure	\$ 2,000.00 800 X NN
7 To check side slip	\$ 60.00 X
8 Labour to dismantle and install above mentioned items, panel beating knocking and straighten necessary portion, replace damaged parts, re-assemble and re-fit with new parts.	\$ 1,800.00 800 1000
9 To dismantle and re-install instrument dashboard, check electrical lightings and re-run, re-route wire harness	\$ 380.00 200
10 To putty, apply primer & spray painting on the affected areas	\$ 2,400.00 800 1000
11 To check and connect wiring functions	\$ 120.00 30
	\$ 7,720.00

Repair Cost Total \$ 12,018.62 2170

4793.05

20%: 3600 3800

7 Days.

30/11/18

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 21 December 2018 10:28 AM
To: 'Boon Auto CS'
Cc: SUR
Subject: RE: YP 2228S-DOA: 12/4/2018

Dear Raphael,

Noted with thanks.

We did not received the after paint photos, please re-forward to us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boon Auto CS <cs.boonauto@gmail.com>
Sent: Friday, 21 December 2018 2:22 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: YP 2228S-DOA: 12/4/2018

Dear Veron,

We accepted your offer Lump Sum \$3800 @ 7 working days. The painted pictures(pdf) were enclosed in earlier emails.

Thanks & Regards,
Raphael Lim

Boon Automobile Service

General servicing & repair, Panel beating, welding, spray painting

Accident Insurance claim , Buy/Sell & Used cars.

Tel: 6482 0801(24hrs) / Whatsapp: 9738 0801

Email us at cs.boonauto@gmail.com

On Fri, Nov 30, 2018 at 3:41 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$3800 @ 7 working days.

Kindly check and confirm.

Please forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 24 October 2018 10:21 AM
To: 'CS.Boonauto@gmail.com' <CS.Boonauto@gmail.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: YP2228S-DOA: 12/4/2018

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$3600 @ 7 working days.

Kindly check and confirm.

Please forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 28 August 2018 10:51 AM
To: 'CS.Boonauto@gmail.com' <CS.Boonauto@gmail.com>
Cc: SUR <sur@lkkauto.com>
Subject: YP 2228S-DOA: 12/4/2018

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$3600 @ 7 working days.

Kindly check and confirm.

Please forward us after paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



































...CLAIM SUBFOLDER...(Pending for Survey Report)

















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Apr 2018		13 Apr 2018 18:34 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CALDRON HARDWARE ENTERPRISE , Co. Reg. No.: 36924700X								
Main Claimant:	PEEL & SEAL TRADING , Co. Reg. No.: 53013106D								
Vehicle Reg. No.:	YP2228S	Date of Loss:	12/04/2018 13:00 - :59 [23 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 555428	Policy/Cover Note No.:	A29007663TMV (Third Party Only) Coverage: 01/10/2017 - 30/09/2018						
Vehicle Reg. No. (Insured):	GT1240D	Policy No. (Claimant):							
		Excess:							
Repairer:	Boon Automobile Service (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-267, 569536 Ang Mo Kio - Tel: 64820801								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 14/04/2018]								
Driver/Custodian (Insured):	YONG LING TIAN SAMUEL (YANG LINTIAN) (), NRIC: S7412823H, Tel: +6591705498								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP2228S (555428)**
[GT1240D]
TP
PEEL & SEAL TRADING
Apr 12 2018 1:00PM
[CALDRON HARDWARE ENTERPRISE]
Boon Automobile Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/04/18 17:27	Accident Statement <small>From: SC - Reg. No: GT1240D, Claimant: CALDRON HARDWARE ENTERPRISE</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/18 12:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/12/18 08:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	24/12/18 08:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	24/12/18 08:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/04/18 17:27	TPD YP2228S GIA REPORT.pdf	 Load PDF	
2	13/04/18 17:27	Email 10 SURYVORS to TPD - YP2228S.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006909/GVBE2

Date: 27/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29007663TMV

Claimant Vehicle
No: YP2228S

Insured Vehicle No: GT1240D

Date of Loss: 12/04/2018

Nature of Claim: TP

Claim No: 555428

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP2228S

Make & Model: ISUZU NHR85EU3ES, 3.0 D (M)

Engine No: 4JJ12J0218

Reg. Date: 03/05/2016 (Man. Year: 2015)

Chassis No: JAANHR85EF7100568

Colour: White

Odometer: 25056 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 165 R14

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,298.62	2,323.05	1,975.57	45.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,720.00	2,470.00	5,250.00	68.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,018.62	4,793.05	7,225.57	60.12
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	12,018.62	3,800.00	8,218.62	68.38

INSPECTION

Date of Assignment: 13/04/2018

Date Inspected: 17/04/2018 Inspected At:

Boon Automobile Service (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-267
Singapore 569536

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Dec 2018)

Parts: N/A ISUZU NHR85EU3ES 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP2228S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	290.00 FL	*290.00 FL
2	1		*HEADLAMP RHS	Distorted	240.00 FL	*240.00 FL
3	1		*HEADLAMP COVER PROTECTOR RUBBER GARNISH	Not Necessary	95.00 FL	*- FL
4	1		*HEADLAMP LOWER MOULDING	Not Necessary	53.00 FL	*- FL
5	1		*HEADLAMP LOWER FINISHER	Not Necessary	55.00 FL	*- FL
6	6		*HEADLAMP LOWER FINISHER CLIP	Not Necessary	19.20 FL	*- FL
7	1		*FRONT INDICATOR LAMP RHS	Cut	57.00 FL	*57.00 FL
8	1		*SIDE LAMP	Distorted	120.00 FL	*120.00 FL
9	1		*SIDE MIRROR WITH ARM	Cut	42.00 FL	*42.00 FL
10	1		*SIDE MIRROR WITH ARM COVER CAP	Missing	38.00 FL	*38.00 FL
11	1		*FRONT PANEL	Buckled	540.00 FL	*540.00 FL
12	1		*FRONT SIDE PANEL	Missing	360.00 FL	*360.00 FL
13	4		*SIDE PANEL CLIPS	Necessary	20.00 FL	*20.00 FL
14	1		*NH LOGO STICKER	Necessary	55.00 FL	*55.00 FL
15	1		*EMBLEM ISUZU	Necessary	92.00 FL	*92.00 FL
16	1		*FRONT BUMPER	Bent	498.00 FL	*498.00 FL
17	1		*FRONT BUMPER BRAKET LEFT & RIGHT	N/S Bent / O/S Not Necessary	160.00 FL	*80.00 FL
18	4		*FRONT BUMPER FASTENER SCREW	Necessary	20.00 FL	*20.00 FL
19	1		*FRONT CORNER PANEL	Repair	138.00 FL	*- FL
20	1		*FRONT DOOR RHS	Repair	890.00 FL	*- FL
21	1		*FRONT DOOR PILLAR	Repair	960.00 FL	*- FL
22	1		*WINDSCREEN NOZZLE	Missing	28.00 FL	*28.00 FL
23	1		*WINDSCREEN NOZZLE WIPER	Not Necessary	34.00 FL	*- FL
24	1		*SET WINDSCREEN SEALANT	Necessary	100.00 FL	*100.00 FL
25	1		*WINDSCREEN MOLDING	Necessary	88.00 FL	*88.00 FL
26	1		*INNER SEAL	Necessary	65.00 FL	*65.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 5,057.20 2,733.00
 - List Item Discount on L Items 15.00/15.00% (S\$) 758.58 409.95

Total Parts (S\$) 4,298.62 2,323.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	150.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	60.00
4	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	250.00	120.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHERS TO ENABLE REPAIR	New	280.00	60.00
6	TO PLACE VEHICLE ON JIG BENCH AND CORRECT FRONT CHASSIS FRAME, DOOR PILLAR & STRUCTURE	New	2,000.00	0.00
7	TO CHECK SIDE SLIP	New	60.00	0.00
8	LABOUR TO DISMANTLE AND INSTALL ABOVE MENTIONED ITEMS, PANEL BEATING KNOCKING AND STRAIGHTEN NECESSARY PORTION, REPLACE DAMAGED PARTS, RE-ASSEMBLE AND RE-FIT WITH NEW PARTS	New	1,800.00	1,000.00
9	TO DISMANTLE AND RE-INSTALL INSTRUMENT DASHBOARD, CHECK ELECTRICAL LIGHTINGS AND RE-RUN, RE-ROUTE WIRE HARNESS	New	380.00	200.00
10	TO PUTTY, APPLY PRIMER & SPRAY PAINTING ON THE AFFECTED AREAS	New	2,400.00	1,000.00
11	TO CHECK AND CONNECT WIRING FUNCTIONS	New	120.00	30.00
Gross Labour Cost (S\$)			7,720.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >