

PREMIER AUTOMOTIVE SERVICES PTE L**23 Changi South Ave 2****#01-02, Singapore 486443****Assessment Number: MSIG0003****Version: PREMIERA/1****Assessor Report****Printed: 14/04/2018****Summary Information****Claim**

Claim Reference:	SHB8543S	Insured:	
Policy Number:		Third Party:	
Date of Decision:	14/04/2018	Able to Authorise Repairs:	TBA
Repairer:		Repairs Authorised?	TBA
Estimated Repair Time (Working Days):	0.0		

Insured's Liability

Excess:	TBA
Customer Contribution:	\$0.00 (excl GST)

Vehicle Details**Vehicle**

Registration:	SHB8543S	VIN/Chassis Number:	
Manufacturer:	KIA	Model:	Optima
Registration Month:	October	Registration Year:	2013
Odometer:	Not Known	Colour:	
Build Date:			
Model Specs	FROM 10/2013 PREPARE OFF VEHICLE BASECOAT CLEAR		

Vehicle Condition**Vehicle Status**

Date of Incident:	12/04/2018	Market Value:	Unknown
Pre-Accident Condition:		Salvage Value:	Unknown
Pre-Accident Damage:		Date of Inspection:	14/04/2018
Steering Rim Ply:		Place of Inspection:	
Brake Pedal Travel:			
Vehicle Status:			
Damage Severity:			

Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Tread Depth RHF:

Tread Depth RHR:

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR****Price/Dent = \$50.00/HR****Repair /****Guide Number Repair Details**

86520R00	RENEW REAR BUMPER (REMOVED)
86621R00)	R + R BUMPER ABSORBER

WU	Cost Price (\$)
11.0	55.00
4.0	20.00

LABOUR COST**Total Work Units**

15.0

Corrosion Protection External Labour

0.0HRS 0.00

Corrosion Protection Internal Labour

0.0HRS 0.00

Sub Total

1.5HRS \$75.00

Paint Labour

2.9HRS \$145.00

Total Labour

4.4HRS \$220.00

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0003

Version: PREMIERA/1

Assessor Report

Printed: 14/04/2018

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	14.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	14.0	
	Preparation Main Work Plastic	15.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	29.0	
	Total Paintwork Labour	2.9HRS	\$145.00
	MATERIAL COST - PAINT		Cost Price
	New Part Painting - Plastic K1R		\$70.36
	Material-Const Main Work Plastic		\$28.60
	Total Excluding Pearlescent Uplift		\$98.96
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$98.96

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
2618	1	R/R BUMPER BRACKET	866142T501	X <i>see</i>	0% 29.00*
3414	1	R/R REFLECTOR	924062T500	X <i>see</i>	0% 46.00*
2583	1	REAR BUMPER	866112T500	<i>external</i>	0% 696.00*
2644	1	REAR BUMPER DAMPER	866202T500	X <i>see</i>	0% 114.00*
2770	1	REAR BUMPER SPOILER	866122T500	<i>id</i>	0% 206.00*
f: OEM Parts		(under cover)		Sub Total	\$1,091.00
g: Original				Deduction from RRP (35 %)	-\$381.85
h: Secondhand				Total Parts	\$709.15
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$280.00 <i>200</i>
REAR BUMPER CLIPS SPECIALIST		\$48.00
Total Extras		\$328.00

Final Calculation

Total Parts	\$709.15
Labour	
Total Panel/Mechanical	\$75.00
Total Paintwork	\$145.00
Total Labour	\$220.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$328.00
Total of Additional Costs	\$328.00