



**SINGAPORE
POLICE FORCE**



T/20180408/2079

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 3

Report No. T/20180408/2079

CONTINUATION OF REPORT

Driver			
Name	SEKAR CHINNADURAI	ID No.	G2731595Q
Related Vehicle	YP485D (Lorry)	Contact No.	96103972
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

VIDE:J/20180408/0171

On 08/04/2018 at about 1455hrs, I was driving my company vehicle bearing the plate: YP485D along Tuas Crescent towards Tuas Ave 2. The weather was clear and the road is dry. As I was approaching the junction of the said road and Pioneer Rd, I continue on straight as the light was in my favor. However, suddenly I was hit from the left rear. The incident happened so quickly I could not react. I then brake abruptly and put my vehicle to a stop.

I alighted and went to the vehicle (bearing the plate number: SHA2552K) to aid the driver. The driver seem injured thus I called for the ambulance. There was a male Chinese passenger seated at the rear passenger seat. The passenger do not seem injured.

Shortly after the ambulance and Traffic police were at scene.

I could not furnish the full particulars of the driver as he was injured and was conveyed by ambulance. I was not injured nor is my passenger. My vehicle was damaged. The left bumper was damaged and the left passenger door was dented, the left headlight was also damaged. The I was instructed by IO Jeya, HP:6547 6232, to lodge a Traffic Police report.



**SINGAPORE
POLICE FORCE**



T/20180408/2079

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 3

Report No. T/20180408/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

HAYRUL HAZIQ BIN OSMAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/04/2018 16:57

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN MOHAMED
JUNID

Contact No.: 65476247

Classification Of Case:

Authentication Stamp

NP108



Signature :

SN 127

Singapore Police Force

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8137A
Vehicle Details	
Vehicle No.:	YP485D
Vehicle to be Exported:	No
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4HK1417108
Chassis No.:	JAANPR75HF7105940
Maximum Power Output:	-
Open Market Value:	\$33,154.00
Original Registration Date:	11 Dec 2015
First Registration Date:	11 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,658.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,947.00
COE Rebate Amount:	\$17,546.00
Total Rebate Amount:	\$17,546.00

The information contained herein is correct as at 17 Apr 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Isuzu NPR75U

Price Range

Depreciation

2015

Vehicle Type

Search

Advanced Search

Home » Used Cars » Direct Owners » Isuzu NPR75U

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Leasing



Isuzu NPR75U

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$69,900	
Depreciation	\$9,340 /yr View models with similar depreciation	
Reg Date	09-Oct-2015 (7yrs 5mths 21days COE left)	
Manufactured	2015	
Mileage	52,368 km (20.8k /yr)	
Transmission	Auto	
Engine Cap	5,193 cc	
Curb Weight	2,480 kg	
Fuel type	Diesel	
Features	Camera, GPS, Wooden Body, Tool Box, Fire Extinguisher.	

Accessories

Description Oct 2015 Isuzu NPR14 Feet Wooden Body (Opened) Lorry, Euro 4 Engine, Mint Condition With Daily In House Maintenance, 10 x Free Servicing, Low Mileage. Parked Under Shelter, Accident Free! Like New! COE: \$44890.

COE \$44,890

OMV \$31,886

ARF \$1,595

Dereg Value \$33,588 as of today (change)

No. of Owners 1

Type of Veh Truck

Category Direct Owner Sale

Availability Available

DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 04-Apr-2018 | Last Updated on: 11-Apr-2018

Tags: Isuzu NPR75U, 2015 Isuzu NPR75U, Isuzu, NPR75U, Used Isuzu

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$6,990 (change)	Maximum 90% Loan
1st Instalment	\$927	



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Seller Information

Contact Person(s) Julie Tan

Contact No. 81129485

Enquiry Contact Seller

USEFUL FORMS

- » Indemnity form
- » Receipt
- » M01
- » Sales agreement
- » Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

[Compare](#)



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VCA/P2039292 Account No. : 04437
Coverage : Comprehensive
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : JIAWEN TRADELINK
Vehicle Registration No. : YP485D
Period of Insurance : From 11/12/2017 To 10/12/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

- (a) Use in connection with the Policyholder's business
 - (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
 - (c) Use for social, domestic and pleasure purposes
- This Policy does not cover
- (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
 - (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

EXCESS :

Sect I - Any Authorised Driver : SGD 800.00

Windscreen Excess : SGD 160.00

(Please refer to your policy for Additional Excess)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGIJPZB2 on 14/12/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number **G2731595Q**


Name

SEKAR CHINNADURAI

Birth Date **28 Jul 1992**

Issue Date **15 Aug 2016**

Valid Till **14/08/2021**



S PASS

Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
PROTEK CHEMICAL & ENGINEERING PTE LTD

Sector: **MANUFACTURING**

Name

SEKAR CHINNADURAI

Occupation

DRIVER



S Pass No.
0 36582251



Date of Application

16-01-2018

Date of Issue

01-03-2018

Date of Expiry

01-03-2020



L8629321

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles $\leq$ 200 CC
Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors/vehicles $\leq$ 2500 kg

15 Aug 2016
07 Jun 2017

5
5

G2731595Q

S / No. 9000300552

NP 428A



Licence No: G2731595Q

VISIT PASS
Immigration Regulations

Name

SEKAR CHINNADURAI



Date of Birth	Sex	Nationality
28-07-1992	M	INDIAN
FIN	Date of Issue	Date of Expiry
G2731595Q	01-03-2018	01-03-2020

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 12/04/2018

TO : AXA INSURANCE PTE LTD

ATTN : MOTOR CLAIMS DEPARTMENTS

OFFICE / MOBILE : -

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 8116-6611

EMAIL ADDRESS : williamgosc@goldbell.com.sg

VEHICLE NO. : YP485D

MODEL NO. : ISUZU NPR75UH5A

CHASSIS NO. : JAANPR75HF7105940

ENGINE NO. : 4HK1417108

REG. DATE : 11/12/2015

REF. NO. :

D.O.A. : 08/04/2018

POLICY NO. : VCA/P2039292

CLAIM TYPE : OD CLAIM - AXA

WORKSHOP : 53 UBI AVE 1 #01-23

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		FRONT DOOR LHS	1	\$ bt 950.00
2		FRONT DOOR WEATHERSTRIP LHS	1	\$ ne 290.00
3		FRONT DOOR HINGE LHS - <i>photo</i>	1 2	\$ bt 300.00
4		FRONT DOOR ARC GARNISH LHS	1	\$ cut 85.00
5		FRONT DOOR LOWER SEAL LHS	1	\$ ne 45.00
6		FRONT DOOR SIDE LAMP LHS	1	\$ cut 85.00
7		FRONT CORNER PANEL LHS	1	\$ de 225.00
8		FRONT BUMPER	1	\$ ole 500.00
9		FRONT STEP GARNISH LHS	1	\$ cut 420.00
10		HEADLAMP LHS	1	\$ cut 450.00
11		FRONT TURN SIGNAL LAMP LHS	1	\$ se 250.00
12		REAR VIEW MIRROR LHS	1	\$ cut 100.00
13		REAR RIM LHS	1	\$ bt 450.00
14		REAR WHEEL BEARING AND OIL SEAL LHS	1	\$? 275.00

SUB-TOTAL :	\$ 4,425.00
LESS 15% :	\$ 663.75
BALANCE :	\$ 3,761.25

SPECIAL-NETT ITEMS

1	REAR TYRE LHS	1	\$ 70% 450.00
2	SIDE GUARD LHS	1	\$ bt 700.00
3	SIDE GUARD BRACKET LHS/RHS	4	\$ bt 600.00
4	REAR MUDGUARD LHS/RHS	2	\$ de 500.00
5	REAR MUDGUARD BRACKET LHS/RHS	4	\$ bt 400.00
6	U-BOLT	6	\$ bt 1,080.00
7	REAR DECK LOWER VERTICAL WOOD LHS/RHS	2	\$ de 2,800.00
8	REAR DECK LOWER HORIZONTAL WOOD	7	\$? 3,850.00
9	BOLT & NUT SET	14	\$ ne 490.00
10	REAR DECK FLOOR PANEL	7	\$? 4,900.00
11	REAR DECK FLOOR PANEL FRAME	1	\$? 1,800.00

PARTS TOTAL :	\$ 21,331.25
---------------	--------------

bizSAFE
S T R



Certificate No.: AIA/SJ121243

Certificate No.: AIA/SJ121243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	400. \$ 1,200.00
2 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC.	\$ 150 250.00
3 TO REMOVE & REFIX FRONT DOOR COMPARTMENTS.	\$ 150 200.00
4 TO REMOVE & REFIX FUEL TANK ASSY.	\$ 250 400.00
5 TO REMOVE, REFIX AND REALIGN REAR CANOPY ASSY. TO REMOVE, REFIX & REALIGN REAR WOODEN DECK ASSY. TO REPLACE ALL DAMAGED PARTS. *photo.	3600. \$ 4,000.00
6 TO PANEL BEAT AND REALIGN BOTH MAIN CHASSIS FRAMES AND ALL CHASSIS CROSSMEMBERS. *photo.	5800 \$ 7,000.00
7 TO APPLY TUFF COAT ON REPAIR AREA.	200. \$ 250.00
8 TO REPLACE REAR RIM AND TYRE LHS. TO CARRY OUT WHEEL BALANCING.	100. \$ 200.00
9 TO CARRY OUT WHEEL ALIGNMENT CHECK.	\$ ✓ 280.00
10 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	2100. \$ 2,400.00
11 SUNDRIES	rec \$ 80 100.00

LABOUR TOTAL : \$ 16,680.00

GRAND TOTAL : \$ 38,011.25

PREPARED BY : WILLIAM GO

DATE / TIME : 17/4/18 @ 1130

SURVEYOR : Tanjoh

MOBILE NO. : 97495749

OFFICE FAX NO. :

EMAIL ADDRESS : sur@lkhauto.com

EXCESS AMOUNT : \$2800

REPAIR TYPE : PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 18 days

REMARKS :

bizSAFE
S T R



Certificate No: AIA/S/19101243 / Certificate No: AIA/1004

Veron Chen (LKKAuto)

From: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Sent: Thursday, 26 April 2018 10:10 AM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: RE: YP 485D-DOA:8/4/2018 (AXA OD)
Attachments: Jia Wen.pdf

Dear Veron,

Please see the attached Authorization letter which I have just received from my client. Kindly assist for approval.



We will prefer to repair the vehicle under part by part basis.

Thanks & Best Regards,



William Go Shaw Chan | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tanjong Penjuru)
29 Tanjong Penjuru Singapore 609026



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, April 25, 2018 8:54 AM
To: William Go Shaw Chan <WilliamGoSC@goldbell.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: YP 485D-DOA:8/4/2018 (AXA OD)

Dear William,

Please forward us authorise letter and relationship between driver and owner.

Please advised vehicle able to repair at Lump Sum basis.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

JIAWEN TRADELINK

138D Yuan Ching Road #13-151 Singapore (614138)
CO Registration No.:53198137A
Tel no.: 81553322

Date: 11/04/2018

Dear Sir/Mdm,

This is to confirm that the vehicle with registration plate YP485D was loaned to Protek Chemicals and Engineering Pte. Ltd on 8 April 2018 as their delivery vehicle had broken down, therefore their employee Sekar Chinnadurai FIN no. G2731595Q was driving the vehicle at the time of the accident.
Thank you.

Best Regards,



JIAWEN TRADELINK

Clement Tham Jiawen
Sole-proprietor
Jiawen Tradelink

Re:RE: Re:RE: Re:RE: Re:AUTHORIZE LETTER UPLOADED.

Type

🔔 Question

Message

Hi Veron, Please refer to Special-Nett items no 4 and 7, is it 1 piece or 2 pieces? Please clarify. The damages is on left side, why approve right hand side?

Reply *

Dear Sir/Madam,

According to surveyor, The damage on the right side is induced damage. The impact on the left side of the lorry had caused the chassis to bent towards the right. Both the items are attached to the chassis and was hence damaged when the chassis shifted towards the right. Thanks Veron Chen

Cancel Reply

Reply Now

Re:RE: Re:RE: Re:RE: Re: AUTHORIZE LETTER UPLOADED.

Type

Question

Message

Hi Veron, Please refer to Special-Nett items no 4 and 7, is it 1 piece or 2 pieces? Please clarify. The damages is on left side, why approve right hand side?

Reply *

Dear Sir/Madam,

According to surveyor, due to the huge impact to the left side of the lorry causes the both chassis of the lorry to bent which causes the (item 7) rear deck lower vertical wood LH/RH vehicle is attached to the chassis to give way and crack. As for item 4 rear mudguard, due to the damage to the chassis, causes the rear deck (attached to chassis) to be shifted and causes damage to the RHS mudguard attached to it. Thanks Veron Chen

Cancel Reply

Reply Now

The damage on the right side is ~~due~~
induced damage. The impact on the left side of the lorry
had caused the chassis to bent towards the right.
Both the items are attached to the chassis and was
hence damaged when the chassis shifted ~~and~~ towards
the right.

**Re:RE: Re:RE: Re:RE: Re:AUTHORIZE LETTER - VP 4851
UPLOADED.**

Type

🔗 Question

Message

Hi Veron, Please refer to Special-Nett items no 4 and 7, is it 1 piece or 2 pieces? Please clarify. The damages is on left side, why approve right hand side?

Reply

Due to the huge impact to the left side of the lorry
causes ~~the~~ ^{both} chassis of the lorry to bent which causes the
near deck lower vertical wood LH/RH ^{which is attached to the chassis} to give way and crack.
(item 7) near deck lower vertical wood LH/RH ^{which is attached to the chassis}
As for item 4 near undeground, ~~the floor is attached to~~
due to the damage to the chassis, causes the near deck (attached
to be shifted and causes damage to the RHS undeground chassis)
attached to it.

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M00DGC
Reference	CS/ASM18006964/vbLoss Date
Request Date	April 8, 2018
Due Date	April 13, 2018
Vendor Name	April 16, 2019
Type of Loss	LKK AUTO CONSULTANTS PTE Loss LTD (OD)
Own Damage	Services

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information	
Incident Vehicle Registration #	YP485D
Service Address	ISUZU 29
Model	NPR75UH5A
Tanjong Penjur, . . .	
609026	
Primary Contact/Insured	
JIAWEN TRADELINK BLK 621 CHOA CHU KANG ST 62, #12-08, 680621, Singapore 65674755 wennn86@gmail.com	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
MARK ESTIMATE.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2018
EMAIL FOR OD CLAIM WITH GIA & ESTIMATE.msg	Forms / Claim Documents	Estimate / Quotation	KUMAR Shailendra	April 13, 2018
SHA252K TP GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	April 13, 2018
CI.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	NG Stacey	April 11, 2018
SCHEDULE.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	NG Stacey	April 11, 2018
YP485D INS GIA.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	April 11, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M00DGC	Vehicle Information	
Reference		Incident Vehicle	YP485D
CS/ASM18006964/vb Loss Date		Registration #	Make
April 8, 2018	Request Date	ISUZU	Service Address
April 13, 2018	Due Date	Model	29
April 16, 2019	Vendor Name	NPR75UH5A	
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss	Tanjong Penjuru, ,	
Own Damage	Services	609026	
Primary Contact/Insured			
JIAWEN TRADELINK BLK 621 CHOA CHU KANG ST 62, #12-08, 680621, Singapore 65674755 wennn86@gmail.com			

Actions

Next Step

Finish the work

Complete Work

More



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

General Details

Involving
1 2015 ISUZU NPR75UH5A (YP485D)

Date of Loss
April 8, 2018

Time of Loss
14.55

Loss Description
YP485D (INSD) C/W SHA2552K (TP) - BOTH ALLEGED GREEN LIGHT
IN THEIR FAVOUR

Comment

Workshop Details

Total Rebate Amount

17546

Nett Loss Amount
\$52,454.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

04/20/2018 

Days of work completion *

7

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

YP485D

Registration State

SINGAPORE

Mileage

111565

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO... 2015

Purchase Date

mm/dd/yyyy

Registration Date *

12/11/2015

Age of Vehicle

2

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

SEKAR CHINNADURAI

POST SURVEY INF...

ASSESSMENT INFO... JAANPR75HF7105940

FNOL INFORMATI... 0

CATEGORY	Engine No
POLICY INFORMAT...	4HK1417108
ASSESSMENT INFO...	4HK1417108

POST SURVEY INF ...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF ...	

CATEGORY	Engine Capacity
POLICY INFORMAT...	
ASSESSMENT INFO...	5193 cc

CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Sum Insured
POLICY INFORMAT...	0
ASSESSMENT INFO...	0

CATEGORY	License Issue Date
FNOL INFORMATI...	January 1, 2018
POST SURVEY INF...	mm/dd/yyyy

CATEGORY	Market Value
POLICY INFORMAT...	0
ASSESSMENT INFO...	70000

CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF ...	mm/dd/yyyy

CATEGORY	Address
----------	---------

POST SURVEY INF...

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

WESTLAKE 6mm

Rear left side

WESTLAKE 66mm

Front right side

WESTLAKE 6mm

Rear right side

WESTLAKE 66mm

SERVICE REQUESTSMESSAGESCLAIMS

<< Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts					
Add Approve Deny			SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
		1	1			FRONT DOOR LHS				Bent	950		15		807.5
		2	1			FRONT DOOR WEATHERSTRIP LHS				Necessary	290		15		246.5
		3	1			FRONT DOOR HINGES LHS				Bent	300		15		255
		4	1			FRONT DOOR ARC GARNISH LHS				Cut	85		15		72.25
		5	1			FRONT DOOR LOWER SEAL LHS				Necessary	45		15		38.25
		6	1			FRONT DOOR SIDE LAMP LHS				Cut	85		15		72.25
		7	1			FRONT CORNER PANEL LHS				Deformed	225		15		191.25
		8	1			FRONT BUMPER				Deformed	500		15		425
		9	1			FRONT STEP GARNISH LHS				Cut	420		15		357

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
☐ 	7		TO APPLY TUFF COAT ON REPAIR AREA.	200	0	0	Reviewing	
☐ 	8		TO REPLACE REAR RIM AND TYRE LHS. TO CARRY OUT WHEEL BALANCING.	100	0	0	Reviewing	
☐ 	9		TO CARRY OUT WHEEL ALIGNMENT CHECK.	280	0	0	Reviewing	
☐ 	10		TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	2100	0	0	Reviewing	

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	DAYS OF REPAIR	Reviewing	18		
--	---	----------------	-----------	----	--	--

	2	REAR TYRE LHS (@ \$450.00 DISC 70%)	Reviewing	0	*Check	
--	---	-------------------------------------	-----------	---	--------	--

	3	SIDE GUARD LHS	Reviewing	700	BENT	
--	---	----------------	-----------	-----	------	--

	4	SIDE GUARD BRACKET LHS/RHS	Reviewing	600	BENT	
--	---	----------------------------	-----------	-----	------	--

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	12	REAR DECK FLOOR PANEL FRAME	Reviewing	0	*Check	
	13	SUNDRIES	Reviewing	80	NECESSARY	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$21,207.50 Claim Amount \$21,207.50

CATEGORY

ESTIMATE

REVISED AMOUNT

Labour

\$13,830.00

\$13,830.00

Miscellaneous

\$6,650.00

\$6,650.00

Excess

-\$2,800.00

-\$2,800.00

Submit for Review