



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 12/04/2018

TO : AXA INSURANCE PTE LTD

ATTN : MOTOR CLAIMS DEPARTMENTS

OFFICE / MOBILE : -

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 8116-6611

EMAIL ADDRESS : williamgosc@goldbell.com.sg

VEHICLE NO. : YP485D

MODEL NO. : ISUZU NPR75UH5A

CHASSIS NO. : JAANPR75HF7105940

ENGINE NO. : 4HK1417108

REG. DATE : 11/12/2015

REF. NO. :

D.O.A. : 08/04/2018

POLICY NO. : VCA/P2039292

CLAIM TYPE : OD CLAIM - AXA.

WORKSHOP : 53 UBI AVE 1 #01-23

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		FRONT DOOR LHS	1	\$ bt 950.00
2		FRONT DOOR WEATHERSTRIP LHS	1	\$ ne 290.00
3		FRONT DOOR HINGE LHS - <i>ph to.</i>	1 2	\$ bt 300.00
4		FRONT DOOR ARC GARNISH LHS	1	\$ cut 85.00
5		FRONT DOOR LOWER SEAL LHS	1	\$ ne 45.00
6		FRONT DOOR SIDE LAMP LHS	1	\$ cut 85.00
7		FRONT CORNER PANEL LHS	1	\$ de 225.00
8		FRONT BUMPER	1	\$ de 500.00
9		FRONT STEP GARNISH LHS	1	\$ cut 420.00
10		HEADLAMP LHS	1	\$ cut 450.00
11		FRONT TURN SIGNAL LAMP LHS	1	\$ ne 250.00
12		REAR VIEW MIRROR LHS	1	\$ cut 100.00
13		REAR RIM LHS	1	\$ bt 450.00
14		REAR WHEEL BEARING AND OIL SEAL LHS	1	\$? 275.00
SUB-TOTAL :				\$ 4,425.00
LESS 15% :				\$ 663.75
BALANCE :				\$ 3,761.25

SPECIAL-NETT ITEMS

1	REAR TYRE LHS	1	\$? <i>70%</i> 450.00
2	SIDE GUARD LHS	1	\$ bt 700.00
3	SIDE GUARD BRACKET LHS/RHS	4	\$ bt 600.00
4	REAR MUDGUARD LHS/RHS	2	\$ de 500.00
5	REAR MUDGUARD BRACKET LHS/RHS	4	\$ bt 400.00
6	U-BOLT	6	\$ bt 1,080.00
7	REAR DECK LOWER VERTICAL WOOD LHS/RHS	2	\$ de 2,800.00
8	REAR DECK LOWER HORIZONTAL WOOD	7	\$? 3,850.00
9	BOLT & NUT SET	14	\$ ne 490.00
10	REAR DECK FLOOR PANEL	7	\$? 4,900.00
11	REAR DECK FLOOR PANEL FRAME	1	\$? 1,800.00

PARTS TOTAL : \$ 21,331.25

bizSAFE
S T R



Certificate No: AJA(S)01/Q1243

Certificate No: AJA(S)01/Q1254



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Industrial Vehicles.

20,000 Served. And Counting.

LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	400. 1200. \$ 1,600.00
2 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC.	\$ 150 250.00
3 TO REMOVE & REFIX FRONT DOOR COMPARTMENTS.	\$ 150 200.00
4 TO REMOVE & REFIX FUEL TANK ASSY.	\$ 250 400.00
5 TO REMOVE, REFIX AND REALIGN REAR CANOPY ASSY. TO REMOVE, REFIX & REALIGN REAR WOODEN DECK ASSY. TO REPLACE ALL DAMAGED PARTS. *photo.	3600. \$ 4,000.00
6 TO PANEL BEAT AND REALIGN BOTH MAIN CHASSIS FRAMES AND ALL CHASSIS CROSSMEMBERS. *photo.	5800 \$ 7,000.00
7 TO APPLY TUFF COAT ON REPAIR AREA.	200. \$ 250.00
8 TO REPLACE REAR RIM AND TYRE LHS. TO CARRY OUT WHEEL BALANCING.	100. \$ 200.00
9 TO CARRY OUT WHEEL ALIGNMENT CHECK.	\$ ✓ 280.00
10 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	2100. \$ 2,400.00
11 SUNDRIES	80. \$ 100.00

LABOUR TOTAL : \$ 16,680.00

GRAND TOTAL : \$ 38,011.25

PREPARED BY : WILLIAM GO

DATE / TIME : 17/4/18 @ 1130

SURVEYOR : Tanfer

MOBILE NO. : 97495749

OFFICE FAX NO. :

EMAIL ADDRESS : sur@hkauto.com

EXCESS AMOUNT : \$2800

REPAIR TYPE : PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 18 days

REMARKS :

bizSAFE
S T R



Certificate No: AJA(SJ)1/Q1243 / Certificate No: AJA91335