

REPAIR ESTIMATE*

DATE 13/4/2018 14:59

MAKE :

MODEL : HYUNDAI SONATA

Page 1 of 2

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Rear No. Plate ✓			\$ 25.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Rear Fender Comfort Sticker (RH) ✓			\$ 30.00	Nett
	Rear Windscreen Sealant ✓			\$ 46.00	Nett
				\$ 516.70	
	Labour Charge				
	Panel Beating			\$ 1,600.00 ¹²⁰⁰	
	Spray Painting Charge			\$ 1,750.00 ¹⁰⁰⁰	
	Wiring Charge			\$ 50.00 ²⁰	
	Tuff Kote			\$ 100.00 ⁵⁰	
	Towing Charge-King Dolly			\$ 150.00 ¹⁰⁰	
	Rear Chassis Alignment Charge			\$ 400.00 ¹⁰⁰	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ⁵⁰	
	Remove/Refix Rear Windscreen Glass			\$ 120.00 ¹⁰⁰	
	Remove/Refix Reverse Sensor			\$ 120.00 ²⁰	
	Remove/Refix Exhaust Pipe			\$ 150.00 ⁵⁰	
	TOTAL LABOUR			\$ 4,590.00	
	ESTIMATE TOTAL			\$ 14,964.94	
16000 16000 13/4/8 16000 TBA Repair By: Check Book value to check again on Main chassis.					
LKN Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modifications are allowed • Supplementary item(s) must be resurveyed and is subject to final approval of LKN Auto Consultants Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					