

**WTS Engineering Pte Ltd**

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 09/04/18
VEHICLE NO: XD4136K
DRIVER: RAMARASU VILLAVAN GOTHAI
ATTENTION TO:
PREPARED BY: Winson

LOCATION: Gul Workshop
Q REF No: Q18/04/868
DEPARTMENT: WTS Prime Mover Department
ACCIDENT DATE: 04/04/18
REF No: JW/0418/313

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	STEP PLATE (LH)	1	150	bt ✓ 150.00
2	STEP PLATE, LOWER (LH)	1	60	de ✓ 60.00
3	STEP STRUCTURE (LH)	1	320	de ✓ 320.00
4	MUDGUARD, FRONT (LH)	1	168	cu ✓ 168.00
5	MUDGUARD, REAR (LH)	1	168	dis ✓ 168.00
6	WASHER CONTAINER ASSY	1	230	? 230.00
7	SIGNAL LAMP (LH)	1	45	cu ✓ 45.00
8	HEAD LAMP (LH)	1	140	an ✓ 140.00
Labour Costs				
1	TO REPAIR AND REPLACE LHS STEPBOARD (UPPER & LOWER), MUDGUARD (FRONT & REAR), WASHER CONTAINER, HEAD LAMP & SIGNAL LAMP.	1	350	300 350.00
2	TO REPAIR AND PUTTY FIBER LHS CORNER BUMPER.	1	150	100 150.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING FOR ACCIDENT AREA AND LHS CORNER BUMPER.	1	200	150 200.00
TOTAL:				1,981.00
Total Amount				SGD 1,981.00

Remarks:

09.04.18

Signature of Workshop Dpt

Nedra 9.4.18

Signature of Department Head

9/4/18

Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
- wp -

16/4/18 @ 1610.

3 days

before / after repair

1 / 1 Sur @ lkkauto.com.

Surveyor Sign:

Surveyor Name: Taufik

Date: 16/4/18