

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

Not Authorised
Resurvey B4 paint
1.B.1
6 days

CHUNG FOOK TET

c/o 46 Lentor Plain
Singapore 786548

Date : 16/04/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : HONDA JAZZ / SLP 466 M		
1 pc	rear bumper	R 646.00 ✓
2 pcs	rear bumper side retainer @ 76.30	D 152.60 ✓
2 pcs	rear bumper side cover @ 117.40	SL 234.80 X
1 pc	rear end outer panel	R 546.20 ✓
1 pc	rear end inner panel	461.70 ?
1 pc	rear end panel garnish	mg D 316.20 ✓
1 pc	rear spare tyre panel	R 865.70 X
1 pc	rear spare tyre panel top board	SL 342.10 X
2 pcs	rear fender inner trim @ 314.70	629.40 ?
1 pc	rear boot lid	R 974.20 ✓
1 pc	rear boot lock	R 123.50 X
1 pc	rear boot lock catch	R 67.00 X
1 pc	rear boot inner trim	365.00 ?
1 pc	rear boot emblem 'JAZZ'	R 74.20 ✓
2 pcs	rear tail lamp @ 577.40	CR 1,154.80 ✓
1 pc	rear windscreen glass moulding	R 117.00 ✓
1 pc	exhaust silencer	R 876.40 X
1 pc	tool kit foam box	CR 378.60 ✓
sub-total		8,325.40
less 20%		1,665.08
sub-total		6,660.32
1 pc	reverse sensor (4 sensor type) s.nett	short 320w 450.00
1 pc	windscreen glass sealant s.nett	403w 60.00
sub-total		7,170.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	balance bought forward.	7,170.32
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	600/- 1,100.00
	To check wiring system.	50.00 20/-
	To apply rust proofing on affected areas.	60/- 180.00
	To water waterproof sealant on affected areas.	30/- 180.00
	To apply putty and spray painting on affected areas.	600/- 650.00
	To install reverse sensors.	60/- 100.00
	To remove rear windscreen glass to enable repair.	120/- 140.00
	To remove carpet, trimming and seats to enable repair.	60/- 120.00
	To transfer tail doors accessories.	40.00 ✓
	Total	9,730.32